

C2240, C2325, C2425, C2535, CS421, CS521, and CS622 Printers

5029-038, 23x, 43x, 6x6

Service Manual

- Start diagnostics
- Maintenance
- Safety and notices
- Trademarks
- Index

September 14, 2020

www.lexmark.com

Product information

Product name:

Lexmark C2240, Lexmark C2325dw, Lexmark C2425dw, Lexmark C2535dw, Lexmark CS421dn, Lexmark CS521dn, Lexmark CS622de printers

Machine type:

5029

Model(s):

038, 230, 238, 430, 438, 636, 696

Edition notice

September 14, 2020

The following paragraph does not apply to any country where such provisions are inconsistent with local law: LEXMARK INTERNATIONAL, INC., PROVIDES THIS PUBLICATION "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions; therefore, this statement may not apply to you.

This publication could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in later editions. Improvements or changes in the products or the programs described may be made at any time.

References in this publication to products, programs, or services do not imply that the manufacturer intends to make these available in all countries in which it operates. Any reference to a product, program, or service is not intended to state or imply that only that product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any existing intellectual property right may be used instead. Evaluation and verification of operation in conjunction with other products, programs, or services, except those expressly designated by the manufacturer, are the user's responsibility.

Trademarks

Lexmark and the Lexmark logo are trademarks of Lexmark International, Inc., registered in the United States and/or other countries. PCL® is a registered trademark of the Hewlett-Packard Company. PCL is Hewlett-Packard Company's designation of a set of printer commands (language) and functions included in its printer products. This printer is intended to be compatible with the PCL language. This means the printer recognizes PCL commands used in various application programs, and that the printer emulates the functions corresponding to the commands.

PostScript is a registered trademark of Adobe Systems Incorporated in the United States and/or other countries. All other trademarks are the property of their respective owners.

© 2018 Lexmark International, Inc.

All rights reserved.

P/N

Table of contents

| Product information | 2 |
|---|----|
| Edition notice | 2 |
| Notices, conventions, and safety information | 11 |
| Laser notice | 11 |
| Conventions | |
| Safety information | |
| Change history | 17 |
| Change history | 17 |
| General information | 21 |
| Printer model configurations | 21 |
| Finding the serial number | 22 |
| Paper support | 22 |
| Supported paper sizes | |
| Supported paper types | |
| Supported paper weights | 26 |
| Tools required for service | 27 |
| Diagnostics and troubleshooting | 29 |
| Troubleshooting precautions | 29 |
| Troubleshooting overview | 31 |
| Performing the initial troubleshooting check | 31 |
| Fixing print quality issues | 31 |
| Initial print quality check | 31 |
| Supplies used to resolve print quality issues | 32 |
| Blurred print check | 34 |
| Misaligned color check | |
| Toner easily rubs off check | |
| Gray or solid background check | |
| Solid color or black image check | |
| Blank or white pages check | |
| Horizontal colored lines or handing check | |
| Horizontal colored lines or banding check Text or images cut off check | |
| Mottled print and dots check | 48 |

| Vertical white lines check | 50 |
|-----------------------------------|-----|
| Ghost images check | 51 |
| Dark print check | 53 |
| Missing color check | 55 |
| Uneven print density check | 59 |
| Repeating defects check | 60 |
| Light print check | 63 |
| Skewed print check | 65 |
| Toner patch sensing service check | 67 |
| Auto alignment service check | 71 |
| Paper jams | 74 |
| Avoiding jams | 74 |
| Identifying jam locations | 75 |
| 200 paper jams | 76 |
| 202 paper jams | 79 |
| 231 paper jams | 86 |
| 232 paper jams | 91 |
| 24y paper jams | 92 |
| User attendance messages | 97 |
| Non-Lexmark supply | |
| 24 user attendance errors | |
| 31 user attendance errors | |
| 32 user attendance errors | 99 |
| 33 user attendance errors | |
| 34 user attendance errors | 102 |
| 42 user attendance errors | 102 |
| 43 user attendance errors | 103 |
| 80 user attendance errors | 104 |
| 82 user attendance errors | 104 |
| 84 user attendance errors | 106 |
| 88 user attendance errors | 106 |
| Non-supply user attendance errors | 107 |
| Printer hardware errors | 115 |
| 100 errors | |
| 110 errors | |
| 120 errors | 117 |
| 121 errors | 119 |
| 126 errors | 124 |
| 142 errors | 125 |
| 151 errors | 127 |
| 160 errors | 128 |
| 161 errors | 129 |
| 162 errors | 131 |
| 163 errors | 131 |

| 166 errors | 132 |
|--|-----|
| 167 errors | 132 |
| 171 errors | 132 |
| 600 errors | 133 |
| 602 errors | 134 |
| 620 errors | 135 |
| 642 errors | 135 |
| 651 errors | 136 |
| 661 errors | 136 |
| 662 errors | 137 |
| 663 errors | 137 |
| 666 errors | 138 |
| 667 errors | 138 |
| Procedure before starting the 9yy service checks | 138 |
| 900 errors | 140 |
| 91y errors | 145 |
| 938 errors | 147 |
| 95y errors | 147 |
| 96y errors | 151 |
| 97y errors | 151 |
| 980-984 errors | 153 |
| 99y errors | 153 |
| Other symptoms | 154 |
| Base printer symptoms | 154 |
| Input option symptoms | 171 |
| Service menus | 197 |
| Using the control panel | 197 |
| Lexmark C2325 | |
| Lexmark CS421, Lexmark CS521, Lexmark C2425, and Lexmark C2535 | |
| Lexmark CS622 and Lexmark C2240 | |
| Understanding the status of the power button and indicator light | |
| Using the home screen | |
| Configuring the door interlock bypass jumpers | |
| Diagnostics menu | 202 |
| Entering the Diagnostics menu | |
| Reports | |
| Advanced Print Quality Samples | |
| Event Log | |
| Input tray quick print | |
| Printer Setup | |
| Printer diagnostics and adjustments | |
| Additional input tray diagnostics | |

| Configuration Menu | 210 |
|--|-----|
| Service Engineer menu | 213 |
| Entering the Service Engineer (SE) menu | 213 |
| General SE | 213 |
| Network SE | 213 |
| Entering Invalid engine mode | 214 |
| Entering Recovery mode | 214 |
| Parts removal | 217 |
| Data security notice | 217 |
| Removal precautions | 218 |
| Handling ESD-sensitive parts | |
| Critical information for controller board or control panel replacement | |
| Restoring the printer configuration after replacing the controller board | 221 |
| Restoring solutions, licenses, and configuration settings | 224 |
| Updating the printer firmware | 225 |
| Backing up eSF solutions and settings | 226 |
| Disconnecting ribbon cables | 226 |
| Ribbon cable connectors | 227 |
| Zero Insertion Force (ZIF) connectors | |
| Horizontal top contact connector | |
| Horizontal bottom contact connector | |
| Vertical mount contact connector | |
| Horizontal sliding contact connector | |
| Low Insertion Force (LIF) connector | |
| Adjustments | 240 |
| Registration adjustment | 240 |
| Entering the TPS characterization data | 242 |
| Removal procedures | 244 |
| Left side removals | 244 |
| Left cover removal | 244 |
| Motor (drive unit) removal | 247 |
| EP drive assembly removal | 247 |
| LVPS removal | 250 |
| Sensor (fuser exit) removal | 252 |
| Speaker (CS622) removal | 257 |
| Right side removals | 257 |
| Right cover removal | 257 |
| Toner supply door removal | 259 |
| Motor (fuser drive) removal | 260 |
| TMC card removal | 261 |
| Sensors (toner patch) removal | 264 |

| | Developer unit removal | 266 |
|----|--|-----|
| | HVPS removal | 267 |
| | Transfer module removal | 272 |
| | Imaging kit removal | 276 |
| | Toner cartridge contacts removal | 278 |
| | Waste toner bottle removal | 280 |
| | Waste toner bottle contact block removal | 281 |
| =r | ont removals | 282 |
| | Front door removal | 282 |
| | Front door inner deflector removal | 287 |
| | Interlock switch cover assembly removal | 288 |
| | Control panel base removal | 289 |
| | 2-line control panel badge cover removal | 290 |
| | 2.4-inch control panel badge cover removal | 291 |
| | 4.3-inch control panel badge cover removal | 291 |
| | 2-line control panel bezel removal | 292 |
| | 2.4-inch control panel bezel removal | 292 |
| | 4.3-inch control panel bezel removal | 293 |
| | 2-line control panel assembly removal | 295 |
| | 2-line control panel top cover removal | 296 |
| | 2.4-inch control panel top cover removal | 297 |
| | 4.3-inch control panel top cover removal | 299 |
| | 2.4-inch control panel keypad removal | |
| | Weather station removal | 303 |
| | Wireless card removal | 306 |
| | Front USB cable removal | 307 |
| | Fuser removal | 311 |
| | Exit deflector removal | 314 |
| 30 | ottom removals | 316 |
| | Pick tires removal | 316 |
| | Lower left frame removal | 318 |
| | Lower right frame removal | 328 |
| | Sensor (duplex) removal | 334 |
| | Transfer module guide removal | 335 |
| | Sensor (tray present) removal | 338 |
| | Tray 1 media feeder removal | 339 |
| R∈ | ear side removals | 342 |
| - | System fan removal | |
| | Rear cover removal | |
| | Controller board removal | |
| Γ∽ | p side removals | |
| ı٥ | Top cover removal | |
| | Sensor (narrow media/output bin full) removal | |
| | Narrow media/bin full sensor flag removal | |
| | - 14011044 1110010/DITTUIL JOHJOH HUU TOHIO401 | |

| Printhead removal | 352 |
|---|-----|
| Right output bin deflector removal | 354 |
| Options removals | 354 |
| 650-sheet duo tray insert removal | 355 |
| 650-sheet duo tray removal | |
| Dust cover removal | |
| Pick tire removal | 358 |
| Component locations | 361 |
| Printer configurations | 361 |
| Controller board connectors | 362 |
| Motor locations | 373 |
| Sensor locations | 374 |
| Maintenance | 375 |
| Inspection guide | |
| Scheduled maintenance | |
| Maintenance kits | |
| Resetting the maintenance counter | 377 |
| Cleaning the printer parts | 377 |
| Cleaning the printer | |
| Cleaning the printhead lenses | 378 |
| Parts catalog | 380 |
| Legend | 380 |
| Assembly 1: 2-line control panel | 381 |
| Assembly 2: 2.4-inch and 4.3-inch control panel | |
| Assembly 3: Covers | 387 |
| Assembly 4: Paper path and frame | 389 |
| Assembly 5: Electronics | |
| Assembly 6: Cables and sensors | 393 |
| Assembly 7: Option trays | 395 |
| Assembly 8: Miscellaneous | |
| Assembly 9: Maintenance kits | |
| Printer specifications | 401 |
| Power consumption | |
| Product power consumption | |
| Sleep Mode | |
| Hibernate Mode | 402 |

| Off mode | 402 |
|--|-----|
| Total energy usage | 402 |
| Selecting a location for the printer | 402 |
| Noise emission levels | 403 |
| Temperature information | 403 |
| Enabling the security reset jumper | 404 |
| Options and features | 405 |
| Available internal options | 405 |
| Adding available options in the print driver | 405 |
| Input/output configurations and capacities | 406 |
| Theory of operation | 407 |
| Paper path and transport components | 407 |
| Paper path information | 407 |
| Transport components | |
| Duplexing | |
| Print engine theory | |
| Electrophotographic process (EP process) Electrophotographic process basics | |
| Color theory | |
| Color theory | |
| Acronyms | 417 |
| Acronyms | 417 |
| Index | 419 |
| Part number index | 423 |
| Part name index | 427 |

Notices, conventions, and safety information

Laser notice

The printer is certified in the U.S. to conform to the requirements of DHHS 21 CFR, Chapter I, Subchapter J for Class I (1) laser products, and elsewhere is certified as a Class I laser product conforming to the requirements of IEC 60825-1: 2014.

Class I laser products are not considered to be hazardous. The laser system and printer are designed so there is never any human access to laser radiation above a Class I level during normal operation, user maintenance, or prescribed service conditions. The printer has a non-serviceable printhead assembly that contains a laser with the following specifications:

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 15 Wavelength (nanometers): 650–670

Avis relatif à l'utilisation du laser

Cette imprimante est certifiée conforme aux exigences de la réglementation des Etats-Unis relative aux produits laser de classe I (1) (DHHS 21 CFR, Chapitre I, Sous-chapitre J). Pour les autres pays, elle est certifiée conforme aux exigences des normes CEI 60825-1:2014 relatives aux produits laser de classe I.

Les produits laser de classe I ne sont pas considérés comme dangereux. Le système laser ainsi que l'imprimante ont été conçus de manière à ce que personne ne soit jamais exposé à des radiations laser dépassant le niveau de classe I dans le cadre d'un fonctionnement normal, de l'entretien par l'utilisateur ou de la maintenance. L'imprimante dispose d'un ensemble de têtes d'impression non réparable contenant un laser doté des caractéristiques suivantes :

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 15 Wavelength (nanometers): 650–670

Aviso de láser

Esta impresora se ha certificado en EE.UU. cumpliendo con los requisitos de DHHS 21 CFR, capítulo I, subcapítulo J para los productos láser de Clase I (1) y en otros países está certificada como un producto láser de Clase I de acuerdo con los requisitos de IEC 60825-1: 2014.

Los productos láser de Clase I no se consideran peligrosos. El sistema láser y la impresora se han diseñado para que el ser humano no acceda nunca a las radiaciones láser por encima del nivel de Clase I durante su uso normal, ni en tareas de mantenimiento o intervenciones de servicio técnico prescritas. El conjunto de cabezal de impresión de la impresora no se puede reparar y contiene un láser con las siguientes especificaciones:

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 15 Wavelength (nanometers): 650–670

Laser-Hinweis

Der Drucker wurde in den USA zertifiziert und entspricht den Anforderungen der Vorschriften DHHS 21 CFR Kapitel I für Laserprodukte der Klasse I (1), andernorts ist er als Laserprodukt der Klasse I zertifiziert, das den Anforderungen von IEC 60825-1 entspricht: 2014.

Laserprodukte der Klasse I werden nicht als gefährlich betrachtet. Das Lasersystem und der Drucker sind so konstruiert, dass unter normalen Betriebsbedingungen, bei der Wartung durch den Benutzer oder bei den vorgeschriebenen Wartungsbedingungen Menschen keiner Laserstrahlung ausgesetzt sind, die die Werte für Klasse I überschreitet. Der Drucker verfügt über eine Druckkopfeinheit, die nicht gewartet werden kann und mit einem Laser mit den folgenden Spezifikationen ausgestattet ist.

Class: IIIb (3b) AlGaInP

Nominal output power (milliwatts): 15 Wavelength (nanometers): 650-670

Conventions

Note: A note identifies information that could help you.

Warning: A warning identifies something that could damage the product hardware or software.

CAUTION: A caution indicates a potentially hazardous situation that could injure you.

Different types of caution statements include:



CAUTION—POTENTIAL INJURY: Indicates a risk of injury.



CAUTION—SHOCK HAZARD: Indicates a risk of electrical shock.



CAUTION—HOT SURFACE: Indicates a risk of burn if touched.



CAUTION—TIPPING HAZARD: Indicates a crush hazard.



CAUTION—PINCH HAZARD: Indicates a risk of being caught between moving parts.

Conventions

Remarque: Une Remarque fournit des informations pouvant vous être utiles.

Avertissement : Un Avertissement signale un danger susceptible d'endommager le logiciel ou le matériel.

ATTENTION: La mention *Attention* vous signale un risque de blessure corporelle.

Il existe différentes mises en garde :



ATTENTION—RISQUE DE BLESSURE : Signale un risque de blessure.



ATTENTION—RISQUE D'ELECTROCUTION : Signale un risque d'électrocution.



ATTENTION—SURFACE CHAUDE : Signale un risque de brûlure de contact.



ATTENTION—RISQUE DE BASCULEMENT : Signale un risque d'écrasement.



ATTENTION : RISQUE DE PINCEMENT : Signale un risque de pincement entre des pièces mobiles.

Convenciones

Nota: Las notas señalan información que puede serle útil.

Aviso: Las advertencias indican algo que podría dañar el software o el hardware del producto.

PRECAUCIÓN: Las *precauciones* indican una situación de posible peligro que puede implicar lesiones para el usuario.

Estos son los tipos de avisos de precaución que existen:



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: Indica que existe riesgo de lesiones.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Indica que existe riesgo de descarga eléctrica.



PRECAUCIÓN: SUPERFICIE CALIENTE: Indica que existe riesgo de sufrir quemaduras por contacto.



PRECAUCIÓN: RIESGO DE CAÍDA: Indica que existe peligro de aplastamiento.



PRECAUCIÓN: PELIGRO DE ATRAPAMIENTO: Existe riesgo de atrapamiento entre las piezas en movimiento.

Konventionen

Hinweis: Ein Hinweis enthält nützliche Informationen.

Warnung: Durch eine *Warnung* werden Sie auf einen Umstand hingewiesen, durch den die Produkthardware oder -software beschädigt werden könnte.

VORSICHT: Vorsicht weist auf eine mögliche gefährliche Situation hin, die ein Verletzungsrisiko birgt.

Verschiedene Vorsichtshinweise:



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Weist auf ein Verletzungsrisiko hin.



VORSICHT – STROMSCHLAGGEFAHR: Weist auf das Risiko eines elektrischen Schlags hin.



VORSICHT – HEISSE OBERFLÄCHE: Weist auf das Risiko von Verbrennungen bei Berührung hin.



VORSICHT – KIPPGEFAHR: Weist auf Quetschgefahr hin.



VORSICHT – QUETSCHGEFAHR: Weist auf das Risiko hin, zwischen beweglichen Komponenten eingequetscht zu werden.

Safety information

- The safety of this product is based on testing and approvals of the original design and specific components. The manufacturer is not responsible for safety in the event of use of unauthorized replacement parts.
- The maintenance information for this product has been prepared for use by a professional service person and is not intended to be used by others.

• There may be an increased risk of electrical shock and personal injury during disassembly and servicing of this product. Professional service personnel should understand this risk and take necessary precautions.



CAUTION—SHOCK HAZARD: When you see this symbol on the product, there is a danger from hazardous voltage in the area of the product where you are working. Unplug the product before you begin, or use caution if the product must receive power in order to perform the task.



CAUTION—POTENTIAL INJURY: The lithium battery in this product is not intended to be replaced. There is a danger of explosion if a lithium battery is incorrectly replaced. Do not recharge, disassemble, or incinerate a lithium battery. Discard used lithium batteries according to the manufacturer's instructions and local regulations.



CAUTION—POTENTIAL INJURY: To avoid the risk of fire or electrical shock, connect the power cord to an appropriately rated and properly grounded electrical outlet that is near the product and easily accessible.



CAUTION—POTENTIAL INJURY: To avoid the risk of fire or electrical shock, use only the power cord provided with this product or the manufacturer's authorized replacement.



CAUTION—POTENTIAL INJURY: Do not use this product with extension cords, multioutlet power strips, multioutlet extenders, or UPS devices. The power capacity of these types of accessories can be easily overloaded by a laser printer and may result in a risk of fire, property damage, or poor printer performance.



CAUTION—POTENTIAL INJURY: Only a Lexmark Inline Surge Protector that is properly connected between the printer and the power cord provided with the printer may be used with this product. The use of non-Lexmark surge protection devices may result in a risk of fire, property damage, or poor printer performance.



CAUTION—POTENTIAL INJURY: If the printer weight is greater than 20 kg (44 lb), then it may require two or more people to lift it safely.

Consignes de sécurité

- La sécurité de ce produit est basée sur des tests et certifications de sa conception d'origine et de ses composants spécifiques. Le fabricant décline toute responsabilité en cas d'utilisation de pièces de rechange non autorisées.
- Les informations de maintenance de ce produit sont destinées à des professionnels qualifiés et ne sont pas conçues pour être utilisées par d'autres personnes.
- Il existe un risque potentiel de choc électrique et de blessures lors du démontage et de la maintenance de ce produit. Le personnel professionnel de maintenance doit comprendre les risques et prendre les précautions nécessaires.



ATTENTION—RISQUE D'ELECTROCUTION : Ce symbole indique un danger lié à des niveaux de tension dangereux dans la zone du produit à manipuler. Débranchez le produit avant de commencer, ou agissez avec prudence si le produit doit être alimenté pour effectuer l'opération.



ATTENTION—RISQUE DE BLESSURE : La batterie lithium de ce produit n'est pas destinée à être remplacée. Si vous ne respectez pas les instructions de remplacement de la batterie, vous risquez de provoquer une explosion. Ne rechargez pas, ne désassemblez pas et ne brûlez pas la batterie au lithium. Mettez les batteries lithium usagées au rebut selon les instructions du fabricant et les réglementations locales.



ATTENTION—RISQUE DE BLESSURE : Pour éviter tout risque d'électrocution ou d'incendie, l'branchez le câble d'alimentation directement à une prise électrique répondant aux exigences requises et correctement mise à la terre, proche du produit et facile d'accès.



ATTENTION—RISQUE DE BLESSURE : Pour éviter tout risque d'incendie ou d'électrocution, utilisez uniquement le câble d'alimentation fourni avec ce produit ou un câble de remplacement autorisé par le fabricant.



ATTENTION—RISQUE DE BLESSURE : Ce produit ne doit pas être utilisé avec des rallonges, des barres multiprises, des rallonges multiprises ou des périphériques UPS. La capacité de ces types d'accessoires peut être facilement dépassée par une imprimante laser, d'où un risque de dégâts matériels, d'incendie ou de performances d'impression amoindries.



ATTENTION—RISQUE DE BLESSURE: Utilisez uniquement un parasurtenseur correctement raccordé à l'imprimante et au câble d'alimentation fourni avec la machine. L'utilisation de parasurtenseurs non fabriqués par Lexmark comporte un risque d'incendie et de dégâts matériels, et peut amoindrir les performances de l'imprimante.



ATTENTION—RISQUE DE BLESSURE : Si votre imprimante pèse plus de 20 kg (44 lb), l'intervention d'au moins deux personnes est nécessaire pour la soulever sans risque.

Información de seguridad

- La seguridad de este producto se basa en las pruebas y comprobaciones del diseño original y los componentes específicos. El fabricante no se hace responsable de la seguridad en caso de uso de piezas de repuesto no autorizadas.
- La información de mantenimiento de este producto se ha preparado para su uso por parte de un profesional de asistencia técnica y no está diseñada para su uso por parte de otros usuarios.
- Es posible que haya un mayor riesgo de descarga eléctrica y daños personales durante el desmontaje y el mantenimiento de este producto. El personal de asistencia profesional debe conocer este riesgo y tomar las precauciones necesarias.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Cuando vea este símbolo en el producto, existe peligro de tensiones peligrosas en el área del producto en la que está trabajando. Desconecte el producto antes de empezar o tenga cuidado si el producto debe recibir alimentación a fin de realizar la tarea.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: La batería de litio de este producto no debe reemplazarse. Existe riesgo de explosión si se sustituye incorrectamente una batería de litio. No recargue, desmonte ni incinere una batería de litio. Deseche las baterías de litio usadas según las instrucciones del fabricante y las normativas locales.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: Para evitar el riesgo de incendio o descarga eléctrica, conecte el cable de alimentación a una toma de corriente debidamente conectada a tierra con la potencia adecuada que se encuentre cerca del dispositivo y resulte fácilmente accesible.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: Para evitar el riesgo de incendio o descarga eléctrica, utilice exclusivamente el cable de alimentación que se suministra junto con este producto o el repuesto autorizado por el fabricante.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: No utilice este producto con cables alargadores, regletas de varias tomas, cables alargadores de varias tomas o sistemas de alimentación ininterrumpida. La potencia de este tipo de accesorios puede sobrecargarse fácilmente si se utiliza una impresora láser, lo que puede dar lugar a que el rendimiento de la impresora sea bajo, a daños materiales o a posibles incendios.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: Solo debe usarse con este producto un protector de sobretensión insertable Lexmark debidamente conectado entre la impresora y el cable de alimentación que con ella se suministra. El uso de protectores de sobretensión de marcas distintas a Lexmark puede dar lugar a que el rendimiento de la impresora sea bajo, a daños materiales o a posibles incendios.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: si el peso de la impresora es superior a 20 kg (44 lb), pueden ser necesarias dos o más personas para levantarla de forma segura.

Sicherheitshinweise

- Die Sicherheit dieses Produkts basiert auf Tests und Zulassungen des Originaldesigns und der spezifischen Komponenten. Sofern nicht autorisierte Ersatzteile eingesetzt werden, übernimmt der Hersteller keinerlei Verantwortung in Bezug auf die Sicherheit dieses Produkts.
- Die Wartungsinformationen für dieses Produkt wurden für ausgebildete Servicemitarbeiter zusammengestellt und dürfen nicht von anderen verwendet werden.
- Möglicherweise besteht bei der Demontage und Wartung dieses Produkts eine erhöhte Stromschlag- und Verletzungsgefahr. Ausgebildete Servicemitarbeiter sollten sich dieser Gefahr bewusst sein und die notwendigen Vorsichtsmaßnahmen ergreifen.



VORSICHT – STROMSCHLAGGEFAHR: Wenn Sie dieses Symbol sehen, besteht eine Gefahr durch gefährliche Spannungen in dem Produktbereich, in dem Sie arbeiten. Trennen Sie das Produkt von seiner Stromverbindung, bevor Sie beginnen, oder gehen Sie vorsichtig vor, wenn das Produkt für die Durchführung der Aufgabe mit Strom versorgt werden muss.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Die Lithiumbatterie in diesem Produkt darf nicht ausgetauscht werden. Wird eine Lithiumbatterie nicht ordnungsgemäß ausgetauscht, besteht Explosionsgefahr. Lithiumbatterien dürfen auf keinen Fall wieder aufgeladen, auseinander genommen oder verbrannt werden. Befolgen Sie zum Entsorgen verbrauchter Lithiumbatterien die Anweisungen des Herstellers und die örtlichen Bestimmungen.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Um Feuer- und Stromschlaggefahr zu vermeiden, schließen Sie das Netzkabel direkt an eine ordnungsgemäß geerdete Steckdose an, die sich in der Nähe des Geräts befindet und leicht zugänglich ist.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Um das Risiko eines Feuers oder elektrischen Schlags zu vermeiden, verwenden Sie ausschließlich das diesem Produkt beiliegende Netzkabel bzw. ein durch den Hersteller zugelassenes Ersatzkabel.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Verwenden Sie das Produkt nicht mit Verlängerungskabeln, Mehrfachsteckdosen, Mehrfachverlängerungen oder Geräten für unterbrechungsfreie Stromversorgung. Die Belastbarkeit solcher Zubehörteile kann durch Laserdrucker schnell überschritten werden, was zu Brandgefahr, Beschädigung von Eigentum oder einer eingeschränkten Druckerleistung führen kann.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Mit diesem Produkt darf nur ein Lexmark Inline Surge Protector verwendet werden, der vorschriftsgemäß zwischen dem Drucker und dem mitgelieferten Netzkabel angeschlossen ist. Die Verwendung von nicht von Lexmark stammenden Überspannungsschutzgeräten kann zu Brandgefahr, Beschädigung von Eigentum oder einer eingeschränkten Druckerleistung führen.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Wenn der Drucker mehr als 20 kg wiegt, sind zum sicheren Anheben mindestens zwei Personen notwendig.

Change history

Change history

September 15, 2020

- Updated the Critical information for controller board or control panel replacement topic in the Parts removal chapter.
- Added video demonstration links in the following topics:
 - Transfer module removal
 - Fuser removal
- Added PN 41X1872 in the Parts catalog chapter.

August 5, 2020

- Updated the Restoring the printer configuration after replacing the controller board topic in the Parts removal chapter.
- Updated the Controller board removal topic in the Parts removal chapter.

July 30, 2020

- Obsoleted PN 41X1014 in the Parts catalog chapter.
- Removed PN 41X2615 in the Parts catalog chapter.

March 13, 2020

- Added the Entering Recovery Mode topic in the Service menus chapter.
- Updated the Text or images cut off check topic in the Diagnostics and troubleshooting chapter.
- Updated the supported printer models of the following PNs in the Parts catalog chapter:
 - 41X2100
 - 41X1790
 - 41X1043
 - 41X1788
 - 41X2127
 - 41X2132
 - 41X2133
 - 41X1304
 - 41X1627
 - 41X1309
 - 41X2021
 - 41X1306
 - 41X2113
 - 41X1302
 - 41X2115
 - 41X1310

- 41X2140
- 41X2019
- 41X1311

February 5, 2020

• Added the PN 41X2615 in the Parts catalog chapter.

November 18, 2019

• Updated the Sensor (redrive/duplex path 1) service check topic in the Diagnostics and troubleshooting chapter.

October 23, 2019

- Updated the Notices, conventions, and safety information section.
- Updated the Troubleshooting precautions section in the Diagnostics and troubleshooting chapter.
- Updated the Removal precautions section in the Parts removal chapter.
- Updated the LVPS removal and HVPS removal topics in the Parts removal chapter.
- Updated the Cleaning the printer topic in the Maintenance chapter.
- Updated the Paper jams section of the Diagnostics and troubleshooting chapter.
- Removed the Installing optional trays topic from the Options and features chapter.

July 9, 2019

- Removed PN 40X9934 (320 GB SATA hard disk drive) in Assembly 8 of the Parts catalog chapter.
- Added PN 41X1026 (500 GB USB hard disk drive) in Assembly 8 of the Parts catalog chapter.
- Removed the Controller board/control panel replacement topic in the Parts removal chapter.
- Added the Critical information for controller board or control panel replacement topic in the Parts removal chapter.
- Updated the EP setup topic in the Service menus chapter.

May 15, 2019

- Added the PN 41X2663 in the Parts catalog chapter.
- Added the Front door inner deflector removal topic in the Parts removal chapter.
- Updated the System software error service check topic in the Diagnostics and troubleshooting chapter.

April 26, 2019

Added PN 41X1303 in the Parts catalog chapter.

January 14, 2019

• Updated the description for PN 41X2021 in the Parts catalog chapter.

December 12, 2018

• Added the Maintenance kits assembly in the Parts catalog chapter.

September 17, 2018

- Added the 2.4-inch control panel keypad removal topic in the Parts removal chapter.
- Added the 2.4-inch control panel keypad false navigation key press service check topic in the Diagnostics and troubleshooting chapter.

August 16, 2018

• Updated the 220 V fuser maintenance kit content PN in the Maintenance chapter.

August 13, 2018

- Removed PN 40X7641 and PN 41X1724 from the Parts catalog chapter.
- Removed PN 41X0027 and replaced it with PN 41X2055 in the Miscellaneous section of the Parts catalog chapter.
- Updated the description of the following PNs in the Miscellaneous section of the Parts catalog chapter.
 - 41X2095
 - 41X2096
 - 41X2097
- Updated the description for PN 41X1039 to transfer module in Assembly 4 of the Parts catalog chapter.
- Changed all instances of the term image transfer unit to transfer module.
- Updated the following topics in the Removals chapter:
 - Data security notice
 - Imaging kit removal
 - Transfer module removal

June 19, 2018

• Product announce

General information

Printer model configurations


The LexmarkTM C2240, C2325, C2425, C2535, CS421, CS521, CS622 printers are network-capable, multifunction laser printers. The printers support color and monochrome printing and are embedded with home screen solutions and applications. All information in this service manual pertains to all models unless explicitly noted.

The printers are available in the following models:

| Model | Configurations | Machine type/model |
|---------|---|--------------------|
| C2240 | Network-ready color laser printer with 4.3" color touchscreen and internal duplex printing for small workgroups | 5029-696 |
| C2325dw | Network-ready color laser printer with 2-line display and internal duplex printing for small workgroups | 5029-038 |
| C2425dw | Network-ready color laser printer with 2.4" color display and internal duplex printing for small workgroups | 5029-238 |
| C2535dw | Network-ready color laser printer with 2.4" color display and internal duplex printing for small workgroups | 5029-438 |
| CS421dn | Network-ready color laser printer with 2.4" color display and internal duplex printing for small workgroups | 5029-230 |
| CS521dn | Network-ready color laser printer with 2.4" color display and internal duplex printing for small workgroups | 5029-430 |
| CS622de | Network-ready color laser printer with 4.3" color touchscreen and internal duplex printing for small workgroups | 5029-636 |

Finding the serial number

Open door A, and then find the serial number at the left side of the printer.



Paper support

Supported paper sizes

Note: Your printer model may have a 650-sheet duo tray, which consists of a 550-sheet tray and an integrated 100-sheet multipurpose feeder. The 550-sheet tray of the 650-sheet duo tray supports the same paper sizes as the optional 550-sheet tray. The integrated multipurpose feeder supports different paper sizes, types, and weights.

| Paper size and | Standard | Manual | Optional 65 | 0-sheet duo tray | Optional | Two-sided |
|---|----------------|----------|-------------------|------------------------|-------------------|-----------|
| dimension | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| A4 210 x 297 mm (8.27 x 11.7 in.) | ✓ | ✓ | ✓ | √ | ✓ | ✓ |
| A5 ^{1,2} 148 x 210 mm (5.83 x 8.27 in.) | ✓ | ✓ | / | √ | ✓ | х |

¹ Load this paper size into tray 1 and the manual feeder with the long edge entering the printer first.

² Load this paper size into tray 2, tray 3, and the multipurpose feeder with the short edge entering the printer first.

 $^{^3}$ When Universal is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

⁴ Load narrow paper with the short edge entering the printer first.

 $^{^5}$ When Other Envelope is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

| Paper size and | | Manual | Optional 65 | 0-sheet duo tray | Optional | Two-sided |
|--|----------------|----------|-------------------|------------------------|-------------------|-----------|
| dimension | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| A6 105 x 148 mm (4.13 x 5.83 in.) | \ | ✓ | х | √ | x | х |
| JIS B5 182 x 257 mm (7.17 x 10.1 in.) | ✓ | ✓ | ✓ | √ | ✓ | х |
| Letter 215.9 x 279.4 mm (8.5 x 11 in.) | ✓ | ✓ | ✓ | √ | / | √ |
| Legal 215.9 x 355.6 mm (8.5 x 14 in.) | ✓ | ✓ | ✓ | √ | / | √ |
| Executive 184.2 x 266.7 mm (7.25 x 10.5 in.) | ✓ | ✓ | ✓ | √ | ✓ | х |
| Oficio (Mexico) 215.9 x 340.4 mm (8.5 x 13.4 in.) | ✓ | ✓ | ✓ | √ | ✓ | ✓ |
| Folio 215.9 x 330.2 mm (8.5 x 13 in.) | ✓ | √ | ✓ | √ | ✓ | ✓ |
| Statement 139.7 x 215.9 mm (5.5 x 8.5 in.) | ✓ | ✓ | х | √ | х | х |
| Hagaki 100 x 148 mm (3.94 x 5.83 in.) | ✓ | √ | х | √ | x | х |
| Universal ^{3,4} 98.4 x 148 mm to 215.9 x 355.6 mm (3.87 x 5.83 in. to 8.5 x 14 in.) | ✓ | √ | х | √ | х | х |

¹ Load this paper size into tray 1 and the manual feeder with the long edge entering the printer first.

² Load this paper size into tray 2, tray 3, and the multipurpose feeder with the short edge entering the printer first.

 $^{^3}$ When Universal is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

⁴ Load narrow paper with the short edge entering the printer first.

 $^{^{5}}$ When Other Envelope is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

| Paper size and | Standard | Manual | Optional 650-sheet duo tray | | Optional | Two-sided |
|---|----------------|----------|-----------------------------|------------------------|-------------------|-----------|
| dimension | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| Universal ^{3,4} 76.2 x 127 mm to 215.9 x 355.6 mm (3 x 5 in. to 8.5 x 14 in.) | X | √ | X | √ | х | х |
| Universal ^{3,4} 148 x 210 mm to 215.9 x 355.6 mm (5.83 x 8.27 in. to 8.5 x 14 in.) | ✓ | √ | ✓ | ✓ | ✓ | х |
| Universal ^{3,4} 210 x 250 mm to 215.9 x 355.6 mm (8.27 x 11.0 in. to 8.5 x 14 in.) | ✓ | √ | ✓ | ✓ | ✓ | ✓ |
| 7 3/4 Envelope 98.4 x 190.5 mm (3.875 x 7.5 in.) | ✓ | ✓ | x | ✓ | X | Х |
| 9 Envelope 98.4 x 225.4 mm (3.875 x 8.9 in.) | √ | √ | х | √ | х | х |
| 10 Envelope 104.8 x 241.3 mm (4.12 x 9.5 in.) | √ | √ | х | √ | х | х |
| DL Envelope 110 x 220 mm (4.33 x 8.66 in.) | √ | √ | х | √ | х | х |
| C5 Envelope 162 x 229 mm (6.38 x 9.01 in.) | √ | √ | х | √ | х | х |
| B5 Envelope 176 x 250 mm (6.93 x 9.84 in.) | √ | √ | х | √ | х | х |

¹ Load this paper size into tray 1 and the manual feeder with the long edge entering the printer first.

² Load this paper size into tray 2, tray 3, and the multipurpose feeder with the short edge entering the printer first.

 $^{^3}$ When Universal is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

⁴ Load narrow paper with the short edge entering the printer first.

 $^{^{5}}$ When Other Envelope is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

| Paper size and | Standard | Manual | Optional 65 | 0-sheet duo tray | Optional | Two-sided |
|---|----------------|----------|-------------------|------------------------|-------------------|-----------|
| dimension | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| Monarch | \ | / | Х | | X | X |
| 98.425 x 190.5 mm (3.875 x 7.5 in.) | · | , | | , | | |
| Other Envelope ⁵ | ✓ | / | Х | ✓ | х | х |
| 98.4 x 162 mm to 176 x 250 mm (3.87 x 6.38 in. to 6.93 x 9.84 in.) | · | · | | · | | |

¹ Load this paper size into tray 1 and the manual feeder with the long edge entering the printer first.

Supported paper types

Notes:

- Your printer model may have a 650-sheet duo tray, which consists of a 550-sheet tray and an integrated 100-sheet multipurpose feeder. The 550-sheet tray of the 650-sheet duo tray supports the same paper types as the 550-sheet tray. The integrated multipurpose feeder supports different paper sizes, types, and weights.
- Labels, envelopes, and card stock always print at 25 pages per minute.

| Paper type | Standard Manual | | Optional 6 | 50-sheet duo tray | Optional | Two-sided |
|--------------|-------------------|----------|-------------------|------------------------|-------------------|-----------|
| | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| Plain paper | \ | √ | ✓ | ✓ | ✓ | ✓ |
| Card stock | < | √ | ✓ | ✓ | ✓ | х |
| Envelopes | < | √ | x | ✓ | x | х |
| Paper labels | \ | √ | / | ✓ | √ | √ |
| Vinyl labels | ✓ | √ | / | √ | ✓ | X |

² Load this paper size into tray 2, tray 3, and the multipurpose feeder with the short edge entering the printer first.

 $^{^3}$ When Universal is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

⁴ Load narrow paper with the short edge entering the printer first.

 $^{^{5}}$ When Other Envelope is selected, the page is formatted for 215.9 x 355.6 mm (8.5 x 14 in.) unless the size is specified by the software application.

Supported paper weights

Notes:

- Your printer model may have a 650-sheet duo tray, which consists of a 550-sheet tray and an integrated 100-sheet multipurpose feeder. The 550-sheet tray of the 650-sheet duo tray supports the same paper types as the 550-sheet tray. The integrated multipurpose feeder supports different paper sizes, types, and weights.
- Labels, envelopes, and card stock always print at 25 pages per minute.

| Paper type and | Standard Manual | | Optional 6 | 50-sheet duo tray | Optional | Two-sided |
|---|-------------------|----------|-------------------|------------------------|-------------------|------------|
| weight | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | printing |
| Light paper ¹ 60–74.9 g/m ² grain long (16– 19.9-Ib bond) | \ | √ | √ | ✓ | ✓ | ~ |
| Plain paper 75–90.3 g/m² grain long (20– 24-lb bond) | ✓ | √ | ✓ | ✓ | ✓ | ✓ |
| Heavy paper 90.3–105 g/m² grain long (24.1– 28-lb bond) | ✓ | √ | ✓ | ✓ | √ | ✓ |
| Card stock 105.1–162 g/m ² grain long (28.1– 43-lb bond) | ✓ | √ | ✓ | ✓ | ✓ | х |
| Card stock 105.1–200 g/m ² grain long (28.1– 53-lb bond) | ✓ | √ | х | х | х | х |
| Paper Labels ² 131 g/m ² (35-lb bond) | ✓ | ✓ | ✓ | √ | ✓ | √ 3 |
| Vinyl Labels ² 131 g/m ² (35-lb bond) | ✓ | ✓ | / | √ | ✓ | х |

¹ Paper less than 75 g/m² (20 lb) must be printed with Paper Type set to Light Paper. Failure to do so may cause excessive curl which can lead to feeding errors, especially in more humid environments.

² Labels and other specialty media are supported for occasional use and must be tested for acceptability.

 $^{^{3}}$ Paper labels up to 105 g/m 2 (28-lb bond) are supported.

⁴ 100% cotton content maximum weight is 24-lb bond.

⁵ 28-lb bond envelopes are limited to 25% cotton content.

| Paper type and | Standard | Manual | Optional 6 | 50-sheet duo tray | Optional | Two-sided printing | |
|---|-------------------|----------|-------------------|------------------------|-------------------|--------------------|--|
| weight | 250-sheet tray | feeder | 550-sheet tray | Multipurpose feeder | 550-sheet tray | | |
| Envelopes ^{4,5} | \ | / | х | ✓ | Х | Х | |
| 60–105 g/m ² (16– 28-lb bond) | · | • | | · | | | |

¹ Paper less than 75 g/m² (20 lb) must be printed with Paper Type set to Light Paper. Failure to do so may cause excessive curl which can lead to feeding errors, especially in more humid environments.

Tools required for service

- Flat-blade screwdrivers, various sizes
- #1 Phillips screwdriver, magnetic
- #2 Phillips screwdriver, magnetic
- #2 Phillips screwdriver, magnetic short-blade
- Torx screwdriver (T20 head)
- Needle-nose pliers
- · Diagonal side cutters
- · Spring hook
- · Feeler gauges
- · Analog or digital multimeter
- 3-mm ball hex wrench
- Toner vacuum
- Flashlight

² Labels and other specialty media are supported for occasional use and must be tested for acceptability.

 $^{^{3}}$ Paper labels up to 105 g/m 2 (28-lb bond) are supported.

⁴ 100% cotton content maximum weight is 24-lb bond.

⁵ 28-lb bond envelopes are limited to 25% cotton content.

Diagnostics and troubleshooting

Troubleshooting precautions



CAUTION—SHOCK HAZARD: When you see this symbol on the product, there is a danger from hazardous voltage in the area of the product where you are working. Unplug the product before you begin, or use caution if the product must receive power in order to perform the task.



CAUTION—SHOCK HAZARD: This product uses an electronic power switch. It does not physically disconnect the input AC voltage. To avoid the risk of electrical shock, always remove the power cord from the printer when removal of the input AC voltage is required.



CAUTION—SHOCK HAZARD: To avoid the risk of electrical shock while troubleshooting with covers removed or doors open, do not touch the exposed wires or circuits while the printer is connected to an electrical outlet.



CAUTION—SHOCK HAZARD: To avoid the risk of electrical shock and to prevent damage to the printer, remove the power cord from the electrical outlet and disconnect all connections to any external devices before you connect or disconnect any cable, electronic board, or assembly.



CAUTION—HOT SURFACE: The inside of the printer might be hot. To reduce the risk of injury from a hot component, allow the surface to cool before touching it.



CAUTION—PINCH HAZARD: To avoid the risk of a pinch injury, use caution in areas marked with this label. Pinch injuries may occur around moving parts, such as gears, doors, trays, and covers.

Précautions de dépannage



ATTENTION—RISQUE D'ELECTROCUTION: Ce symbole indique un danger lié à des niveaux de tension dangereux dans la zone du produit à manipuler. Débranchez le produit avant de commencer, ou agissez avec prudence si le produit doit être alimenté pour effectuer l'opération.



ATTENTION—RISQUE D'ELECTROCUTION: Ce produit utilise un commutateur d'alimentation électronique. Il ne déconnecte pas physiquement la tension d'alimentation CA. Pour éviter tout risque d'électrocution, débranchez toujours le cordon d'alimentation de l'imprimante lorsque vous devez déconnecter la tension d'alimentation CA.



ATTENTION—RISQUE D'ELECTROCUTION: Pour éviter tout risque d'électrocution lors du dépannage de l'imprimante avec les capots retirés ou les portes ouvertes, prenez garde de ne pas toucher les fils ou circuits dénudés si l'imprimante est connectée à une prise électrique.



ATTENTION-RISQUE D'ELECTROCUTION: Pour éviter tout risque d'électrocution et éviter d'endommager l'imprimante, débranchez le cordon d'alimentation de la prise électrique et déconnectez toute connexion à tout périphérique externe avant de brancher ou débrancher des câbles ou circuits et assemblages électroniques.



ATTENTION—SURFACE CHAUDE : L'intérieur de l'imprimante risque d'être brûlant. pour réduire le risque de brûlure, laissez la surface ou le composant refroidir avant d'y toucher.



ATTENTION: RISQUE DE PINCEMENT: Pour éviter tout risque de blessure par pincement, agissez avec précaution au niveau des zones signalées par cette étiquette. Les blessures par pincement peuvent se produire autour des pièces mobiles telles que les engrenages, portes, tiroirs et capots.

Precauciones durante la solución de problemas



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Cuando vea este símbolo en el producto, existe peligro de tensiones peligrosas en el área del producto en la que está trabajando. Desconecte el producto antes de empezar o tenga cuidado si el producto debe recibir alimentación a fin de realizar la tarea.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Este producto utiliza un interruptor de corriente electrónico. No desconecta físicamente la entrada de voltaje de CA. Para evitar el riesgo de descarga eléctrica, desenchufe siempre el cable de alimentación de la impresora cuando sea necesario retirar la entrada de voltaje de CA.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Para evitar el riesgo de descarga eléctrica al solucionar problemas sin las cubiertas o con las puertas abiertas, no toque los cables ni los circuitos expuestos mientras la impresora está conectada a una toma de corriente.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Para evitar el riesgo de descargas eléctricas y daños en la impresora, retire el cable de alimentación de la toma eléctrica y desconecte todas las conexiones a dispositivos externos antes de conectar o desconectar cualquier cable, placa electrónica o conjunto.



PRECAUCIÓN: SUPERFICIE CALIENTE: El interior de la impresora podría estar caliente. Para evitar el riesgo de heridas producidas por el contacto con un componente caliente, deje que la superficie se enfríe antes de tocarlo.



PRECAUCIÓN: PELIGRO DE ATRAPAMIENTO: Para evitar el riesgo de lesión por atrapamiento, preste atención en las áreas marcadas con esta etiqueta. Las lesiones por atrapamiento se pueden producir en torno a partes móviles, tales como engranajes, puertas, bandejas y cubiertas.

Vorsichtsmaßnahmen bei der Fehlerbehebung



VORSICHT – STROMSCHLAGGEFAHR: Wenn Sie dieses Symbol sehen, besteht eine Gefahr durch gefährliche Spannungen in dem Produktbereich, in dem Sie arbeiten. Trennen Sie das Produkt von seiner Stromverbindung, bevor Sie beginnen, oder gehen Sie vorsichtig vor, wenn das Produkt für die Durchführung der Aufgabe mit Strom versorgt werden muss.



VORSICHT – STROMSCHLAGGEFAHR: Dieses Produkt verwendet einen elektronischen Leistungsschalter. Er trennt die Eingangswechselspannung nicht physikalisch. Um das Risiko eines elektrischen Schlags zu vermeiden, ziehen Sie stets das Netzkabel vom Drucker ab, wenn eine Abtrennung der Eingangswechselspannung erforderlich ist.



VORSICHT – STROMSCHLAGGEFAHR: Um die Gefahr eines Stromschlags während der Fehlerbehebung bei entfernten Abdeckungen oder offenen Klappen zu vermeiden, berühren Sie die freiliegenden Drähte oder Stromkreise nicht, wenn der Drucker an eine Steckdose angeschlossen ist.



VORSICHT – STROMSCHLAGGEFAHR: Um das Risiko eines elektrischen Schlags und Schäden am Drucker zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose und trennen Sie alle Verbindungen zu jeglichen externen Geräten, bevor Sie Kabel, Elektronikplatinen oder Baugruppen einstecken oder abziehen.



VORSICHT – HEISSE OBERFLÄCHE: Das Innere des Druckers kann sehr heiß sein. Vermeiden Sie Verletzungen, indem Sie heiße Komponenten stets abkühlen lassen, bevor Sie ihre Oberfläche berühren.



VORSICHT – QUETSCHGEFAHR: Um das Risiko einer Quetschung zu vermeiden, gehen Sie in Bereichen, die mit diesem Etikett gekennzeichnet sind, mit Vorsicht vor. Quetschungen können im Bereich von beweglichen Komponenten auftreten, wie z. B. Zahnrädern, Klappen, Fächern und Abdeckungen.

Troubleshooting overview

Performing the initial troubleshooting check

Before you start the troubleshooting procedures, perform the following checks:

- Use genuine Lexmark supplies and parts for the best results. Third-party supplies or parts may affect the performance, reliability, or life of the printer and its imaging components.
- With the power cord unplugged from the electrical outlet, check that the cord is free from the breakage, short circuits, disconnected wires, or incorrect connections.
- Make sure the printer is properly grounded. Check the power cord ground terminal.
- Make sure the power supply line voltage is within 10% of the rated line voltage.
- Make sure the machine is securely installed on a level surface in a well-ventilated area.
- Make sure the room temperature is between 16 and 32°C (60 and 90°F) and that the relative humidity is between 20 and 80%.
- Avoid sites generating ammonia gas, high temperature, high humidity (near water faucets, kettles, humidifiers), cold spaces, near open flames, and dusty areas.
- · Avoid sites exposed to direct sunlight.
- Make sure the paper is the recommended paper for this printer.
- · Make a trial print with paper from a newly opened package, and check the result.

Fixing print quality issues

Initial print quality check

Before troubleshooting print problems, perform the following:

- Make sure that the printer is located in an area that follows the recommended operating environment and power requirement specifications.
- Check the status of supplies. Replace supplies that are low or empty.
- Load 20-lb (75-80 g/m²) plain letter or A4 paper. Make sure that the paper guides are properly set and locked. From the control panel, set the paper size and type to match the paper loaded in the tray.

- From the control panel, navigate to Settings > Troubleshooting > Print Quality Test Pages.
- Print and keep the Menu Settings Page. The original page is used to restore the custom settings if necessary. From the control panel, navigate to Settings > Reports > Menu Settings Page, and then press OK.
- On the Menu Settings page, check if the print resolution is set to 600 dpi and the toner darkness is set to Normal.
- Check the toner cartridges for damage, and replace if necessary.
- Make sure that the correct print driver is used to prevent print problems. If the wrong print driver is installed, then incorrect characters could print and the copy may not fit the page correctly.

Supplies used to resolve print quality issues

For this family of printers, the following supplies are available to resolve print quality issues:


| Supply item | Part number |
|--------------------|---|
| Developer units | 78C0D60—40K page starter black developer unit |
| | • 78C0D70—40K page starter cyan developer unit |
| | 78C0D80—40K page starter magenta developer unit |
| | • 78C0D90—40K page starter yellow developer unit |
| | • 78C0D10—125K page black developer unit |
| | • 78C0D20—125K page cyan developer unit |
| | 78C0D30—125K page magenta developer unit |
| | • 78C0D40—125K page yellow developer unit |
| Imaging kits | • 78C0Z10—125K page black imaging kit |
| | • 78C0Z50—125K page black and color imaging kit |
| | • 78C0ZK0—125K page black return imaging kit |
| | 78C0ZV0—125K page black and color return imaging kit |
| Toner cartridges | Check the supplies guide for the part number of the cartridge used in your printer. |
| Waste toner bottle | 78C0W00—25K pages |

Notes:

- The photoconductor basket is not available.
- Before ordering a developer unit, make sure to check which imaging kit the customer is using.

Determining the installed imaging kit and developer unit types from the imaging kit label

- The 40K developer unit has *Starter* printed on the label.
- The 125K developer unit does not have *Starter* printed on the label.
- The 40K imaging kit has an A printed on the right side of the label of the photoconductor basket. It is found under the QR code on the label.
- The 125K does not have the A printed.



Determining the installed imaging kit and developer unit types from the printer reports

- The Menu Settings and Device Statistics reports can either be printed from the Reports menu on the control panel, or they can be accessed through the Embedded Web Server.
- Under the Other Supplies section of the Menu Settings pages, the capacity value indicates either 40K or 125K.
- Under the Supply Information section of the Device Statistics pages, the capacity value indicates either 40000 or 125000.

Supply item interchangeability

- The 40K developer units work only with the 40K page starter imaging kit.
- The 125K developer units work only with the 125K page imaging kit.

Using the imaging kit

- If a printer with a starter 40K imaging kit has a print defect that is traced to a cyan, magenta, yellow, or black photoconductor unit, then use the 125K black and color imaging kit as a replacement.
- If a printer with a 125K imaging kit has a print defect that is traced to a cyan, magenta, yellow, or black photoconductor unit, then use the 125K black imaging kit as a replacement.

Blurred print check

| Action | Yes | No |
|--|----------------|------------------------|
| Step 1 From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. Does the problem remain? | Go to step 2. | The problem is solved. |
| Step 2 Load paper from a fresh package. Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 a Remove the imaging kit. See "Imaging kit removal" on page 276. b Clean the printhead lenses. See "Cleaning the printhead lenses" on page 378. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Weather Station b Press OK or touch Start. Are the temperature and humidity levels reported similar to the actual temperature and humidity levels in the room? | Go to step 6. | Go to step 5. |
| Step 5 Perform the weather station service check. See "Weather station removal" on page 303. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 Make sure that the HVPS cable is properly connected to the HVPS connector on the controller board. Does the problem remain? | Go to step 7. | The problem is solved. |
| Step 7 Check the HVPS cable for continuity. Is there continuity? | Go to step 10. | Go to step 8. |

| Action | Yes | No |
|---|-------------------|------------------------|
| Step 8 Check the HVPS cable for damage, and replace if necessary. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 | Go to step 11. | Go to step 10. |
| a Remove the transfer module. See <u>"Transfer module removal"</u> on page 272. | | |
| b Make sure that the three HVPS contacts are properly positioned, and can freely move up and down. | | |
| Are the contacts properly positioned, and do they freely move up and down? | | |
| Step 10 | Go to step 11. | The problem is |
| a Reseat the HVPS. | | solved. |
| b Reseat the transfer module. | | |
| Does the problem remain? | | |
| Step 11 | Go to step 12. | The problem is |
| Replace the HVPS. See "HVPS removal" on page 267. | | solved. |
| Does the problem remain? | | |
| Step 12 | Go to step 13. | The problem is |
| Replace the transfer module. See "Transfer module removal" on page 272. | | solved. |
| Does the problem remain? | | |
| Step 13 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

Misaligned color check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Enter the Diagnostics menu, and then navigate to: | Go to step 2. | The problem is solved. |
| Advanced Print Quality Samples > Advanced Print Quality Test Pages | | |
| b Check pages G and H on the test pages to determine the color misalignment. | | |
| Is there color misalignment? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 2 From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Perform the auto alignment service check. See "Auto alignment service check" on page 71. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 Replace the printhead. See <u>"Printhead removal" on page 352</u> . Does the problem remain? | Contact the next level of support. | The problem is solved. |

Toner easily rubs off check



Note: Before performing this print quality check, go to the home screen and navigate to **Settings** > **Troubleshooting** > **Print Quality Test Pages**, and then perform the initial print quality check. See <u>"Initial print quality check" on page 31</u>.

| Actions | Yes | No |
|---|---------------|------------------------|
| Step 1 Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | Go to step 2. | The problem is solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 2 Check if the paper weight is supported. Note: If the weight is not supported, then load a supported one. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |

| Actions | Yes | No |
|---|-------------------|-------------------|
| Step 3 | Go to step 4. | The problem is |
| Load paper from a fresh package. | | solved. |
| Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. | | |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | Contact the next |
| a From the home screen, navigate to Settings > Device >Maintenance > Configuration Menu > Reports > Event Log | | level of support. |
| b Check the log history for fuser error codes. | | |
| Are fuser error codes logged? | | |
| Step 5 | Go to step 6. | The problem is |
| Perform the service check for the error code. | | solved. |
| Does the problem remain? | | |
| Step 6 | Contact the next | The problem is |
| Replace the LVPS. See <u>"LVPS removal" on page 250</u> . | level of support. | solved. |
| Does the problem remain? | | |


Gray or solid background check



| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Remove, and then insert the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 6. |
| a Place a narrow strip of paper over the gap between the developer units. | | |
| Note: Make sure that the paper stays in place when inserting the imaging kit to prevent the laser from discharging the photoconductor units. | | |
| b From the home screen, navigate to Settings > Reports > Print Quality Pages . | | |
| c Check the test pages for solid colors. | | |
| Is the solid color missing where the strip of paper was placed? | | |
| Step 3 | Go to step 4. | The problem is |
| Reseat the printhead cable on the controller board. | | solved. |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Replace the printhead. See <u>"Printhead removal" on page 352</u> . | | solved. |
| Does the problem remain? | | |
| Step 5 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |
| Step 6 | Go to step 7. | The problem is |
| Reseat the HVPS cable on the HVPS and on the JHVPS1 connector on the controller board. | | solved. |
| Does the problem remain? | | |
| Step 7 | Go to step 9. | Go to step 8. |
| Check the HVPS cable for continuity. | | |
| Is there continuity? | | |
| Step 8 | Go to step 9. | The problem is |
| Replace the HVPS cable. | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 9 | Go to step 11. | Go to step 10. |
| a Remove the transfer module. See <u>"Transfer module removal"</u> on page 272. | | |
| b Check if the three HVPS contacts are properly positioned, and if they can freely move up and down. | | |
| Are the contacts properly positioned, and do they freely move up and down? | | |
| Step 10 | Go to step 11. | The problem is |
| a Reseat the HVPS. | | solved. |
| b Reseat the transfer module. | | |
| Does the problem remain? | | |
| Step 11 | Go to step 12. | The problem is |
| Replace the imaging kit. See <u>"Imaging kit removal" on page</u> <u>276</u> . | | solved. |
| Does the problem remain? | | |
| Step 12 | Go to step 13. | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | | solved. |
| Does the problem remain? | | |
| Step 13 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |


Solid color or black image check



| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 1 Remove, and then insert the imaging kit. See "Imaging kit removal" on page 276. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| a Place a narrow strip of paper over the gap between the developer units. Note: Make sure that the paper stays in place when inserting the imaging kit to prevent the laser from discharging the photoconductor units. | Go to step 3. | Go to step 6. |
| b From the home screen, navigate to Settings > Reports > Print Quality Pages. c Check the test pages for solid colors. Is the solid color missing where the strip of paper was placed? | | |
| Step 3 Reseat the printhead cable on the controller board. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Replace the printhead. See <u>"Printhead removal" on page 352</u> . | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Replace the controller board. See <u>"Controller board removal" on page 345</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Reseat the HVPS cable on the HVPS and on the JHVPS1 connector on the controller board. | Go to step 7. | The problem is solved. |
| Does the problem remain? | | |
| Step 7 Check the HVPS cable for continuity. Is there continuity? | Go to step 9. | Go to step 8. |
| Step 8 Replace the HVPS cable. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 9 | Go to step 11. | Go to step 10. |
| a Remove the transfer module. See <u>"Transfer module removal"</u> on page 272. | | |
| b Check if the three HVPS contacts are properly positioned, and if they can freely move up and down. | | |
| Are the contacts properly positioned, and do they freely move up and down? | | |
| Step 10 | Go to step 11. | The problem is |
| a Reseat the HVPS. | | solved. |
| b Reseat the transfer module. | | |
| Does the problem remain? | | |
| Step 11 | Go to step 12. | The problem is |
| Replace the imaging kit. See <u>"Imaging kit removal" on page</u> <u>276</u> . | | solved. |
| Does the problem remain? | | |
| Step 12 | Go to step 13. | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | | solved. |
| Does the problem remain? | | |
| Step 13 | Contact the next | The problem is |
| Replace the controller board. See "Controller board removal" on page 345. | level of support. | solved. |
| Does the problem remain? | | |

Blank or white pages check



Pre-check procedure

Make sure to perform the following pre-check procedure before performing this service check:

- 1 From the home screen, navigate to **Settings** > **Troubleshooting** > **Print Quality Test Pages**.
- **2** Check page A to determine any missing colors.

3 If any one color or black is missing, then perform the missing color check. See <u>"Missing color check"</u> on page 55.

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Remove, and then insert the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 a Remove the imaging kit. See "Imaging kit removal" on page 276. b Check if the developer unit and the imaging kit capacities match. Note: The available capacities are 40K and 125K. | Go to step 4. | Go to step 3. |
| · | | |
| Step 3 Replace the mismatched developer unit. See "Developer unit removal" on page 266. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| a Remove the imaging kit. See "Imaging kit removal" on page 276. b Remove the developer units from the imaging kit. See "Developer unit removal" on page 266. c Check the contacts between the developer units and the PCUs on the imaging kit. | Go to step 6. | Go to step 5. |
| Are the contacts clean? | | |
| Step 5 Clean the contacts. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 | Go to step 7. | Go to step 8. |
| Check if the contacts between the developer units and the PCUs on the imaging kit are damaged. | To to step 7. | σο το στέρ ο. |
| Are the contacts damaged? | | |
| Step 7 Replace the damaged imaging kit component. See <u>"Supplies used to resolve print quality issues" on page 32</u> . | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 8 Reseat the printhead cable on the JPH1 connector on the controller board. Does the problem remain? | Go to step 9. | The problem is solved. |
| Step 9 | Go to step 10. | The problem is |
| Reseat the HVPS cable on the HVPS and on the JHVPS1 connector on the controller board. | Outo step 10. | solved. |
| Does the problem remain? | | |
| Step 10 Check the HVPS cable for continuity. | Go to step 11. | Go to step 12. |
| Is there continuity? | | |
| Step 11 Replace the HVPS cable. | Go to step 12. | The problem is solved. |
| Does the problem remain? | | |
| Step 12 a Remove the transfer module. See "Transfer module removal" on page 272. b Check if the three HVPS contacts are properly positioned, and if they can freely move up and down. Are the contacts properly positioned, and do they freely move up and down? | Go to step 14. | Go to step 13. |
| Step 13 | Go to step 14. | The problem is |
| Reposition the HVPS so that the pins can freely move up and down. Does the problem remain? | | solved. |
| Step 14 | Go to step 15. | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | | solved. |
| Does the problem remain? | | |
| Step 15 Replace the printhead. See <u>"Printhead removal" on page 352</u> . | Go to step 16. | The problem is solved. |
| Does the problem remain? | | |
| Step 16 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Horizontal white lines check



| Actions | Yes | No |
|---|---------------|------------------------|
| Step 1 Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | Go to step 2. | The problem is solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 2 Remove, and then insert the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 a Remove the HVPS. See "HVPS removal" on page 267. b Check if the HVPS cable connectors are pinched or damaged. Are the cable connectors pinched or damaged? | Go to step 4. | Go to step 5. |
| Step 4 Replace the HVPS cable. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 Check the cables connecting the HVPS to the controller board for proper connection, and reseat if necessary. Does the problem remain? | Go to step 6. | The problem is solved. |

| Actions | Yes | No |
|--|------------------------------------|------------------------|
| Step 6 Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Horizontal colored lines or banding check



| Actions | Yes | No |
|--|---------------|------------------------|
| Step 1 | Go to step 2. | The problem is solved. |
| Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | | Solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. | | |
| You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | The problem is |
| Load paper from a fresh package. | | solved. |
| Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. | | |
| Does the problem remain? | | |
| Step 3 | Go to step 4. | The problem is |
| Remove, and then reinstall the imaging kit. See "Imaging kit removal" on page 276. | | solved. |
| Does the problem remain? | | |

| Actions | Yes | No |
|---|------------------------------------|------------------------------------|
| Step 4 a Enter the Diagnostics menu, and then navigate to: Settings > Troubleshooting > Print Quality Test Pages b Check the test page for lines. | Go to step 5. | Contact the next level of support. |
| Do the lines appear in equal intervals? | | |
| Step 5 Perform the repeating defects check. See <u>"Repeating defects check" on page 60</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Text or images cut off check



| Actions | Yes | No |
|---|---------------|------------------------|
| Step 1 Adjust the paper guides in the tray to the correct position for the paper loaded. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Depending on your operating system, specify the paper size from the Printing Preferences or Print dialog. | Go to step 3. | The problem is solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. The paper size setting can be changed on the printer control panel. | | |
| Does the problem remain? | | |

| Actions | Yes | No |
|---|---------------|------------------------|
| Step 3 a Remove, and then insert the imaging kit. See "Imaging kit removal" on page 276. b Remove, and then insert the developer units. See "Developer unit removal" on page 266. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check for packing material left on the imaging components. Is there packing material left on the imaging components? | Go to step 5. | Go to step 6. |
| Step 5 Remove the packing material. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 a Remove the imaging kit. See "Imaging kit removal" on page 276. b Check if the developer unit hold downs are in their proper position. | Go to step 8. | Go to step 7. |

| Actions | Yes | No |
|--|------------------------------------|------------------------|
| Step 7 a Return the developer unit hold downs to their proper position. b Make sure that the developer unit hold downs are properly operating. | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |
| Step 8 Replace the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Mottled print and dots check



| Action | Yes | No |
|--|---------------|---------------|
| Step 1 | Go to step 2. | Go to step 6. |
| Check the printer for leaked toner contamination. | | |
| Is the printer free of leaked toner? | | |
| Step 2 | Go to step 4. | Go to step 3. |
| a From the home screen, navigate to Settings > Paper > TrayConfiguration > Paper Size/Type | | |
| b Check if the paper type and paper size settings match the paper loaded. | | |
| c Make sure that paper does not have a textured or rough finish. | | |
| Do the settings match? | | |

| Action | Yes | No |
|--|-------------------|----------------|
| Step 3 | Go to step 4. | The problem is |
| Depending on your operating system, specify the paper size and paper type from the Printing Preferences or Print dialog. | | solved. |
| Notes: | | |
| Make sure that the settings match the paper loaded. | | |
| You can also change the settings on the printer control panel. | | |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Load paper from a fresh package. | | solved. |
| Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. | | |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Remove, and then insert the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | | solved. |
| Does the problem remain? | | |
| Step 6 | Go to step 7. | The problem is |
| a Using a toner vacuum, clean the printer thoroughly. | | solved. |
| b Perform a print job to clear the remaining toner from the imaging components. | | |
| Does the problem remain? | | |
| Step 7 | Go to step 8. | The problem is |
| Replace the developer unit of the leaking color. See <u>"Supplies</u> used to resolve print quality issues" on page 32 to determine which developer unit to use. | | solved. |
| Does the problem remain? | | |
| Step 8 | Go to step 9. | The problem is |
| Replace the photoconductor unit. See <u>"Supplies used to resolve print quality issues" on page 32</u> to determine which photoconductor unit to use. | | solved. |
| Does the problem remain? | | |
| Step 9 | Contact the next | The problem is |
| Check the transfer module for proper installation and damage, and replace if necessary. See <u>"Transfer module removal" on page 272</u> . | level of support. | solved. |
| Does the problem remain? | | |
| | | |

Vertical white lines check



| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | Go to step 2. | The problem is solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 2 Load paper source with the recommended paper type. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Remove, and then insert the imaging kit. See <u>"Imaging kit removal"</u> on page 276. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 a Remove the waste toner bottle. See "Waste toner bottle service check" on page 105. b Remove the imaging kit. See "Imaging kit removal" on page 276. c Clean the printhead lenses. See "Cleaning the printhead lenses" on page 378. d From the home screen, navigate to Settings > Troubleshooting > Print Quality Test Pages. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 5 a Check the test pages and identify the affected color. b Replace the developer unit of the affected color. c If vertical streaks in all colors appear on page A, then replace the transfer module. See "Transfer module removal" on page 272. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Replace the photoconductor unit. See <u>"Supplies used to resolve print quality issues" on page 32</u> to determine which photoconductor unit to use. Does the problem remain? | Go to step 7. | The problem is solved. |
| Step 7 Check the transfer module for proper installation and damage, and replace if necessary. See "Transfer module removal" on page 272. Does the problem remain? | Go to step 8. | The problem is solved. |
| Step 8 Replace the printhead. See "Printhead removal" on page 352. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Ghost images check



| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Load the tray with the correct paper type. | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | The problem is |
| Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | | solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. | | |
| You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 3 | Go to step 4. | The problem is |
| From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. | | solved. |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Remove, and then reinstall the imaging kit. See "Imaging kit removal" on page 276. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | Go to step 7. |
| From the home screen, check the status of the black and color imaging kit. | | |
| Does the status indicate ok ? | | |
| Step 6 | Go to step 8. | Go to step 7. |
| Measure the distance from one point of the original image to the same point on the ghost image. | | |
| Is the distance 43.9 mm? | | |
| Step 7 | Go to step 8. | The problem is |
| Replace the developer unit of the affected color. See <u>"Supplies used to resolve print quality issues" on page 32</u> to determine which developer unit to use. | | solved. |
| Does the problem remain? | | |
| Step 8 | Go to step 9. | The problem is |
| Replace the imaging kit. See <u>"Imaging kit removal" on page</u> 276. | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------------------|
| Step 9 a From the home screen, navigate to Settings > Reports > Menu Settings Page | Go to step 10. | Contact the next level of support. |
| Note: Perform this step twice to clear any debris. b Check the fuser assembly for toner contamination. Is the fuser assembly contaminated? | | |
| Step 10 Replace the fuser. See <u>"Fuser removal" on page 311</u> . Does the problem remain? | Contact the next level of support. | The problem is solved. |

Dark print check




| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust b Perform a color adjustment. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Depending on your operating system, reduce the toner darkness from the Printing Preferences or Print dialog. | Go to step 3. | The problem is solved. |
| Note: You can also change the setting on the printer control panel. Does the problem remain? | | |

| Action | Yes | No |
|---|----------------|----------------|
| Step 3 | Go to step 4. | The problem is |
| Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. | | solved. |
| Notes: | | |
| Make sure that the setting matches the paper loaded. | | |
| You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | Go to step 6. |
| Check if the paper is textured or has a rough finish. | | |
| Is the paper textured or rough? | | |
| Step 5 | Go to step 6. | The problem is |
| Replace textured or rough paper with plain paper. | | solved. |
| Does the problem remain? | | |
| Step 6 | Go to step 7. | The problem is |
| Load paper from a fresh package. | | solved. |
| Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. | | |
| Does the problem remain? | | |
| Step 7 | Go to step 8. | Go to step 9. |
| a From the home screen, navigate to Settings > Troubleshooting> Print Quality Test Pages | | |
| b Check the test pages. | | |
| Is only one color affected? | | |
| Step 8 | Go to step 9. | The problem is |
| Enter the Diagnostics menu, and then navigate to: | | solved. |
| Printer diagnostics & adjustments > Color alignment adjust > AA adjustment row | | |
| Does the problem remain? | | |
| Step 9 | Go to step 10. | The problem is |
| Perform the toner patch sensing service check. See <u>"Toner patch sensing service check" on page 67</u> . | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 10 Check the HVPS cable for proper connection, and reseat if necessary. | Go to step 11. | The problem is solved. |
| Does the problem remain? | | |
| Step 11 Check the continuity of the main HVPS cable. | Go to step 13. | Go to step 12. |
| Does the cable have continuity? | | |
| Step 12 Replace the cable. | Go to step 13. | The problem is solved. |
| Does the problem remain? | | |
| Step 13 Check the contacts on the transfer module for damage. Are the contacts free of damage? | Go to step 15. | Go to step 14. |
| Step 14 Replace the transfer module. See "Transfer module removal" on page 272. Does the problem remain? | Go to step 15. | The problem is solved. |
| Step 15 Replace the HVPS. See "HVPS removal" on page 267. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Missing color check



| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Remove any packing material left on the imaging kit. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 a Make sure that the toner cartridges and developer units are properly installed. b Make sure that the developer units and the imaging kit match. See "Supplies used to resolve print quality issues" on page 32. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 a Remove, and then insert the imaging kit. See "Imaging kit removal" on page 276. b Remove, and then insert the waste toner bottle. See "Waste toner bottle removal" on page 280. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 | Go to step 6. | The problem is |
| Reseat the printhead cable connector on the controller board. | Go to step o. | solved. |
| Does the problem remain? | | |
| Step 6 a From the home screen, navigate to Settings > Troubleshooting > Print Quality Test Pages. b Check the test pages. ls only one color missing? | Go to step 7. | Go to step 10. |
| Step 7 | Go to step 8. | Go to step 10. |
| Check if the missing color is yellow. | 00 to step 0. | 30 to step 10. |
| Is the missing color yellow? | | |

| Action | Yes | No |
|---|----------------|------------------------|
| Step 8 Remove the imaging kit, and then check if the transfer module cleaning blade is in the correct position. | Go to step 9. | Go to step 10. |
| | | |
| Is the cleaning blade in the correct position? | | |
| Step 9 Replace the transfer module. See <u>"Transfer module removal" on page 272</u> . | Go to step 10. | The problem is solved. |
| Does the problem remain? | | |
| Step 10 | Go to step 12. | Go to step 11. |
| Check the contacts on the imaging kit and the developer unit of the missing color for dust or debris. | | |
| Are the contacts free of dust or debris? | | |
| Step 11 Clean the contacts between the developer unit and the imaging kit. | Go to step 12. | The problem is solved. |
| Does the problem remain? | | |
| Step 12 Replace the developer unit of the affected color. See <u>"Supplies"</u> used to resolve print quality issues" on page 32 to determine which developer unit to use. | Go to step 13. | The problem is solved. |
| Does the problem remain? | | |
| Step 13 | Go to step 15. | Go to step 14. |
| Check if the pins in the HVPS freely move in and out with an equal amount of spring force. | | |
| Do the pins freely move? | | |
| Step 14 | Go to step 15. | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|-------------------|----------------|
| Step 15 | Go to step 17. | Go to step 16. |
| a Remove the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Motor tests | | |
| c Go to the appropriate developer unit motor test for the missing color, and then run the test. | | |
| Does the motor run? | | |
| Step 16 | Go to step 17. | The problem is |
| Replace the defective EP drive motor. See "Motor (drive unit) removal" on page 247. | | solved. |
| Does the problem remain? | | |
| Step 17 | Go to step 19. | Go to step 18. |
| a Remove the imaging kit. See "Imaging kit removal" on page 276. | | |
| b While manually turning the motors, check if the couplers that drive the imaging kit move. | | |
| Do the couplers move? | | |
| Step 18 | Go to step 19. | The problem is |
| Replace the EP drive assembly. See <u>"EP drive assembly removal"</u> on page 247. | | solved. |
| Does the problem remain? | | |
| Step 19 | Go to step 20. | Go to step 21. |
| Check the Print Quality Test Pages if the black plane or the CMY plane is missing. | | |
| Is the black plane or the CMY plane missing? | | |
| Step 20 | Go to step 21. | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | | solved. |
| Does the problem remain? | | |
| Step 21 | Go to step 22. | The problem is |
| Replace the printhead. See <u>"Printhead removal" on page 352</u> . | | solved. |
| Does the problem remain? | | |
| Step 22 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

Uneven print density check



| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Remove, and then insert the imaging kit. See "Imaging kit removal" on page 276. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 a From the home screen, navigate to Settings > Device > Preferences b Check if the paper type and size settings match the paper type and size set on the tray. | Go to step 5. | Go to step 4. |
| Do the settings match? | | |
| Step 4 Change the paper size and type, or adjust the size settings in the tray. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Check the paper for texture or rough finish. | Go to step 6. | Go to step 7. |
| Is the paper textured or rough? | | |
| Step 6 Replace the textured or rough paper with plain paper. | Go to step 7. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 7 Clean the printhead lenses. See <u>"Cleaning the printhead lenses"</u> on page 378. | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |
| Step 8 Replace the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Repeating defects check



| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 Check the rollers in the paper path for dust or debris. | Go to step 2. | Go to step 3. |
| Is there dust or debris on any of the rollers? | | |
| Step 2 Clean the affected rollers. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|-------------------|------------------------------------|
| Step 3 a Print the Print Quality Test Pages. From the control panel, navigate to: Settings > Troubleshooting > Print Quality Test Pages b Measure the distance between the repeating defects on the affected color page. c Check if the distance matches any of the following measurements: Imaging kit 94.20 mm (3.71 in.) 29.80 mm (1.17 in.) 23.20 mm (0.91 in.) Developer unit 43.90 mm (1.73 in.) 45.50 mm (1.79 in.) Transfer module 37.70 mm (1.48 in.) 78.50 mm (3.09 in.) 55 mm (2.17 in.) Fuser 79.80 mm (3.14 in.) 94.30 mm (3.71 in.) | Yes Go to step 4. | Contact the next level of support. |
| Do the repeating defects match any of the measurements? | | |
| Step 4 Replace the component indicated by the measurement you observed in step 3. See "Supplies used to resolve print quality issues" on page 32 to determine which developer or imaging kit to use. Does the problem remain? | Go to step 5. | The problem is solved. |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 5 | Contact the next | The problem is |
| Refer to the following list for additional components that can be replaced to resolve a repeating defect. | level of support. | solved. |
| Replace the parts one at a time in the following order, and then print a test after replacing a part. | | |
| 99 mm interval | | |
| • Fuser | | |
| 94 mm interval | | |
| Imaging kit | | |
| 79 mm interval | | |
| Developer of the affected color | | |
| 75 mm interval | | |
| • Fuser | | |
| 55-56 mm interval | | |
| a Developer | | |
| b Transfer module | | |
| c EP drive | | |
| 44-45 mm interval | | |
| Developer | | |
| 33 mm interval | | |
| a Developer | | |
| b EP drive | | |
| 28 mm, 24 mm, 16 mm, 12-14 mm, 9 mm, and 4-5 mm interval | | |
| EP drive | | |
| 6-7 (mm) interval | | |
| a Fuser motor | | |
| b EP drive | | |
| Less than 1 mm interval | | |
| a EP drive | | |
| b Fuser motor | | |
| Note: If a part was replaced in the previous step, then contact the next level of support. | | |
| Does the problem remain? | | |

Light print check



| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 From the home screen, navigate to Settings > Print > Quality > Advanced Imaging > Color Adjust. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Depending on your operating system, increase the toner darkness from the Printing Preferences or Print dialog. | Go to step 3. | The problem is solved. |
| Note: You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 3 a From the home screen, navigate to Settings > Print > Quality > Color Saver. b Turn off Color Saver. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Depending on your operating system, specify the paper type from the Printing Preferences or Print dialog. Notes: | Go to step 5. | The problem is solved. |
| Make sure that the setting matches the paper loaded. You can also change the setting on the printer control panel. | | |
| Does the problem remain? | | |
| Step 5 Check if the paper is textured or rough. | Go to step 6. | Go to step 7. |
| Is the paper textured or rough? | | |

| Action | Yes | No |
|--|----------------|----------------|
| Step 6 | Go to step 7. | The problem is |
| Replace the textured or rough paper with plain paper. | | solved. |
| Does the problem remain? | | |
| Step 7 | Go to step 8. | The problem is |
| Load paper from a fresh package. | | solved. |
| Note: Paper absorbs moisture due to humidity. Store paper in its original wrapper until it is ready to be used. | | |
| Does the problem remain? | | |
| Step 8 | Go to step 9. | The problem is |
| Remove, and then reinstall the imaging kit. See <u>"Imaging kit</u> removal" on page 276. | | solved. |
| Does the problem remain? | | |
| Step 9 | Go to step 10. | The problem is |
| Remove, and then reinstall the developer unit of the affected color. See "Developer unit removal" on page 266. | | solved. |
| Does the problem remain? | | |
| Step 10 | Go to step 12. | Go to step 11. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Motor tests | | |
| b Select the motor of the affected color, and then run the test. | | |
| Does the motor run? | | |
| Step 11 | Go to step 12. | The problem is |
| Check the motor cable for proper installation, and reseat if necessary. | | solved. |
| Does the problem remain? | | |
| Step 12 | Go to step 13. | The problem is |
| Clean the printhead lenses. See <u>"Cleaning the printhead lenses"</u> on page 378. | | solved. |
| Does the problem remain? | | |
| Step 13 | Go to step 15. | Go to step 14. |
| Check the HVPS cable on the HVPS and on the JHVPS1 connector on the controller board for proper connection. | | |
| Is the cable properly connected at both ends? | | |

| Action | Yes | No |
|---|-------------------|------------------------|
| Step 14 Reconnect the cable. | Go to step 15. | The problem is solved. |
| Does the problem remain? | | |
| Step 15 | Go to step 17. | Go to step 16. |
| Check the cable for continuity. | | |
| Does the cable have continuity? | | |
| Step 16 | Go to step 17. | The problem is |
| Replace the HVPS cable. | | solved. |
| Does the problem remain? | | |
| Step 17 | Go to step 19. | Go to step 18. |
| a Remove the transfer module. See <u>"Transfer module removal"</u> on page 272. | | |
| b Check if the three contacts are visible and if they freely move. | | |
| Are the contacts visible and do they freely move? | | |
| Step 18 | Go to step 19. | The problem is |
| Replace imaging kit. See "Imaging kit removal" on page 276. | | solved. |
| Does the problem remain? | | |
| Step 19 | Go to step 20. | The problem is |
| Replace the transfer module. See <u>"Transfer module removal" on page 272</u> . | | solved. |
| Does the problem remain? | | |
| Step 20 | Contact the next | The problem is |
| Replace the HVPS. See <u>"HVPS removal" on page 267</u> . | level of support. | solved. |
| Does the problem remain? | | |

Skewed print check



| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Adjust the paper guides in the tray to the correct position for the paper loaded. b Make sure that the paper stack is below the maximum paper fill line. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Load paper from a fresh package. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Make sure that the paper loaded is supported. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the transfer module for proper installation and damage, and reinstall if necessary. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Perform the printhead adjustment. See "Registration adjustment" on page 240. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Check the pick rollers for dust or debris, and clean the rollers if necessary. | Go to step 7. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 7 | Contact the next | The problem is |
| If the paper from tray 1 are straight but the paper from the other tray are skewed, then perform the following: | level of support. | solved. |
| a Make sure that the paper guides in the tray are free to move and properly adjusted. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Registration adjust | | |
| c Select Duplex Skew or Option Skew. | | |
| Notes: | | |
| Duplex Skew affects the duplex sides. | | |
| Option Skew affects the tray 2, tray 3, and MPF paper. | | |
| Raising the value of the skew setting rotates the horizontal lines clockwise while the vertical lines will remain vertical. | | |
| d Print a test page. | | |
| Does the problem remain? | | |

Toner patch sensing service check

Pre check procedure

Note: Perform this procedure before performing the service check.

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Toner patch sensor adjust > Full calibration

- 2 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **3** Check pages G and H on the test pages to determine the color misalignment.
- 4 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.
- **5** Find AA adjustment, and then press **OK** or touch **Start**.

Note: This action triggers the auto align routine which performs the color alignment error corrections for the 0.42 mm, 0.84 mm, and 3 mm ranges.

- 6 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **7** Check pages G and H on the test pages to determine the color misalignment.
- 8 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.

Note: Ignore the AA adjustment pre-check in this step.

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 a From the home screen, navigate to Settings > Troubleshooting > Print Quality Test Pages. | Go to step 2. | The problem is solved. |
| b On the Device information section of the test page, check the CalSet values of the following: | | |
| C developer unit operating point | | |
| C laser operating point | | |
| C linearization stat | | |
| M developer unit operating point | | |
| M laser operating point | | |
| M linearization stat | | |
| Y developer unit operating point | | |
| Y laser operating point | | |
| Y linearization stat | | |
| K developer unit operating point | | |
| K laser operating point | | |
| K linearization stat | | |
| Are the CalSet values 0? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Perform the blank or white pages service check. See <u>"Blank or white pages check" on page 41</u> . | | |
| Was an issue found and resolved? | | |
| Step 3 | Go to step 4. | The problem is |
| Perform the auto alignment service check. See <u>"Auto alignment service check" on page 71</u> . | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------|------------------------|
| Step 4 a Enter the Diagnostics menu, and then navigate to: Printer setup > EP setup > Toner patch sensor adjust b Find Sensor gain characterization, and then press OK or touch Start. c Find Sensor gain verification, and then press OK or touch Start. d On the TPS Sensor Characterization and Verification Information page section of the print out, check the values of following: The PaperLeft-NDS Volts and PaperRight-DS Volts in the Patch Average from the TPS Verification Page section. The Left-NDS Volts and Right-DS Volts in the High Gain Bare Belt Characterization Results section. The mV value in the Amplifier Offset Characterization Result section. | The problem is solved. | Go to step 5. |
| Do the results approximately match the expected values and fall within the requirements? Step 5 Check the cables at the JTPS1 and JTPS2 connectors on the controller board for proper connection, and reseat if necessary. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 a Remove the transfer module. See "Transfer module removal" on page 272. b Make sure that the sensors (toner patch) are free of dust or debris. c Perform the auto alignment service check. See "Auto alignment service check" on page 71. Does the problem remain? | Go to step 7. | The problem is solved. |

| Ac | tion | Yes | No |
|----|---|----------------|-------------------|
| St | ep 7 | The problem is | Contact the next |
| а | Replace the sensors (toner patch). See <u>"Sensors (toner patch)"</u> removal" on page 264. | solved. | level of support. |
| b | Enter the Diagnostics menu, and then navigate to: | | |
| | Printer setup > EP setup > Toner patch sensor adjust | | |
| С | Find Sensor gain characterization, and then press \mathbf{OK} or touch $\mathbf{Start}.$ | | |
| d | Find Sensor gain verification, and then press OK or touch Start . | | |
| е | On the TPS Sensor Characterization and Verification Information page section of the print out, check the values of following: | | |
| | 1 The PaperLeft-NDS Volts and PaperRight-DS Volts in the Patch Average from the TPS Verification Page section. | | |
| | 2 The Left-NDS Volts and Right-DS Volts in the High Gain Bare Belt Characterization Results section. | | |
| | 3 The mV value in the Amplifier Offset Characterization Result section. | | |
| | the results approximately match the expected values and fall hin the requirements? | | |

Post check procedure

Note: Perform this procedure before performing the service check.

- **1** Enter the Diagnostics menu, and then navigate to:
 - Printer Setup > EP setup > Toner patch sensor adjust > Full calibration
- 2 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **3** Check pages G and H on the test pages to determine the color misalignment.
- 4 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.
- **5** Find AA adjustment, and then press **OK** or touch **Start**.
 - **Note:** This action triggers the auto align routine which performs the color alignment error corrections for the 0.42 mm, 0.84 mm, and 3 mm ranges.
- 6 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **7** Check pages G and H on the test pages to determine the color misalignment.
- 8 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.
 - **Note:** Ignore the AA adjustment pre-check in this step.
- **9** From the home screen, navigate to **Settings** > **Troubleshooting** > **Print Quality Test Pages**.

10 On the Device information section of the print quality test page, check the CalSet values of the following:

- C developer unit operating point
- C laser operating point
- C linearization stat
- M developer unit operating point
- M laser operating point
- M linearization stat
- Y developer unit operating point
- Y laser operating point
- Y linearization stat
- K developer unit operating point
- K laser operating point
- K linearization stat

11 If the CalSet values are not 0, then contact the next level of support.

Auto alignment service check

Pre check procedure

Note: Perform this procedure before performing the service check.

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Toner patch sensor adjust > Full calibration

- 2 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **3** Check pages G and H on the test pages to determine the color misalignment.
- 4 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.
- **5** Find AA adjustment, and then press **OK** or touch **Start**.

Note: This triggers the auto align routine which performs the color alignment error corrections for the 0.42 mm, 0.84 mm, and 3 mm ranges.

- 6 Navigate to Advanced Print Quality Samples > Advanced Print Quality Test Pages.
- **7** Check pages G and H on the test pages to determine the color misalignment.
- 8 If colors are misaligned, then navigate to **Printer diagnostics & adjustments > Color alignment adjust** > **Auto align**.

Note: Ignore the AA adjustment pre check in this step.

| Action | Yes | No |
|---|------------------------|------------------------|
| Step 1 a From the home screen, navigate to Settings > Troubleshooting > Print Quality Test Pages. b On the CalSet section of the test page, check the color alignment stat value. Is the value 0? | Go to step 2. | The problem is solved. |
| Step 2 a Perform the Blank or white pages check or Missing color check. See "Blank or white pages check" on page 41 or "Missing color check" on page 55. b Enter the Diagnostics menu, and then navigate to: | The problem is solved. | Go to step 3. |
| Printer setup > EP setup > Toner patch sensor adjust Find Sensor gain characterization, and then press OK or touch Start. Find Sensor gain verification, and then press OK or touch Start. On the TPS Sensor Characterization and Verification Information page section of the print out, check the values of following: The PaperLeft-NDS Volts and PaperRight-DS Volts in the Patch Average from the TPS Verification Page section. The Left-NDS Volts and Right-DS Volts in the High Gain Bare Belt Characterization Results section. The mV value in the Amplifier Offset Characterization Result section. | | |
| Do the results approximately match the expected values and fall within the requirements? Step 3 Check the cables at the JTPS1 and JTPS2 connectors on the controller board for proper connection, and reseat if necessary. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 a Remove the transfer module. See "Transfer module removal" on page 272. b Make sure that the sensors (toner patch) are free of dust or debris. Does the problem remain? | Go to step 5. | The problem is solved. |

| Ac | tion | Yes | No |
|----|---|----------------|-------------------|
| | | The problem is | Contact the next |
| а | Replace the sensors (toner patch). See <u>"Sensors (toner patch)</u> removal" on page 264. | solved. | level or support. |
| b | Enter the Diagnostics menu, and then navigate to: | | |
| | Printer setup > EP setup > Toner patch sensor adjust | | |
| С | Find Sensor gain characterization, and then press \mathbf{OK} or touch $\mathbf{Start}.$ | | |
| d | Find Sensor gain verification, and then press OK or touch Start . | | |
| е | On the TPS Sensor Characterization and Verification Information page section of the print out, check the values of following: | | |
| | 1 The PaperLeft-NDS Volts and PaperRight-DS Volts in the Patch Average part of the TPS Verilication Page section. | | |
| | 2 The Left-NDS Volts and Right-DS Volts in the High Gain Bare Belt Characterization Results section. | | |
| | 3 The mV value in the Amplifier Offset Characterization Result section. | | |
| | the results approximately match the expected values and fall hin the requirements? | | |

Post check procedure

Note: Perform this procedure before performing the service check.

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Color alignment adjust

2 Find AA adjustment, and then press **OK** or touch **Start**.

Note: This action triggers the auto align routine which performs the color alignment error corrections for the 0.42 mm, 0.84 mm, and 3 mm ranges.

3 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Toner patch sensor adjust > Full calibration

Note: This action triggers the auto align routine which performs the color alignment error corrections for the 0.42 mm range only.


- **4** From the home screen, navigate to **Settings** > **Troubleshooting** > **Print Quality Test Pages**.
- **5** On the CalSet section of the test page, check if the color alignment stat value is 0. If the value is not 0, then contact the next level of support.

Paper jams

Avoiding jams

Load paper properly

• Make sure that the paper lies flat in the tray.



- Do not load or remove a tray while the printer is printing.
- Do not load too much paper. Make sure that the stack height is below the maximum paper fill indicator.
- Do not slide paper into the tray. Load paper as shown in the illustration.



- Make sure that the paper guides are positioned correctly and are not pressing tightly against the paper or envelopes.
- Push the tray firmly into the printer after loading paper.

Use recommended paper

- Use only recommended paper or specialty media.
- Do not load paper that is wrinkled, creased, damp, bent, or curled.

• Flex, fan, and align the paper edges before loading.




- Do not use paper that has been cut or trimmed by hand.
- Do not mix paper sizes, weights, or types in the same tray.
- Make sure that the paper size and type are set correctly on the computer or printer control panel.
- Store paper according to manufacturer recommendations.

Identifying jam locations

Notes:

- When Jam Assist is set to On, the printer flushes blank pages or pages with partial prints after a jammed page has been cleared. Check your printed output for blank pages.
- When Jam Recovery is set to On or Auto, the printer reprints jammed pages.



| | Jam location |
|---|---|
| 1 | Standard bin |
| 2 | In the fuser |
| 3 | Below the fuser |
| 4 | Duplex unit |
| 5 | Trays |
| 6 | Manual feeder |
| 7 | Multipurpose feeder |
| | Note: The multipurpose feeder is available only in some printer models. |

200 paper jams

200 paper jam messages

| Error code | Description | Action |
|---------------|--|--|
| 200.02 | The paper fed from the MPF or manual feeder arrived at the sensor (input) earlier than expected. | See "Sensor (input) service check" on page 76. |
| 200.03 | The Paper fed from the MPF did not reach the sensor (input). | |
| 200.05 | The paper fed from the MPF or manual feeder never cleared the sensor (input). | |
| 200.06 | The paper fed from the MPF was not picked. The paper did not reach the sensor (input). | |
| 200.12 | The paper fed from tray 1 arrived at the sensor (input) earlier than expected. | |
| 200.15 | The paper fed from tray 1 never cleared the sensor (input). | |
| 200.16 | The paper fed from tray 1 was not picked. The paper did not reach the sensor (input). | |
| 200.22 | The paper fed from tray 2 arrived at the sensor (input) earlier than expected. | |
| 200.23 | The paper fed from tray 2 did not reach the sensor (input). | |
| 200.25 | The paper fed from tray 2 never cleared the sensor (input). | |
| 200.32 | The paper fed from tray 3 arrived at the sensor (input) earlier than expected. | |
| 200.33 | The paper fed from tray 3 did not reach the sensor (input). | |
| 200.35 | The paper fed from tray 3 never cleared the sensor (input). | |
| 200.91 | The paper remains on the sensor (input) during the warm up sequence. | |

Sensor (input) service check

Notes:

- If the paper source is an option tray, then make sure to perform the Option tray jam service check in addition to this check. See "Option tray jam service check" on page 95.
- Make sure that the tray 1 pass-through and manual feeder are free of dust or debris.

- Make sure that the duplex/manual feed sensor flag freely moves and is not obstructing the paper path.
- If a 232.x3 or 232.x5 error code appears on the display, then perform this check first at step 14, and then perform the Sensor (S1 duplex/manual feed) service check. See <u>"Sensor (redrive/duplex path 1)</u> service check" on page 86.

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 a Remove the tray insert. b Open the front door, and then remove the jammed paper. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Make sure that the sensor (input) paper path and the pass-through paper paths of any installed options are free of debris or dust. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Check if the error code is 200.1x. | Go to step 4. | Go to step 6. |
| Is the error code 200.1x? | | |
| Step 4 Make sure that the pick tires are free of dust or debris. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Replace the pick tires. <u>"Pick tire removal" on page 358</u> . | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Check the sensor (input) for proper installation and damage. | Go to step 7. | Go to step 14. |
| Is the sensor properly installed and free of damaged? | | |

| Action | Yes | No |
|--|----------------|------------------------|
| Step 7 | Go to step 9. | Go to step 8. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| b Find the sensor (Input). | | |
| c Remove the tray insert, and then rotate the input sensor flag (A) to toggle the sensor. | | |
| | | |
| Note: The flag must freely rotate and return to its original position. | | |
| Does the sensor status change while toggling the sensor? | | |
| Step 8 | Go to step 9. | The problem is solved. |
| Make sure that the gray cable is properly connected to the sensor (input). | | solved. |
| Does the problem remain? | | |
| Step 9 | Go to step 11. | Go to step 10. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| b Find the sensor (Tray 1 pick). | | |
| c Remove the tray insert, and then rotate the smart pick encoder to toggle the sensor. | | |
| Note: The counter on the display must increment. | | |
| Did the counter increment? | | |
| Step 10 | Go to step 11. | The problem is |
| Make sure that the red cable is properly connected to the sensor (tray 1 pick). | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|-------------------|----------------|
| Step 11 | Go to step 13. | Go to step 12. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Motor tests | | |
| b Select Pick (Tray 1) Duplex , and then Pick (Tray 1) Picking . | | |
| Did the motors run? | | |
| Step 12 | Go to step 13. | The problem is |
| a Turn off the printer. | | solved. |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Make sure that the JSP1 cable is properly connected on the controller board. | | |
| Does the problem remain? | | |
| Step 13 | Go to step 14. | Go to step 15. |
| Disconnect the cable, and then check the following voltages at the JSP1 connector on the controller board: | | |
| • Pin 14: 5 V dc | | |
| • Pin 15: 3.3 V dc | | |
| Are the voltage readings approximately the same? | | |
| Step 14 | Go to step 15. | The problem is |
| Replace the motor (drive unit). See "Motor (drive unit) removal" on page 247. | | solved. |
| Does the problem remain? | | |
| Step 15 | Contact the next | The problem is |
| Replace the controller board. See "Controller board removal" on page 345. | level of support. | solved. |
| Does the problem remain? | | |

202 paper jams

| Error code | Description | Action |
|------------|--|--|
| 202.03 | The paper fed from the MPF or manual feeder never arrived at the sensor (fuser exit). | See <u>"202.x3 error service check" on page 83</u> . |
| 202.04 | The paper fed from the MPF or manual feeder cleared the sensor (fuser exit) earlier than expected. | See "Sensor (fuser exit) service check" on page 81. |

| Error code | Description | Action |
|------------|--|---|
| 202.05 | The paper fed from the MPF or manual feeder never cleared the sensor (fuser exit). | See <u>"202.x5 error service check" on page 84</u> . |
| 202.13 | The paper fed from tray 1 never arrived at the sensor (fuser exit). | See <u>"202.x3 error service check" on page 83</u> . |
| 202.14 | The paper fed from tray 1 cleared the sensor (fuser exit) earlier than expected. | See "Sensor (fuser exit) service check" on page 81. |
| 202.15 | The paper fed from tray 1 never cleared the sensor (fuser exit). | See <u>"202.x5 error service check" on page 84</u> . |
| 202.23 | The paper fed from tray 2 never arrived at the sensor (fuser exit). | See <u>"202.x3 error service check" on page 83</u> . |
| 202.24 | The paper fed from tray 2 cleared the sensor (fuser exit) earlier than expected. | See "Sensor (fuser exit) service check" on page 81. |
| 202.25 | The paper fed from tray 2 never cleared the sensor (fuser exit). | See <u>"202.x5 error service check" on page 84</u> . |
| 202.33 | The paper fed from tray 3 never arrived at the sensor (fuser exit). | See <u>"202.x3 error service check" on page 83</u> . |
| 202.34 | The paper fed from tray 3 cleared the sensor (fuser exit) earlier than expected. | See "Sensor (fuser exit) service check" on page 81. |
| 202.35 | The paper fed from tray 3 never cleared the sensor (fuser exit). | See <u>"202.x5 error service check" on page 84</u> . |
| 202.91 | The paper remains on the sensor (fuser exit) during the warm up sequence. | See <u>"Sensor (fuser exit) service check" on page 81</u> . |

Sensor (fuser exit) service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 Open the front door to access the jam area, and then remove the jammed paper. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the sensor (A) for proper installation and damage. | Go to step 4. | Go to step 3. |
| A | | |
| Is the sensor properly installed and free of damage? | | |
| Step 3 Replace the sensor. See <u>"Sensor (fuser exit) removal" on page 252</u> . | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Select Sensor (Fuser exit). | Go to step 8. | Go to step 5. |
| Does the sensor status change while toggling the sensor? | | |
| Step 5 a Turn off the printer. b Remove the rear cover. See "Rear cover removal" on page 343. c Make sure that the cable on the JBIN1 connector on the controller board is properly connected. Does the problem remain? | Go to step 6. | The problem is solved. |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 6 a Disconnect the JBIN1 cable on the controller board. b Perform a POR, and then check the following voltages at the JBIN1 connector on the controller board: Pin 4: 5 V dc Pin 5: 3.3 V dc Are values approximately the same? | Go to step 7. | Go to step 12. |
| Step 7 Make sure that the fuser exit sensor cable is properly connected at both ends. Does the problem remain? | Go to step 8. | The problem is solved. |
| Step 8 a Make sure that the fuser exit sensor cable has continuity. b Check the cable for damage, and replace if necessary. Does the problem remain? | Go to step 9. | The problem is solved. |
| Step 9 Replace the sensor. See <u>"Sensor (fuser exit) removal" on page 252</u> . Does the problem remain? | Go to step 10. | The problem is solved. |
| Step 10 a Check the fuser for proper installation and damage. b Check the belt, rollers, and guides for wear or damage, and replace if necessary. Is the fuser properly installed and free of damage? | Go to step 12. | Go to step 11. |
| Step 11 Replace the fuser. See "Fuser removal" on page 311. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 12 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

202.x3 error service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 a Remove the imaging kit. See <u>"Imaging kit removal" on page 276.</u> | Go to step 6. | Go to step 2. |
| b Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Motor tests c Select K+ITM. | | |
| Does the transfer belt move while the motor is running? | | |
| Step 2 Make sure that the transfer belt coupler on the EP drive is engaged with the white transfer module links. | Go to step 6. | Go to step 3. |
| Notes: | | |
| Do not touch the belt.If available, use a mirror. | | |
| | | |
| Is the transfer belt coupler properly engaged? | Co to oto a 4 | The graph land is |
| Step 3 Remove, and then reinstall the transfer module. See <u>"Transfer module removal" on page 272</u> . | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Replace the transfer module guide. See <u>"Transfer module guide removal" on page 335</u> . | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Replace the EP drive. See <u>"EP drive assembly removal" on page 247</u> . | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|---|------------------------|
| Step 6 Check the transfer belt for tear and damage. | Go to step 8. | Go to step 7. |
| Is the belt free of tear and damage? | | |
| Step 7 Replace the transfer module. See <u>"Transfer module removal" on page 272</u> . Does the problem remain? | Perform the Sensor (fuser exit) service check. See <u>"Sensor</u> (fuser exit) service check" on page 81. | The problem is solved. |
| Step 8 a Remove the transfer module. See "Transfer module removal" on page 272. b Using a pair of needle-nose pliers, turn the white coupler on the belt counter-clockwise. | Perform the Sensor (fuser exit) service check. See "Sensor (fuser exit) service check" on page 81. | Go to step 9. |
| Step 9 | Perform the Sensor | The problem is |
| Replace the transfer module. See <u>"Transfer module removal" on page 272</u> . | (fuser exit) service check. See <u>"Sensor</u> (fuser exit) service check" on page 81. | solved. |
| Does the problem remain? | S. Con Dage OI. | |

202.x5 error service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Fan the paper stack before loading. b Make sure that the side and rear tray guides are set to the correct paper size being loaded. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 2 | Go to step 5. | Go to step 3. |
| a Enter the diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| b Find the sensor (Fuser exit). | | |
| Does the sensor status change while toggling the sensor? | | |
| Step 3 | Go to step 4. | The problem is |
| a Make sure that the sensor cable is properly connected on both ends. | | solved. |
| b Check the sensor cable for damage, and replace if necessary. | | |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Replace the sensor (fuser exit). See "Sensor (fuser exit) removal" on page 252. | | solved. |
| Does the problem remain? | | |
| Step 5 | Contact the next | The problem is |
| Replace the fuser. See <u>"Fuser removal" on page 311</u> . | level of support. | solved. |
| Does the problem remain? | | |

231 paper jams

231 paper jam messages

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 231.03 | The paper fed from the MPF or manual feeder did not reach the sensor (redrive/duplex path 1) during a duplex print job. | · · · · · · · · · · · · · · · · · · · |
| 231.05 | The paper fed from the MPF or manual feeder never cleared the sensor (redrive/duplex path 1) during a duplex print job. | |
| 231.13 | The paper fed from tray 1 did not reach the sensor (redrive/duplex path 1) during a print job. | |
| 231.15 | The paper fed from tray 1 never cleared the sensor (redrive/duplex path 1) during a duplex print job. | |
| 231.23 | The paper fed from tray 2 did not reach the sensor (redrive/duplex path 1) during a print job. | |
| 231.25 | The paper fed from tray 2 never cleared the sensor (redrive/duplex path 1) during a duplex print job. | |
| 231.33 | The paper fed from tray 3 did not reach the sensor (redrive/duplex path 1) during a print job. | |
| 231.35 | The paper fed from tray 3 never cleared the sensor (redrive/duplex path 1) during a duplex print job. | |

Sensor (redrive/duplex path 1) service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Make sure that the tray side guides for all the trays are properly adjusted. | Go to step 2. | The problem is solved. |
| b Make sure that the paper type and size settings match the paper type and size set on the tray. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 4. | Go to step 3. |
| Make sure that the paper size and weight are supported by the duplex. See <u>"Supported paper sizes" on page 22</u> and <u>"Supported paper weights" on page 26</u> . | | |
| Are the paper size and weight supported? | | |

| Action | Yes | No |
|--|---------------|------------------------|
| Step 3 Load a supported paper size and weight. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 a Make sure that the printer is on a hard and flat surface, so that the tray is properly seated in the printer, and the S1 actuator can properly move. b Open the front door, and then remove the jammed paper. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 Remove the tray insert, and then make sure that the sensor (A) is free of debris and obstructions. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (Redrive/duplex path 1). c Use a piece of paper to toggle the sensor. Does the sensor status change while toggling the sensor? | Go to step 7. | Go to step 11. |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 7 Check if the actuator (B) in the tray freely rotates and return to its home position. | Go to step 9. | Go to step 8. |
| B | | |
| Does the flag freely rotate and return to its home position? | | |
| Step 8 Replace the tray insert. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 Turn the gear (C) to check if the manual feed shaft freely rotates. | Contact the next level of support. | Go to step 10. |
| C | | |
| Does the manual feed shaft freely rotate? | | |
| Step 10 Replace the tray insert. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|----------------|----------------|
| Step 11 | Go to step 12. | The problem is |
| a Turn off the printer. | | solved. |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Make sure that the cable on the JFUSES2 connector on the controller board is properly connected. | | |
| Does the problem remain? | | |
| Step 12 | Go to step 13. | The problem is |
| Check the cable for continuity or damage, and replace if necessary. | | solved. |
| Does the problem remain? | | |
| Step 13 | Go to step 14. | Go to step 22. |
| Turn on the printer, and then check for the following voltage values at the JFUSES2 connector on the controller board: | | |
| • Pin 7: +5 V dc | | |
| Pin 8: Ground | | |
| • Pin 9: +3.3 V dc | | |
| Are values approximately the same? | | |
| Step 14 | Go to step 15. | The problem is |
| Replace the sensor (redrive/duplex path 1). See <u>"Sensor (duplex) removal" on page 334</u> . | | solved. |
| Does the problem remain? | | |
| Step 15 | Go to step 16. | Go to step 22. |
| Check if the following error codes appear: | | |
| • 231.x3 | | |
| • 231.x5 | | |
| • 232.x3 | | |
| • 232.x5 | | |
| Did any of the error codes appear? | | |
| Step 16 | Go to step 17. | Go to step 18. |
| Run a duplex print job from tray 1 and the option trays. | | |
| Does the error only occur from an option tray? | | |
| Step 17 | Go to step 18. | The problem is |
| Replace the defective option tray. | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 18 Check the fuser rollers for excessive wear or damage. Do the rollers show excessive wear or damage? | Go to step 19. | Go to step 20. |
| Step 19 Replace the fuser. See <u>"Fuser removal" on page 311</u> . Does the problem remain? | Go to step 20. | The problem is solved. |
| Step 20 Check the two duplex aligner rollers (D) for excessive wear or damage. Do the rollers show excessive wear or damage? | Go to step 21. | Go to step 22. |
| Step 21 Replace the front door inner deflector. See "Front door inner deflector removal" on page 287. Does the problem remain? | Go to step 22. | The problem is solved. |
| Step 22 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

232 paper jams

| Error code | Description | Action |
|------------|--|--|
| 232.02 | The paper fed from the MPF or manual feeder arrived at the sensor (input) earlier than expected during a duplex print job. | See "Sensor (input) service check" on page 76. |
| 232.12 | The paper fed from tray 1 arrived at the sensor (input) earlier than expected during a duplex print job. | |
| 232.22 | The paper fed from tray 2 arrived at the sensor (input) earlier than expected during a duplex print job. | |
| 232.32 | The paper fed from tray 3 arrived at the sensor (input) earlier than expected during a duplex print job. | |
| 232.03 | The paper fed from the MPF or manual feeder never arrived at the sensor (input) during a duplex print job. | |
| 232.13 | The paper fed from tray 1 never arrived at the sensor (input) during a duplex print job. | |
| 232.23 | The paper fed from tray 2 never arrived at the sensor (input) during a duplex print job. | |
| 232.33 | The paper fed from tray 3 never arrived at the sensor (input) during a duplex print job. | |
| 232.05 | The paper fed from the MPF or manual feeder never cleared the sensor (input) during a duplex print job. | |
| 232.15 | The paper fed from tray 1 never cleared the sensor (input) during a duplex print job. | |
| 232.25 | The paper fed from tray 2 never cleared the sensor (input) during a duplex print job. | |
| 232.35 | The paper fed from tray 3 never cleared the sensor (input) during a duplex print job. | |

24y paper jams

241 paper jam messages

| Error code | Description | Action |
|------------|--|--|
| 241.05 | The paper fed from the manual feeder never cleared the sensor (redrive/duplex path 1). | See <u>"Sensor (redrive/duplex path 1) service check" on page 86</u> . |
| 241.82 | The motor (tray 1 pick) failed to achieve the expected speed. | See "Motor (tray 1 pick/duplex) service check" on page 130. |
| 241.83 | The motor (tray 1 pick) stalled. | |
| 241.84 | The motor (tray 1 pick) is running too slow. | |
| 241.91 | The paper remains on the sensor (redrive/duplex path 1) during the warm-up sequence. | See "Sensor (redrive/duplex path 1) service check" on page 86. |

| Error code | Description | Action |
|------------|---|---|
| 242.05 | The paper fed from the MPF never cleared the sensor (tray 2 pass-through). | See "Option tray jam service check" on page 95. |
| 242.06 | The paper fed from the MPF was not picked. The paper did not reach the sensor (tray 2 pass-through). | |
| 242.21 | The paper fed from tray 2 remains detected at the sensor (tray 2 pass-through). | |
| 242.22 | The paper fed from tray 2 arrived too early at the sensor (tray 2 pass-through). | |
| 242.25 | The paper fed from tray 2 cleared the sensor (tray 2 pass-through) too late. | |
| 242.26 | The paper fed from the tray 2 was not picked. The paper did not reach the sensor (tray 2 pass-through). | |
| 242.31 | The paper fed from tray 3 remains detected at sensor (tray 2 pass-through). | |
| 242.32 | The paper fed from tray 3 arrived too early at the sensor (tray 2 pass-through). | |
| 242.33 | The paper fed from tray 3 did not reach the sensor (tray 2 pass-through). | |
| 242.35 | The paper fed from tray 3 cleared the sensor (tray 2 pass-through) too late. | |

| Error code | Description | Action |
|------------|--|---|
| 242.7 | The motor (tray 2 pass-through) does not turn on. | |
| 242.71 | The motor (tray 2 pass-through) does not turn off. | <u>page 128</u> . |
| 242.72 | The motor (tray 2 pass-through) failed to achieve the expected speed. | |
| 242.73 | The motor (tray 2 pass-through) stalled. | |
| 242.74 | The motor (tray 2 pass-through) is running too slow. | |
| 242.75 | The motor (tray 2 pass-through) is running too fast. | |
| 242.76 | The motor (tray 2 pass-through) moved too long. | |
| 242.8 | The motor (tray 2 pick) does not turn on. | |
| 242.81 | The motor (tray 2 pick) does not turn off. | |
| 242.82 | The motor (tray 2 pick) failed to achieve the expected speed. | |
| 242.83 | The motor (tray 2 pick) stalled. | |
| 242.84 | The motor (tray 2 pick) is running too slow. | |
| 242.85 | The motor (tray 2 pick) is running too fast. | |
| 242.86 | The motor (tray 2 pick) moved too long. | |
| 242.91 | The paper remains detected at the sensor (tray 2 pass-through) during the warm up sequence. | See "Option tray jam service check" on page 95. |
| 242.92 | The paper fed from an unknown source arrived too early at the sensor (tray 2 pass-through). | |
| 242.93 | The paper fed from an unknown source did not reach the sensor (tray 2 pass-through). | |
| 242.95 | The paper fed from an unknown source cleared the sensor (tray 2 pass-through) too late. | |
| 242.96 | The paper fed from an unknown source was not picked. The paper did not reach the sensor (tray 2 pass-through). | |

| Error code | Description | Action |
|------------|--|--|
| 243.31 | The paper fed from tray 3 remains detected at the sensor (tray 3 pass-through). | See "Option tray jam service check" on page 95. |
| 243.32 | The paper fed from tray 3 arrived too early at the sensor (tray 3 pass-through). | |
| 243.35 | The paper fed from tray 3 cleared the sensor (tray 3 pass-through) too late. | |
| 243.36 | The paper fed from tray 3 was not picked. The paper did not reach the sensor (tray 3 pass-through). | |
| 243.70 | The motor (tray 3 pass-through) does not turn on. | |
| 243.71 | The motor (tray 3 pass-through) does not turn off. | <u>page 128</u> . |
| 243.72 | The motor (tray 3 pass-through) failed to achieve the expected speed. | |
| 243.73 | The motor (tray 3 pass-through) stalled. | |
| 243.74 | The motor (tray 3 pass-through) is running too slow. | |
| 243.75 | The motor (tray 3 pass-through) is running too fast. | |
| 243.76 | The motor (tray 3 pass-through) moved too long. | |
| 243.80 | The motor (tray 3 pick) does not turn on. | |
| 243.81 | The motor (tray 3 pick) does not turn off. | |
| 243.82 | The motor (tray 3 pick) failed to achieve the expected speed. | |
| 243.83 | The motor (tray 3 pick) stalled. | |
| 243.84 | The motor (tray 3 pick) is running too slow. | See "Option tray jam service check" on |
| 243.85 | The motor (tray 3 pick) is running too fast. | <u>page 95</u> . |
| 243.86 | The motor (tray 3 pick) moved too long. | |
| 243.91 | The paper remains detected at the sensor (tray 3 pass-through) during the warm-up sequence. | See "Option tray motor service check" on page 128. |
| 243.92 | The paper fed from an unknown source arrived too early at the sensor (tray 3 pass-through). | |
| 243.93 | The paper fed from an unknown source did not reach the sensor (tray 3 pass-through). | |
| 243.95 | The paper fed from an unknown source cleared the sensor (tray 3 pass-through) too late. | |
| 243.96 | The paper fed from an unknown source was not picked. The paper did not reach the sensor (tray 3 pass-through). | |

Option tray jam service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Check if the paper type and size settings match the paper type and size loaded on the tray. | Go to step 3. | Go to step 2. |
| Do the settings match? | | |
| Step 2 Change the paper size and type, or adjust the size setting in the tray. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 | Go to step 4. | The problem is |
| Make sure that the rear and side guides in the trays are properly adjusted. | oo to step ii | solved. |
| Does the problem remain? | | |
| Step 4 Make sure that the trays and the tray 1 pass-through are free of dust or debris. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| a Make sure that the tray pick tires are free of dust or debris. b Check the tray pick tires for proper installation and damage, and reseat or replace if necessary. | | solved. |
| Does the problem remain? | | |
| Step 6 a Make sure that the pass-through sensors in the option trays are properly installed and free of damage, and replace if necessary. b Make sure that the sensors are free of debris and obstructions. | Go to step 7. | The problem is solved. |
| Does the problem remain? | | |
| Step 7 Check the tray pass-through sensors and actuators for damage. Are the sensors and actuators free of damage? | Go to step 9. | Go to step 8. |
| Step 8 | Go to step 9. | The problem is |
| Replace the affected tray. | So to step 3. | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|----------------|----------------|
| Step 9 | Go to step 11. | Go to step 10. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| b Find the sensor (Pass-through). | | |
| c Find the sensor (MPF media present). | | |
| Do the sensors status change while toggling the sensor? | | |
| Step 10 | Go to step 11. | The problem is |
| Check the affected sensor for proper installation, and reseat if necessary. | | solved. |
| Does the problem remain? | | |
| Step 11 | Go to step 12. | Go to step 13. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| b Select Pick (tray x) motor test , and then press OK or touch Start . | | |
| Note: Make sure to perform the motor test in both directions. | | |
| c Select Pass-through (tray x) motor test, and then press OK or | | |
| touch Start. | | |
| Note: Make sure to perform the motor test in both directions. | | |
| Did the motors run? | | |
| Step 12 | Go to step 13. | The problem is |
| Perform a print test. | | solved. |
| Does the problem remain? | | |
| Step 13 | Go to step 14. | The problem is |
| Make sure that the option connector in the subframe is properly installed in tray 2. | | solved. |
| Does the problem remain? | | |
| Step 14 | Go to step 15. | The problem is |
| Make sure that the cable at the JOPT1 connector on the controller board is properly connected. | | solved. |
| Does the problem remain? | | |
| Step 15 | Go to step 17. | Go to step 16. |
| Check the continuity of the option cable on the printer. | Ου το στερ 17. | ου το στερ το. |
| Does the cable have continuity? | | |

| Action | Yes | No |
|--|-------------------|------------------------|
| Step 16 Replace the cable. | Go to step 17. | The problem is solved. |
| Does the problem remain? | | |
| Step 17 | Contact the next | The problem is |
| Check the tray connections for proper installation and damage, and replace the affected tray if necessary. | level of support. | solved. |
| Does the problem remain? | | |

User attendance messages

Non-Lexmark supply

The printer has detected a non-Lexmark supply or part installed in the printer.

The Lexmark printer is designed to function best with genuine Lexmark supplies and parts. Use of third-party supplies or parts may affect the performance, reliability, or life of the printer and its imaging components.

All life indicators are designed to function with Lexmark supplies and parts and may deliver unpredictable results if third-party supplies or parts are used. Imaging component usage beyond the intended life may damage the Lexmark printer or associated components.

Warning—Potential Damage: Use of third-party supplies or parts can affect warranty coverage. Damage caused by the use of third-party supplies or parts may not be covered by the warranty.

If a customer accepts any and all of these risks and proceeds with the use of non-genuine supplies or parts in the printer, then instruct the customer to press and hold **X** and **#** simultaneously from the control panel for 15 seconds. Do not perform this action yourself.

If a customer does not want to accept these risks, then remove the third-party supply or part from the printer and install a genuine Lexmark supply or part. For more information, see **Using genuine Lexmark parts and supplies**.

If the printer does not print after pressing and holding \mathbf{X} and $\mathbf{\#}$ simultaneously for 15 seconds, then instruct the customer to reset the supply usage counter.

- **1** From the control panel, navigate to:
 - Settings > Device > Maintenance > Configuration Menu > Supply Usage And Counters
- 2 Select the part or supply to reset, and then select **Start**.
- **3** Read the warning message, and then select **Continue**.
- **4** Press and hold **X** and **#** simultaneously for 15 seconds to clear the message.

Note: If the customer is unable to reset the supply usage counters, then the customer should return the item to the place of purchase.

24 user attendance errors

24 user attendance error messages

| Error code | Description | Action |
|------------|---|---|
| 24.04 | The printer tried to do a duplex print job on a sheet that was too short or too narrow for the duplex path. | Perform one of the following: Load the correct paper size in the tray. From the control panel, select Continue to clear the message, and then print using a different tray paper source. Check the tray length and width guides, and then make sure that paper is properly loaded in the tray. Make sure that the correct paper size and type are specified in the Printing Preferences or Print dialog. Make sure that the paper size and type are specified in the Paper menu on the printer control panel. Cancel the print job. |

31 user attendance errors

31 user attendance error messages

| Error code | Description | Action |
|------------|--|--|
| 31.35z | Waste toner bottle smart chip or sensor problem. | See <u>"Waste toner bottle service check" on page 105</u> . |
| 31.40z | The printer failed to replenish due to bad auger gear and toner cartridge gear mesh. | Insert the toner cartridge of the affected color. |
| 31.40z | Black toner cartridge smart chip or sensor problem. | See "Missing toner cartridge, developer unit, or photoconductor unit service check" on |
| 31.41z | Cyan toner cartridge smart chip or sensor problem. | <u>page 100</u> . |
| 31.42z | Magenta toner cartridge smart chip or sensor problem. | |
| 31.43z | Yellow toner cartridge smart chip or sensor problem. | |
| 31.60z | Black imaging kit or photoconductor smart chip or sensor problem. | |
| 31.65z | Black and color imaging kit smart chip or sensor problem. | |

The following are the meaning of the z codes:

- A—Missing
- B—Missing Mux
- C—Read failure
- D-Write failure
- E—Device information read failure
- F—Authentication error
- G—Read failure

32 user attendance errors

32 user attendance error messages

| Error code | Description | Action |
|------------|---|---|
| 32.40z | Black toner cartridge unsupported error. | See <u>"Missing toner cartridge, developer unit, or</u> |
| 32.41z | Cyan toner cartridge unsupported error. | photoconductor unit service check" on page 100. |
| 32.42z | Magenta toner cartridge unsupported error. | |
| 32.43z | Yellow toner cartridge unsupported error. | |
| 32.65z | Black and color imaging kit or photoconductor unit unsupported error. | |

The following are the meaning of the z codes:

- A—Unsupported memory map version in the smart chip
- B—Failed capacity class/model compatibility check
- C—Failed OEM check
- D—Failed SWE marriage check
- E—The supply is on the revoked list
- F—The toner cartridge or imaging kit is MICR, and the firmware release does not support MICR

33 user attendance errors

33 user attendance error messages

Note: See "Non-Lexmark supply" on page 97.

| Error code | Description | Action |
|------------|---|--|
| 33.40z | Non-Lexmark black toner cartridge. The smart chip contents have been manipulated by a third party manufacturer. | See "Missing toner cartridge, developer unit, or photoconductor unit service check" on page 100. |
| 33.41z | Non-Lexmark cyan toner cartridge. The smart chip contents have been manipulated by a third party manufacturer. | |
| 33.42z | Non-Lexmark magenta toner cartridge. The smart chip contents have been manipulated by a third party manufacturer. | |
| 33.43z | Non-Lexmark yellow cartridge. The smart chip contents have been manipulated by a third party manufacturer. | |
| 33.50z | Non-Lexmark black developer unit. The smart chip contents have been manipulated by a third party manufacturer. | |
| 33.64z | Non-Lexmark black and color imaging kit. The smart chip contents have been manipulated by a third party manufacturer. | |

The following are the meaning of the z codes:

- A— Non-genuine Lexmark supply
- B— Supply is exposed

Missing toner cartridge, developer unit, or photoconductor unit service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Make sure that the toner cartridge or photoconductor unit is properly installed. b Check the error code on the display, and then verify if the toner cartridge, developer unit, or photoconductor unit is supported. c Replace the unsupported supply. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the HVPS and pogo pin cables for proper connection, and reseat if necessary. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|------------------------|
| Step 3 a Make sure that the pogo pin contacts are free from dust or debris. b Check the pogo pin contacts for damage, and replace if necessary. | Go to step 4. | The problem is solved. |
| Does the problem remain? | _ | |
| Step 4 Replace the imaging kit. See <u>"Imaging kit removal" on page 276</u> . | Go to step 5. | The problem is solved. |
| Note: See <u>"Supplies used to resolve print quality issues" on page 32</u> to determine which imaging kit to use. | | |
| Does the problem remain? | | |
| Step 5 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (Toner meter). | Go to step 7. | Go to step 6. |
| Does the sensor status change while toggling the sensor? | | |
| Step 6 Replace the TMC card. See <u>"TMC card removal" on page 261</u> . Does the problem remain? | Go to step 7. | The problem is solved. |
| Step 7 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

34 user attendance errors

34 user attendance error messages

| Error code | Description | Action |
|------------|---|---|
| 34.04 | The printer tried to do a duplex print job on a sheet that was too short or too narrow for the duplex path. | Perform one of the following: Load the correct paper size in the tray. From the control panel, select Continue to clear the message, and then print using a different tray paper source. Check the tray length and width guides, and then make sure that paper is properly loaded in the tray. Make sure that the correct paper size and type are specified in the Printing Preferences or Print dialog. Make sure that the paper size and type are specified in the Paper menu on the printer control panel. Cancel the print job. |

42 user attendance errors

42 user attendance error messages

| Error code | Description | Action |
|------------|-------------|--|
| 42.xyz | | See <u>"Region mismatch service check" on page 103</u> . |

The following are the meaning of the xyz codes:

- A b z—A is the printer region (error values 1 to 6, and 0 always matches)
- a B z—B is the cartridge region (values 0 to 6)
- a b Z—Z is the cartridge color (CMY or K)
- 0 b z—Region 0: The machine is not regionalized, and matches any regionalized cartridge
- a 0 z—Region 0: The cartridge is not regionalized, and only matches with machine region 0
- 11 z—Region 1: North America
- 2 2 z—Region 2: Europe Economic Area + Extras
- 3 3 z—Region 3: Asia Pacific Group
- 4 4 z—Region 4: Latin America
- 5 5 z—Region 5: Rest Of Europe, Middle East, and Africa
- 6 6 z—Region 6: Australia and New Zealand

Region mismatch service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Check the region number of the toner cartridge and the printer. | Contact the next level of support. | Go to step 2. |
| Do the numbers match? | | |
| Step 2 Install the appropriate toner cartridge. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

43 user attendance errors

43 user attendance error messages

| Error code | Description | Action |
|------------|--|---|
| 43.40z | Black toner cartridge toner meter cycle error. | See "TMC card service check" on page 103. |
| 43.41z | Cyan toner cartridge toner meter cycle error. | |
| 43.42z | Magenta toner cartridge toner meter cycle error. | |
| 43.43z | Yellow toner cartridge toner meter cycle error. | |

The following are the meaning of the yz codes:

- y—Recoverable first error
- z—Non-recoverable second error

TMC card service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | Go to step 3. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| b Find the sensor (Toner meter). | | |
| Does the sensor status change while toggling the sensor? | | |
| Step 2 | Go to step 3. | The problem is |
| Replace the toner cartridge. | | solved. |
| Does the problem remain? | | |
| Step 3 | Contact the next | The problem is |
| Replace the TMC card. See <u>"TMC card removal" on page 261</u> . | level of support. | solved. |
| Does the problem remain? | | |

80 user attendance errors

80 user attendance error messages

| Error code | Description | Action |
|------------|---|---|
| 80.1 | The maintenance kit is low. | See <u>"Maintenance kit service check" on</u> |
| 80.2 | The maintenance kit is very low. | <u>page 104</u> . |
| 80.3 | Replace the maintenance kit. Zero estimated | |
| 80.4 | pages remain. | |

Maintenance kit service check

| Action | Yes | No |
|---|------------------------------------|------------------------|
| 4 | Contact the next level of support. | The problem is solved. |
| a Replace the required maintenance kit. | | |
| b Reset the maintenance counter. | | |
| Does the problem remain? | | |

82 user attendance errors

82 user attendance error messages

| Error code | Description | Action |
|------------|--|---|
| 82.11 | The waste toner bottle is nearly full. The sensor threshold has been reached. | See "Waste toner bottle service check" on page 105. |
| 82.19 | The waste toner bottle is nearly full. The user-selected EWS set point has been reached. | |
| 82.31 | Replace the waste toner bottle. The sensor end of life threshold has been reached. | |

Waste toner bottle service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Reseat the waste toner bottle. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Make sure that the printer is placed on a hard and flat surface. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Make sure that the waste toner bottle contacts and waste toner bottle contact block contacts are free from dust or debris. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the waste toner bottle contact block for proper connection and damage. | Contact the next level of support. | Go to step 5. |
| Is the waste toner bottle contact block properly connected and free of damage? | | |
| Step 5 Replace the waste toner bottle contact block. See "Waste toner bottle contact block removal" on page 281. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

84 user attendance errors

84 user attendance error messages

| Error code | Description | Action |
|------------|--|---|
| 84.11 | The imaging kit is low. | See "Toner cartridge or photoconductor unit |
| 84.13 | | service check" on page 107. |
| 84.19 | | |
| 84.21 | The imaging kit is very low. | |
| 84.29 | | |
| 84.31 | Replace the imaging kit. Zero estimated pages remain. | |
| 84.41 | Replace the imaging kit. Zero estimated pages remain. Absolute end of life has been reached due to the PC rev counter. | |
| 84.43 | Replace the imaging kit. Zero estimated pages remain. Absolute end of life has been reached due to page count. | |
| 84.48 | Replace the imaging kit. Zero estimated pages remain. Absolute end of life has been reached due to exhausted Quanta. | |

88 user attendance errors

88 user attendance error messages

| Error code | Description | Action |
|------------|---|--|
| 88.00 | The toner cartridge is nearly low. | See <u>"Toner cartridge or photoconductor unit</u> |
| 88.10 | The toner cartridge is low. | service check" on page 107. |
| 88.19 | | |
| 88.20 | The toner cartridge is very low. | |
| 88.30 | Replace the toner cartridge. Zero estimated | |
| 88.40 | pages remain. | |
| 88.48 | | |

Toner cartridge or photoconductor unit service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| a Make sure that the toner cartridge or photoconductor unit is installed. b Check if the toner cartridge or photoconductor unit is supported, and replace if necessary. Does the problem remain? | Go to step 2. | The problem is solved. |
| Step 2 a Make sure that the toner cartridge or photoconductor unit is properly installed. b Make sure that the toner cartridge or photoconductor unit cables are properly connected. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| a Check the toner cartridge or photoconductor unit contacts for damage, and replace if necessary. b Replace the imaging kit if necessary. See "Imaging kit removal" on page 276. Note: See "Supplies used to resolve print quality issues" on page 32 to determine which imaging kit to use. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the controller board pins for damage. | Contact the next level of support. | Go to step 5. |
| Are the controller board pins free of damage? | | |
| Step 5 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Non-supply user attendance errors

Non-supply user attendance error messages

| Error code | Description | Action |
|------------|----------------------------|--|
| 35 | Insufficient memory. | See "Insufficient memory service check" on page 108. |
| 36 | The resolution is reduced. | N/A |

| Error code | Description | Action |
|------------|--|--|
| 37 | No memory for collation, defrag, or held jobs. | See "Insufficient memory service check" on page 108. |
| 38 | The memory is full. | See "Insufficient memory service check" on page 108. |
| 39 | Complex page. | See "Complex page service check" on page 109. |
| 51 | The flash memory is defective. | See "Flash memory failure service check" on page 110. |
| 52 | The flash memory is full. | See "Insufficient flash memory service check" on page 110. |
| 53 | Unformatted flash memory. | See "Flash memory failure service check" on page 110. |
| 54 | Serial port or network error. | See "Flash memory failure service check" on page 110. |
| 55 | The option is not supported. | See "Unsupported internal option service check" on page 111 |
| 56 | The parallel, serial, or USB port is disabled. | See "Disabled port service check" on page 111. |
| 57 | The configuration changed, and all held jobs are lost. | N/A |
| 58 | There are too many input options or trays. | See "Excess options service check" on page 112. |
| 58.xx | The optional tray is defective or incorrectly installed. | See "Invalid input option type or ID is detected service check" on page 162. |
| 59 | The option or tray incompatible. | See "Incompatible hardware option service check" on page 113. |
| 61 | The hard disk is defective. | See "Hard disk failure service check" on |
| 62 | The hard disk is full. | <u>page 114</u> . |
| 63 | The hard disk is not formatted. | Format the hard disk. |
| 64 | The hard disk format is not supported. | |

Insufficient memory service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Perform a POR. | Go to step 2. | The problem is solved. |
| b From the home screen, navigate to Settings > Print > Setup > Download Target > Disk . | | |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 2 If applicable, install an extra memory card. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Check the controller board pins for damage. | Contact the next level of support. | Go to step 4. |
| Are the pins free of damage? | | |
| Step 4 Replace the controller board. See <u>"Controller board removal" on page 345</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Complex page service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Perform a POR. | | solved. |
| b From the home screen, navigate to Settings > Print > Setup > Download Target > Disk . | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | The problem is |
| Enter the Diagnostics menu, and then navigate to: | | solved. |
| Input tray quick print > Tray 1 > Single | | |
| | | |
| Does the problem remain? | | |
| Step 3 | Contact the next | Go to step 4. |
| Check the controller board pins for damage. | level of support. | |
| | | |
| Are the pins free of damage? | | |
| Step 4 | Contact the next | The problem is |
| Replace the controller board. See "Controller board removal" on | level of support. | solved. |
| <u>page 345</u> . | | |
| Does the problem remain? | | |
| Does the problem remain: | | |

Flash memory failure service check

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 1 a From the home screen, navigate to Settings > Print > Job Accounting > Log Near Full Level. b Make sure that the value is set to the maximum. | Go to step 2. | The problem is solved. |
| Does the problem remain? Step 2 Check the controller board pins for damage. Are the pins free of damage? | Go to step 4. | Go to step 3. |
| Step 3 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 Make sure that the printer is using the latest firmware version, and update if necessary. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Insufficient flash memory service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 From the home screen, navigate to Settings > USB Drive > Flash Drive Scan > Format Flash. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 a From the home screen, navigate to Settings > Print > Job Accounting > Log Near Full Level. b Make sure that the value is set to the maximum. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 Check the controller board pins for damage. Are the pins free of damage? | Go to step 5. | Go to step 4. |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 4 Replace the controller board. See "Controller board removal" on page 345. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Make sure that the printer is using the latest firmware version, and update if necessary. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Unsupported internal option service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| If applicable, make sure that the option cards are supported. | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 4. | Go to step 3. |
| Check the controller board pins for damage. | | |
| Are the pins free of damage? | | |
| Step 3 | Go to step 4. | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | | solved. |
| Does the problem remain? | | |
| Step 4 | Contact the next | The problem is |
| Make sure that the printer is using the latest firmware version, and update if necessary. | level of support. | solved. |
| Does the problem remain? | | |

Disabled port service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 a Make sure that the cables connected to the ports are properly installed. b Check the cables for damage, and replace if necessary. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 2 Enter the Network/Ports menu and make sure that the applicable port settings are enabled. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 If applicable, make sure that the option card is supported. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the controller board pins for damage. Are the pins free of damage? | Go to step 6. | Go to step 5. |
| Step 5 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 Make sure that the printer is using the latest firmware version, and update if necessary. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Excess options service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 Perform a POR, and then resend the print job. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 If applicable, make sure that the internal option is supported. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 a If applicable, remove all internal options. b Perform a POR, and then resend the print job. | Go to step 6. | Go to step 4. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 4 Check if the number of internal options installed is allowed, and then remove the excess option. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 Check the number of input options allowed, and then remove the excess input options. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Check the controller board pins for damage. Are the pins free of damage? | Contact the next level of support. | Go to step 7. |
| Step 7 Replace the controller board. See <u>"Controller board removal" on page 345</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Incompatible hardware option service check

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 1 a Reseat the hardware option cables. | Go to step 2. | The problem is solved. |
| b Check the cables for damage, and replace if necessary. Does the problem remain? | | |
| Step 2 | Go to step 3. | The problem is |
| Check if the firmware version of the hardware option is supported by the engine firmware, and update the firmware if necessary. | | solved. |
| Note: Contact the next level of support for the correct firmware version. | | |
| Does the problem remain? | | |
| Step 3 Check the hardware option controller board pins for damage, and replace if necessary. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Hard disk failure service check

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 1 Delete unnecessary files. • From the home screen, navigate to Settings > Device > Maintenance > Out-of-Service Erase > Erase Hard Disk > Sanitize all information on hard disk > Erase downloads > Delete now. • From the home screen, navigate to Settings > Maintenance > Configuration Menu > Disk Configuration > Jobs on Disk > Delete. | Go to step 2. | The problem is solved. |
| Does the problem remain? Step 2 Make sure that the printer is using the latest firmware version. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 a Make sure that the hard disk cable is properly installed. b Check the cable for damage, and replace if necessary. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 a Make sure that the hard disk is properly installed. b Check the hard disk for damage, and replace if necessary. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 Check the controller board pins for damage. Are the pins free of damage? | Contact the next level of support. | Go to step 6. |
| Step 6 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Printer hardware errors

100 errors

| Error code | Description | Action |
|------------|---|---|
| 100.01 | The weather station data is invalid. | See "Weather station service check" on page 169. |
| 100.04D | The printhead temperature is below the range. | See "Printhead service check" on page 116. |
| 100.25 | The cavity thermistor on the sensor (toner patch) is out of range. | See "Toner patch sensing service check" on page 67. |
| | The cavity and toner patch sensor thermistor reading is out of range. | |

110 error messages

| Error code | Description | Action |
|------------|---|--|
| Error code | Description | Action |
| 110.20 | The printhead error was detected before the motor was turned on. | See <u>"Printhead service check" on page 116</u> . |
| 110.21 | The printhead power was off when the laser servo started. | |
| 110.31 | The printhead error (no first Hysnc) was detected. | |
| 110.32 | The printhead error (lost first Hysnc) was detected. | |
| 110.33 | The printhead error (lost first Hysnc) was detected during servo. | |
| 110.34 | The printhead error (mirror motor lost lock) was detected. | |
| 110.35 | The printhead error (mirror motor no first lock) was detected. | |
| 110.36 | The printhead error (mirror motor never stabilized) was detected. | |
| 110.41 | The printhead NVRAM read failure occurred. | |
| 110.70 | The printhead NVRAM values were incorrect. | |
| 110.71 | The printhead timing measurement error was detected. | |
| 110.90 | The video cable was unplugged. | |
| 110.91 | The printhead timing reading error was detected. | |
| 110.92 | The printhead NVRAM checksum mismatch occurred. | |

Printhead service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the cables on the printhead and on the JMIRR1 and JPH1 connectors on the controller board for proper connection. | Go to step 4. | Go to step 3. |
| Are the cables properly connected? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 3 | Go to step 4. | The problem is |
| Reconnect the cables. | | solved. |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Check the printhead cable for damage, and replace if necessary. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Replace the printhead. See <u>"Printhead removal" on page 352</u> . | | solved. |
| Does the problem remain? | | |
| Step 6 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

| Error code | Description | Action |
|------------|---|---|
| 120.80 | The motor (fuser) does not turn on. | See <u>"Motor (fuser) service check" on</u> |
| 120.81 | The motor (fuser) does not turn off. | <u>page 118</u> . |
| 120.82 | The motor (fuser) failed to achieve the expected speed. | |
| 120.83 | The motor (fuser) stalled. | |
| 120.84 | The motor (fuser) is over speeding. | |
| 120.85 | The motor (fuser) is under speeding. | |
| 120.86 | The motor (fuser) moved too long. | |

Motor (fuser) service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Perform a POR. | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check the fuser for damage or life expiration, and replace if necessary. See <u>"Fuser removal" on page 311</u> . | | |
| Does the problem remain? | | |
| Step 3 | Go to step 5. | Go to step 4. |
| Check the cable at the JFUSES2 connector on the controller board for proper connection. | | |
| Is the cable properly connected? | | |
| Step 4 | Go to step 5. | The problem is |
| Reconnect the cable. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Check the cable for damage, and replace if necessary. | | solved. |
| Does the problem remain? | | |
| Step 6 | Contact the next | The problem is |
| Replace the motor (fuser drive). See "Motor (fuser drive) removal" on page 260. | level of support. | solved. |
| Does the problem remain? | | |

| Error code | Description | Action |
|------------|---|--|
| 121.00 | The fuser failed to reach temperature during warm-up. | See <u>"Fuser service check" on page 123</u> . |
| 121.01 | Attempting to heat the fuser, but the fuser is not installed. | |
| 121.02 | Attempting to power up the fuser while it is too warm (belt: 50°C, lamp: 76°C) to execute EWC/line voltage detection after a Wrong Fuser Installed error had been previously declared. | |
| 121.03 | Fuser hardware and driver mismatch. | |
| 121.04 | Attempting to heat the fuser but the fuser relay is open, and the fuser PIC micro controller is not reporting an error or is not responding. | |
| 121.05 | Attempting to heat the fuser but the fuser relay is open, and the fuser PIC micro controller is reporting an error condition. | |
| 121.06 | The fuser has been too cold for too long while it is powered at 100%. | |
| 121.07 | The fuser is on for more than the allowed time after a gap blowout, and the temperature is still too cold. | |
| 121.08 | The fuser is too cold while paper is in the fuser. | |
| 121.09 | The fuser fell below the minimum required temperature for motors. | |
| 121.10 | The fuser did not warm up enough to start EWC/line voltage detection (belt: 60°C, lamp: 88°C) within time-out (belt: 10 seconds, lamp: 90 seconds). | |
| 121.11 | The fuser took too long to reach the final EWC/line detection temperature (belt: 90°C, lamp: 149°C). | |
| 121.12 | The fuser never reached final EWC/line detection temperature (belt: 90°C, lamp: 149°C). | |
| 121.13 | The fuser heated too fast to the final EWC/line detection temperature (belt: 90°C, lamp: 149°C). | |
| 121.15 | The heater power is too high. | |

| Error code | Description | Action |
|------------|---|-------------------------------------|
| 121.16 | The heater power is too low. | See <u>"Fuser service check" on</u> |
| 121.17 | A fuser heater runaway is detected on the LV machine. | <u>page 123</u> . |
| 121.18 | A fuser heater runaway is detected on the HV machine. | |
| 121.19 | The fuser high power trace heated to the final EWC/line detection temperature too fast. | |
| 121.20 | The fuser high power trace heating rate from 165°C to 180°C exceeded the error threshold. | |
| 121.20 | The fuser is too cold during steady state control. | |
| | Note: This event can occur during printing or standby modes. | |
| 121.21 | The fuser low power trace heating rate from 165°C to 180°C exceeded the error threshold. | |
| 121.22 | Open fuser relay detected. | |
| 121.23 | The fuser reached the final EWC/line detection temperature (belt: 90°C, lamp: 149°C). | |
| 121.24 | The fuser never reached the final EWC/line detection temperature (belt: 90°C, lamp: 149°C). | |
| 121.25 | After the line voltage detection, the controller did not roll over to the steady state control in time. | |
| 121.26 | The fuser failed to reach the temperature during warm-up. | |
| 121.28 | The fuser failed to reach the EP warm-up temperature in time. | |
| 121.30 | The fuser has been on for too long after a gap blowout, and the temperature is still too cold. | |
| 121.31 | The fuser is too hot. | |
| 121.32 | The fuser is too cold for too long while its power is at 100%. | |
| 121.33 | The fuser is too cold when the paper is in the fuser. | |

| Error code | Description | Action |
|------------|---|--|
| 121.34 | The fuser is too cold during steady state control when a paper is not in the fuser. Note: This event can occur during printing or standby modes. | See <u>"Fuser service check" on page 123</u> . |
| 121.35 | Attempting to power up with the fuser too warm (belt: 50°C, lamp: 76°C) to execute EWC/line voltage detection after a Wrong Fuser Installed error was previously declared. | |
| 121.36 | An open fuser relay was detected with very cold, or unknown ambient temperature. | |
| 121.37 | The fuser heated to the final EWC/line detection temperature (belt: 90°C, lamp: 149°C) too fast. | |
| 121.38 | Fuser UBER defect detection. Belt to heater temperature delta exceeded. | |
| 121.41 | Fuser mechanism did not detect the expected cam sensor signal. | |
| 121.42 | The fuser gate time is increasing out of control. | |
| 121.48 | Fuser hardware and driver mismatch. | |
| 121.50 | The fuser went over the required temperature during a global over temperature check. | |
| 121.51 | The fuser secondary heater is too hot. | |
| 121.52 | The main thermistor temperature is out of range. | |
| 121.53 | The main thermistor temperature change rate is out of range. | |
| 121.54 | The secondary thermistor temperature is out of range. | |
| 121.55 | The secondary thermistor temperature change rate is out of range. | |
| 121.56 | The middle thermistor temperature is out of range. | |

| Error code | Description | Action |
|------------|--|--|
| 121.57 | The middle thermistor temperature change rate is out of range. | See "Fuser service check" on page 123. |
| 121.58 | The edge thermistor temperature is out of range. | |
| 121.59 | The edge thermistor temperature change rate is out of range. | |
| 121.60 | The belt contact thermistor temperature is out of range. | |
| 121.61 | The belt contact thermistor temperature change rate is out of range. | |
| 121.62 | The belt non contact thermistor temperature is out of range. | |
| 121.63 | The belt non contact thermistor temperature change rate is out of range. | |
| 121.64 | The belt non contact 2 thermistor temperature is out of range. | |
| 121.65 | The belt non contact 2 thermistor temperature change rate is out of range. | |
| 121.66 | The narrow media thermistor temperature is out of range. | |
| 121.67 | The narrow media thermistor temperature change rate is out of range. | |
| 121.70 | The calculated heater resistance is too high. | |
| 121.71 | Open fuser main heater thermistor. | |
| 121.72 | Open fuser secondary heater thermistor. | |
| 121.73 | Open fuser middle heater thermistor. | |
| 121.74 | Open fuser edge thermistor. | |
| 121.76 | Open contact belt thermistor. | |

Fuser service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Some of these errors are caused by a faulty component on the LVPS. Check the history file in the printer to verify other occurrences. If there are other occurrences, then replace the LVPS. See "LVPS removal" on page 250. Does the problem remain? | Go to step 2. | The problem is solved. |
| Step 2 a Turn off the printer. b Remove the rear cover. See "Rear cover removal" on page 343. c Check the cable on the JFUSES2 connector on the controller board for proper connection and damage, and replace if necessary. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 Check the cable on the JLVPS1 connector on the controller board for proper connection and damage, and replace if necessary. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 a Open the front door. b Remove the right cover. See "Right cover removal" on page 257. c Check the power cable and the thermistor cables for proper connection and damage. Are the cables properly connected and free of damage? | Go to step 6. | Go to step 5. |
| Step 5 Replace the damaged cables. Note: If the cables cannot be replaced, then replace the fuser. See "Fuser removal" on page 311. Does the problem remain? | Go to step 6. | The problem is solved. |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 6 | Go to step 7. | Go to step 8. |
| Check the following voltage values on the JFUSES2 connector pins on the controller board: | | |
| Pin 1: +24 V dc (door closed) | | |
| Pin 2: +24 V dc (doors closed) | | |
| Pin 3: +24 V dc (doors closed) | | |
| Pin 4: +24 V dc (doors closed) | | |
| Pin 5: Between 0.6 and 3.28 V dc | | |
| Pin 6: Ground | | |
| Pin 8: Ground | | |
| • Pin 10: Between -3 and +3.3 V dc | | |
| Pin 11: Ground (no wire) | | |
| Are the voltage values approximately the same? | | |
| Step 7 | Contact the next | The problem is |
| Replace the fuser. See <u>"Fuser removal" on page 311</u> . | level of support. | solved. |
| Does the problem remain? | | |
| Step 8 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

| Error code | Description | Action |
|------------|--|------------------------------------|
| 126.05 | The LVPS dropped while not sleeping. | See <u>"LVPS service check" on</u> |
| 126.06 | An LVPS 25 V line error was detected. | <u>page 125</u> . |
| 126.07 | An LVPS 5 V rail was down during POR. | |
| 126.10 | No line frequency was detected. | |
| 126.11 | Line frequency has gone outside the operating range. | |

LVPS service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Perform a POR. | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | The problem is |
| Check the cable on the JLVPS1 connector on the controller board | | solved. |
| for proper connection and damage, and replace if necessary. | | |
| Does the problem remain? | | |
| Step 3 | Go to step 4. | The problem is |
| Replace the LVPS. See <u>"LVPS removal" on page 250</u> . | | solved. |
| Does the problem remain? | | |
| Step 4 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

142 errors

| Error code | Description | Action |
|------------|---|--------------------------------------|
| 142.80 | The motor (CMY) does not turn on. | See "Motor (EP drive) service check" |
| 142.81 | The motor (CMY) does not turn off. | on page 126. |
| 142.82 | The motor (CMY) failed to achieve the expected speed. | |
| 142.83 | The motor (CMY) stalled. | |
| 142.84 | The motor (CMY) is running too slow. | |
| 142.85 | The motor (CMY) is running too fast. | |
| 142.86 | The motor (CMY) moved too long. | |

Motor (EP drive) service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| a Remove the imaging kit. See "Imaging kit removal" on page 276. b Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Motor tests > CMY developer c Press OK or touch Start. Does the motor run? | Go to step 3. | Go to step 7. |
| Step 3 a Remove the imaging kit. See "Imaging kit removal" on page 276. b Remove the transfer module. See "Transfer module removal" on page 272. c Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Motor tests > K/ITM developer d Press OK or touch Start. Does the motor run? | Go to step 4. | Go to step 7. |
| Step 4 Manually turn the black developer unit and transfer module drive gears. Do the gears freely turn? | Go to step 6. | Go to step 5. |
| Step 5 Replace the EP drive. See "EP drive assembly removal" on page 247. Does the problem remain? | Go to step 6. | The problem is solved. |
| Step 6 Check the imaging kit and transfer module for damage or life expiration, and replace if necessary. See "Imaging kit removal" on page 276 and "Transfer module removal" on page 272. Does the problem remain? | Contact the next level of support. | The problem is solved. |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| a Make sure that the cable on the motor (EP drive) is properly connected. b Make sure that the cables on the JCARTP1 and JCARTS1 connectors on the controller board are properly connected. | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |
| Step 8 Check the cables for damage and replace if necessary. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 Replace the motor (drive unit). See "Motor (drive unit) removal" on page 247. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

| Error code | Description | Action |
|------------|---|--------------------------------------|
| 151.80 | The motor (K/ITM) does not turn on. | See "Motor (EP drive) service check" |
| 151.81 | The motor (K/ITM) does not turn off. | <u>on page 126</u> . |
| 151.82 | The motor (K/ITM) failed to achieve the expected speed. | |
| 151.83 | The motor (K/ITM) stalled. | |
| 151.84 | The motor (K/ITM) is running too slow. | |
| 151.85 | The motor (K/ITM) is running too fast. | |
| 151.86 | The motor (K/ITM) moved too long. | |

160 error messages

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 160.80 | The motor (MPF) does not turn on. | See "Option tray motor service check" |
| 160.81 | The motor (MPF) does not turn off. | on page 128. |
| 160.82 | The motor (MPF) failed to achieve the expected speed. | |
| 160.83 | The motor (MPF) stalled. | |
| 160.84 | The motor (MPF) is running too slow. | |
| 160.85 | The motor (MPF) is running too fast. | |
| 160.86 | The motor (MPF) moved too long. | |

Option tray motor service check

| Action | | Yes | No |
|---|--|---------------|----------------|
| Step 1 | | Go to step 2. | Go to step 3. |
| a Enter the Diagnostics menu, and then | navigate to: | | |
| Additional input tray diagnostics > Mo | otor Tests | | |
| b Select Pick (tray x) motor test , and the Start . | en press OK or touch | | |
| Note: Make sure to perform the motor | test in both directions. | | |
| c Select Pass-through (tray x) motor test touch Start. | t , and then press OK or | | |
| Note: Make sure to perform the motor | test in both directions. | | |
| Did the motors run? | | | |
| Step 2 | | Go to step 3. | The problem is |
| Perform a print test. | | | solved. |
| Does the problem remain? | | | |
| Step 3 | | Go to step 4. | The problem is |
| Make sure that the option connector in the subframe is properly connected to the tray 2 option. | | | solved. |
| Does the problem remain? | | | |
| Step 4 | | Go to step 5. | The problem is |
| Make sure that cable on the JOPT1 connector on the controller board is properly connected. | | | solved. |
| Does the problem remain? | | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 5 Check the option cable for continuity, and replace if necessary. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Check the option tray connections for damage, and replace the affected tray if necessary. | Contact the next level or support. | The problem is solved. |
| Does the problem remain? | | |

| Error code | Description | Action |
|------------|---|---|
| 161.80 | The motor (tray 1 pick) does not turn on. | See "Motor (tray 1 pick/duplex) service |
| 161.81 | The motor (tray 1 pick) does not turn off. | check" on page 130. |
| 161.82 | The motor (tray 1 pick) failed to achieve the expected speed. | |
| 161.83 | The motor (tray 1 pick) stalled. | |
| 161.84 | The motor (tray 1 pick) is running too slow. | |
| 161.85 | The motor (tray 1 pick) is running too fast. | |
| 161.86 | The motor (tray 1 pick) moved too long. | |

Motor (tray 1 pick/duplex) service check

| Action | Yes | No |
|---|-----------------------------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 a Remove tray 1. b Enter the Diagnostics menu, and then navigate to: | Go to step 3. | Go to step 4. |
| Printer diagnostics & adjustments > Motor tests > Pick (tray 1) / Duplex | | |
| c Select Tray 1 Picking, and then press OK or touch Start. Note: Make sure to perform the motor test in both directions. d Select Tray 1 Duplex, and then press OK or touch Start. Note: Make sure to perform the motor test in both directions. | | |
| Did the motors run? | | |
| Step 3 Make sure that cable on the JSP1 connector on the controller board is properly connected. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the cable for damage. | Go to step 5. | Go to step 6. |
| Is the cable damaged? | | |
| Step 5 Replace the media feeder. See <u>"Tray 1 media feeder removal" on page 339</u> . | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Replace the controller board. See <u>"Controller board removal" on page 345</u> . | Contact the next level of support | The problem is solved. |
| Does the problem remain? | | |

162 error messages

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 162.70 | The motor (tray 2 pick) does not turn on. | See "Option tray motor service check" |
| 162.71 | The motor (tray 2 pick) does not turn off. | <u>on page 128</u> . |
| 162.72 | The motor (tray 2 pick) failed to achieve the expected speed. | |
| 162.73 | The motor (tray 2 pick) stalled. | |
| 162.74 | The motor (tray 2 pick) is running too slow. | |
| 162.75 | The motor (tray 2 pick) is running too fast. | |
| 162.76 | The motor (tray 2 pick) moved too long. | |

163 errors

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 163.70 | The motor (tray 3 pick) does not turn on. | See "Option tray motor service check" |
| 163.71 | The motor (tray 3 pick) does not turn off. | <u>on page 128</u> . |
| 163.72 | The motor (tray 3 pick) failed to achieve the expected speed. | |
| 163.73 | The motor (tray 3 pick) stalled. | |
| 163.74 | The motor (tray 3 pick) is running too slow. | |
| 163.75 | The motor (tray 3 pick) is running too fast. | |
| 163.76 | The motor (tray 3 pick) moved too long. | |

166 error messages

| Error code | Description | Action |
|------------|--|--|
| 166.70 | The motor (tray 2 transport) does not turn on. | See <u>"Option tray motor service check"</u> |
| 166.71 | The motor (tray 2 transport) does not turn off. | <u>on page 128</u> . |
| 166.72 | The motor (tray 2 transport) failed to achieve the expected speed. | |
| 166.73 | The motor (tray 2 transport) stalled. | |
| 166.74 | The motor (tray 2 transport) is running too slow. | |
| 166.75 | The motor (tray 2 transport) is running too fast. | |
| 166.76 | The motor (tray 2 transport) moved too long. | |

167 errors

167 error messages

| Error code | Description | Action |
|------------|--|--------------|
| 167.70 | The motor (tray 3 transport) does not turn on. | 1 |
| 167.71 | The motor (tray 3 transport) does not turn off. | on page 128. |
| 167.72 | The motor (tray 3 transport) failed to achieve the expected speed. | |
| 167.73 | The motor (tray 3 transport) stalled. | |
| 167.74 | The motor (tray 3 transport) is running too slow. | |
| 167.75 | The motor (tray 3 transport) is running too fast. | |
| 167.76 | The motor (tray 3 transport) moved too long. | |

171 errors

| Error code | Description | Action |
|------------|-----------------|--|
| 171.82 | Main fan error. | See <u>"Main fan service check" on</u> |
| 171.83 | | <u>page 133</u> . |
| 171.84 | | |
| 171.85 | | |

Main fan service check

| Action | Yes | No |
|---|-------------------|----------------|
| Step 1 | Go to step 3. | Go to step 2. |
| Check the main fan area for obstructions. | | |
| Is the fan area free from obstructions? | | |
| Step 2 | Go to step 3. | The problem is |
| Remove the obstructions. | | solved. |
| Does the problem remain? | | |
| Step 3 | Go to step 5. | Go to step 4. |
| Check the cable on the JFAN2 connector on the controller board | | |
| for proper connection. | | |
| Is the cable properly connected? | | |
| Step 4 | Go to step 5. | The problem is |
| Reconnect the cable. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Replace the main fan. See <u>"System fan removal" on page 342</u> . | | solved. |
| Does the problem remain? | | |
| Step 6 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| | | |
| Does the problem remain? | | |

600 errors

| Error code | Description | Action |
|------------|---|----------------|
| 600.95 | The printer intentionally declared a jam. | Perform a POR. |
| | Note: This event is typically used to prevent a kiosk user from printing free pages. | |

602 error messages

| Error code | Description | Action |
|------------|---|---|
| 602.x8 | The tray $[x]$ timed out while waiting for the ILN command. | See <u>"Engine error service check" on page 134</u> . |
| 602.x9 | The tray [x] failed to become the input source. | |

x = tray number

Engine error service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 a Remove the rear cover. See <u>"Rear cover removal" on page 343</u>. b Reseat all the cables on the controller board. c Check the controller board contacts and pins for damage. Is the controller board free of damage? | Contact the next level of support. | Go to step 3. |
| Step 3 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

620 error messages

| Error code | Description | Action |
|------------|---|---|
| 620.80 | The motor (fuser) does not turn on. | See "Motor (fuser) service check" on |
| 620.81 | The motor (fuser) does not turn off. | <u>page 118</u> . |
| 620.82 | The motor (fuser) failed to achieve the expected speed. | |
| 620.83 | The motor (fuser) stalled. | |
| 620.84 | The motor (fuser) is running too slow. | |
| 620.85 | The motor (fuser) is running too fast. | |
| 620.86 | The motor (fuser) moved too long. | |
| 621.01 | The fuser heater was too cold when the paper entered the fuser nip. | See <u>"Fuser service check" on page</u> <u>123</u> . |

642 errors

| Error code | Description | Action |
|------------|---|--------------------------------------|
| 642.80 | The motor (CMY) does not turn on. | See "Motor (EP drive) service check" |
| 642.81 | The motor (CMY) does not turn off. | <u>on page 126</u> . |
| 642.82 | The motor (CMY) failed to achieve the expected speed. | |
| 642.83 | The motor (CMY) stalled. | |
| 642.84 | The motor (CMY) is running too slow. | |
| 642.85 | The motor (CMY) is running too fast. | |
| 642.86 | The motor (CMY) moved too long. | |

651 error messages

| Error code | Description | Action |
|------------|---|--------------------------------------|
| 651.80 | The motor (K/ITM) does not turn on. | See "Motor (EP drive) service check" |
| 651.81 | The motor (K/ITM) does not turn off. | on page 126. |
| 651.82 | The motor (K/ITM) failed to achieve the expected speed. | |
| 651.83 | The motor (K/ITM) stalled. | |
| 651.84 | The motor (K/ITM) is running too slow. | |
| 651.85 | The motor (K/ITM) is running too fast. | |
| 651.86 | The motor (K/ITM) moved too long. | |

661 errors

| Error code | Description | Action |
|------------|---|---|
| 661.80 | The motor (tray 1 pick) does not turn on. | See "Motor (tray 1 pick/duplex) service |
| 661.81 | The motor (tray 1 pick) does not turn off. | check" on page 130. |
| 661.82 | The motor (tray 1 pick) failed to achieve the expected speed. | |
| 661.83 | The motor (tray 1 pick) stalled. | |
| 661.84 | The motor (tray 1 pick) is running too slow. | |
| 661.85 | The motor (tray 1 pick) is running too fast. | |
| 661.86 | The motor (tray 1 pick) moved too long. | |

662 error messages

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 662.70 | The motor (tray 2 pick) does not turn on. | See "Option tray motor service check" |
| 662.71 | The motor (tray 2 pick) does not turn off. | on page 128. |
| 662.72 | The motor (tray 2 pick) failed to achieve the expected speed. | |
| 662.73 | The motor (tray 2 pick) stalled. | |
| 662.74 | The motor (tray 2 pick) is running too slow. | |
| 662.75 | The motor (tray 2 pick) is running too fast. | |
| 662.76 | The motor (tray 2 pick) moved too long. | |

663 errors

| Error code | Description | Action |
|------------|---|---------------------------------------|
| 663.70 | The motor (tray 3 pick) does not turn on. | See "Option tray motor service check" |
| 663.71 | The motor (tray 3 pick) does not turn off. | <u>on page 128</u> . |
| 663.72 | The motor (tray 3 pick) failed to achieve the expected speed. | |
| 663.73 | The motor (tray 3 pick) stalled. | |
| 663.74 | The motor (tray 3 pick) is running too slow. | |
| 663.75 | The motor (tray 3 pick) is running too fast. | |
| 663.76 | The motor (tray 3 pick) moved too long. | |

666 error messages

| Error code | Description | Action |
|------------|--|---------------------------------------|
| 666.70 | The motor (tray 2 transport) does not turn on. | See "Option tray motor service check" |
| 666.71 | The motor (tray 2 transport) does not turn off. | on page 128. |
| 666.72 | The motor (tray 2 transport) failed to achieve the expected speed. | |
| 666.73 | The motor (tray 2 transport) stalled. | |
| 666.74 | The motor (tray 2 transport) is running too slow. | |
| 666.75 | The motor (tray 2 transport) is running too fast. | |
| 666.76 | The motor (tray 2 transport) moved too long. | |

667 errors

667 error messages

| Error code | Description | Action |
|------------|--|--------------|
| 667.70 | The motor (tray 3 transport) does not turn on. | - |
| 667.71 | The motor (tray 3 transport) does not turn off. | on page 128. |
| 667.72 | The motor (tray 3 transport) failed to achieve the expected speed. | |
| 667.73 | The motor (tray 3 transport) stalled. | |
| 667.74 | The motor (tray 3 transport) is running too slow. | |
| 667.75 | The motor (tray 3 transport) is running too fast. | |
| 667.76 | The motor (tray 3 transport) moved too long. | |

Procedure before starting the 9yy service checks

Retrieve certain information that helps your next level of support in diagnosing the problem before replacing the controller board.

Warning—Potential Damage: Do not replace the controller board unless instructed by your next level of support.

- **1** Collect the history information and firmware logs (Fwdebug and logs.tar.gz) from the SE menu.
- **2** Collect the settings from the Menu Settings Page.
- 3 Collect information from the user.

Note: Not all of the items are retrievable from the printer that you are working on.

A. Collecting the history information from the SE menu

Note: Make sure that your printer is connected to a network or to a print server.

1 Open a web browser, type http://printer_IP_address/se, and then press Enter.

Notes:

- printer_IP_address is the TCP/IP address of the printer.
- **se** is required to access the printer diagnostic information.
- 2 Click History Information, copy all information, and then save it as a text file.
- **3** E-mail the text file to your next level of support.

B. Collecting the firmware logs (Fwdebug and logs.tar.gz) from the SE menu

Notes:

- Make sure that your printer is connected to a network or to a print server.
- Some printers are designed to restart automatically after a 9yy error. On these printers, you can retrieve the secondary crash code information using the SE menu.
- 1 Open a web browser, type http://printer_IP_address/se, and then press Enter.
- 2 Click Logs Gzip Compressed.

Note: A logs.tar.gz file is saved to the Downloads folder. The file may take several minutes to save. You may rename the file if a logs.tar.gz already exists in the Downloads folder.

3 E-mail the logs to your next level of support.

Note: To download the FWdebug log to a flash drive, see "General SE" on page 213.

C. Collecting the settings from the Menu Settings Page

Note: The Menu Settings Page is different for each printer. For more information, see the *User's Guide*. Your next level of support will tell you which page they want to see.

Copying the Menu Settings Page from the Embedded Web Server (EWS)

Note: Make sure that your printer is connected to a network or to a print server.

- 1 Open a web browser, type http://printer IP_address, and then press Enter.
- 2 Click Settings, and then select one of the settings pages from the links shown on the page.
- **3** Copy all the information, and then save it as a text file.
- **4** E-mail the text file to your next level of support.

Printing the Menu Settings Page

1 From the home screen, navigate to:

Reports > Menu Settings Page

2 Print the Menu Settings Page, and then use Scan to E-mail to send it to your next level of support.

D. Collecting information from the user

Ask the user for information about the following:

- Print job being run
- Operating system being used
- Print driver being used
- Other information on what was happening when the 9yy error occurred

900 errors

900 error messages

| Error code | Description | Action |
|------------|-------------|--|
| 900.xx | | See <u>"System software error service check" on page 140</u> . |

System software error service check

Different types of 90y.xx errors can occur. There may be a communication problem (bad cable, network connection, and software issues), or a hardware problem with the controller board or ISP (internal solutions port). Check the communication and software problems first. Determine if the problem is constant or intermittent. Use the following troubleshooting procedure to isolate the issue. Take notes as instructed. You will need that information in the event that you need to contact your next level of support.

Before troubleshooting, do the following:

- 1 Perform the "Procedure before starting the 9yy service checks" on page 138.
- **2** Determine the operating system used when the error occurred. If possible, determine whether a PostScriptTM or PCLTM file was sent to the printer when the error occurred. Ask the customer which Lexmark Solutions applications are installed on the printer.

| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Perform a POR. | | solved. |
| Does the error remain? | | |
| Step 2 | Go to step 3. | Go to step 6. |
| a Write down the exact 900.xx error code that appears on the display. | | |
| b Turn off the printer. | | |
| c Clear the print queues. | | |
| d Disconnect all communication cables, and then remove all memory options. | | |
| e Remove any installed ISP. | | |
| f Reset the printer into the Diagnostics menu. | | |
| Does the problem remain? | | |

| Action | Yes | No |
|--|----------------|------------------------|
| Step 3 | Go to step 5. | Go to step 4. |
| Check all the cables on the controller board for proper connection. | C | |
| | | |
| Are the cables properly connected? | | |
| Step 4 | Go to step 5. | Go to step 6. |
| a Reconnect the cables. | | |
| b Reset the printer into the Diagnostics menu. | | |
| Does the problem remain? | | |
| | Co to stop 21 | The problem is |
| a Replace the controller board. See <u>"Controller board removal"</u> on page 345. | Go to step 31. | The problem is solved. |
| b Reset the printer. | | |
| Note: If a different error code displays, then go to the service check for that error code. | | |
| Does the problem remain? | | |
| Step 6 | Go to step 31. | Go to step 7. |
| Print the following: | | |
| Error Log | | |
| Menu Settings Page | | |
| Network Settings Page | | |
| Does the problem remain while printing these pages? | | |
| Step 7 | Go to step 8. | Go to step 10. |
| Note: Before performing this step, write down the following | Co to step c. | 00 to step 10. |
| information about the file being sent to the printer: | | |
| Application used | | |
| Operating system | | |
| Driver type | | |
| File type (PCL, PostScript, XPS, etc.) | | |
| a Reattach the communications cable. | | |
| b Reset the printer. | | |
| c Perform a print job. | | |
| Does the problem remain? | | |
| Step 8 | Go to step 9. | Go to step 10. |
| a Reset the printer. | | |
| b Perform a different print job. | | |
| Does the problem remain? | | |

| Action | Yes | No |
|--|----------------|----------------|
| Step 9 | Go to step 31. | Go to step 10. |
| a Upgrade the firmware. | | |
| Note: Contact your next level of support for the correct firmware level to use. | | |
| b Reset the printer. | | |
| c Perform a print job. | | |
| Does the problem remain? | | |
| Step 10 | Go to step 11. | Go to step 13. |
| Verify if the printer is an MFP. | | |
| Is the printer an MFP? | | |
| Step 11 | Go to step 31. | Go to step 12. |
| Perform a copy job. | | |
| Does the problem remain? | | |
| Step 12 | Go to step 31. | Go to step 13. |
| Scan a document to the computer. | | |
| Does the problem remain? | | |
| Step 13 | Go to step 14. | Go to step 16. |
| Verify if an optional memory is installed. | | |
| Is there an optional memory installed? | | |
| Step 14 | Go to step 15. | Go to step 16. |
| a Reinstall the memory. | | |
| b Perform a print job. | | |
| Does the problem remain? | | |
| Step 15 | Go to step 31. | The problem is |
| a Install a Lexmark-recommended memory option. | | solved. |
| b Perform a print job. | | |
| Does the problem remain? | | |
| Step 16 | Go to step 17. | Go to step 21. |
| Verify if a modem is installed. | | |
| Is a modem installed? | | |

| Action | Yes | No |
|--|----------------|----------------|
| Step 17 | Go to step 18. | Go to step 20. |
| a Reinstall the modem. | | |
| b Reset the printer. | | |
| Does the problem remain? | | |
| Step 18 | Go to step 19. | The problem is |
| a Upgrade the firmware if it was not upgraded in a previous step. | | solved. |
| Note: Contact your next level of support for the correct firmware level to use. | | |
| b Reset the printer. | | |
| c Perform a print job. | | |
| Does the problem remain? | | |
| Step 19 | Go to step 31. | The problem is |
| a Replace the modem. | | solved. |
| b Reset the printer. | | |
| Does the problem remain? | | |
| Step 20 | Go to step 31. | Go to step 21. |
| Perform a fax job. | | |
| Does the problem remain? | | |
| Step 21 | Go to step 22. | The problem is |
| Verify if an ISP option is installed. | | solved. |
| Is an ISP option installed? | | |
| Step 22 | Go to step 24. | Go to step 23. |
| a Reinstall the first ISP option. | | |
| b Reset the printer. | | |
| Does the problem remain? | | |
| Step 23 | Go to step 24. | Go to step 26. |
| Perform a job to test the option. | | |
| Does the problem remain? | | |

| Action | Yes | No |
|--|----------------|------------------------|
| Step 24 a Upgrade the firmware if it was not upgraded in a previous step. Note: Contact your next level of support for the correct firmware level to use. | Go to step 25. | The problem is solved. |
| b Reset the printer. | | |
| c Perform a print job. | | |
| Does the problem remain? | | |
| Step 25 a Replace the faulty ISP option. b Reset the printer. | Go to step 31. | Go to step 26. |
| Does the problem remain? | | |
| Step 26 Verify if there are more ISP options to install. | Go to step 27. | The problem is solved. |
| Are there more ISP options to install? | | |
| Step 27 a Install the next ISP option. b Reset the printer. | Go to step 29. | Go to step 28. |
| Does the problem remain? | | |
| Step 28 Perform a job to test the option. Does the problem remain? | Go to step 29. | Go to step 26. |
| Step 29 a Upgrade the firmware if it was not upgraded in a previous step. Note: Contact your next level of support for the correct firmware level to use. b Reset the printer. c Send a print job. Does the problem remain? | Go to step 30. | Go to step 26. |
| Step 30 | Go to step 31 | Go to step 26 |
| a Replace the faulty ISP option. b Reset the printer. Does the problem remain? | Go to step 31. | Go to step 26. |
| | | |

| Action | Yes | No |
|--|-----|----|
| Step 31 | | |
| Contact your next level of support. | | |
| Provide the following information: | | |
| Exact 90y.xx error digits and complete error message | | |
| Printed Menu Settings Page | | |
| Printed Network Settings Page | | |
| Device error log | | |
| • A sample print file if the error appears isolated to a single file | | |
| • File/Application used if the error is related to specific print file | | |
| Device operating system | | |
| Driver used (PCL/PS) | | |
| Frequency of the occurrence of the error | | |

91y errors

91y error messages

| Error code | Description | Action |
|------------|--------------------------------|---|
| 910.xx | General engine software error. | See <u>"91x.xx (910.xx-919.xx) Engine</u> |
| 911.xx | | software service check" on page 145. |
| 912.xx | | |
| 913.xx | General engine software error. | See "913.xx error code check" on page 146. |
| 914.xx | General engine software error. | See <u>"91x.xx (910.xx–919.xx) Engine</u> |
| 915.xx | | software service check" on page 145. |
| 916.xx | | |
| 917.xx | | |
| 918.xx | | |
| 919.xx | | |

91x.xx (910.xx-919.xx) Engine software service check

| Actions | Yes | No |
|---|---------------|---------------|
| Step 1 | Go to step 2. | Go to step 3. |
| a Remove the rear cover. See "Rear cover removal" on page 343. b Check the cables on the controller board for proper connection. | | |
| Are the cables properly connected? | | |

| Actions | Yes | No |
|--|------------------------------------|------------------------|
| Step 2 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Reconnect the cables, and then perform a POR. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

913.xx error code check

| Actions | Yes | No |
|--|-------------------|------------------------|
| Step 1 | Go to step 3. | Go to step 2. |
| a Turn off the printer, and then remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| b Make sure all cable connections on the controller board are secure. | | |
| Are all cable connections secure? | | |
| Step 2a Reconnect any loose cables.b Print multiple print tests. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 | Go to step 4. | The problem is |
| Replace the motor (fuser drive). See <u>"Motor (fuser drive) removal"</u> on page 260. | | solved. |
| Does the problem remain? | | |
| Step 4 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

938 errors

938 error messages

| Error code | Description | Action |
|------------|---|-----------------------------------|
| 938.01 | The board level was not obtained. | See "Controller board removal" on |
| 938.02 | Timed out while waiting for the bullet serial data to be updated. | <u>page 345</u> . |
| 938.03 | The NVM_OK was not received from the NV2 server for a successfully submitted request. | |
| 938.04 | An over temperature condition is detected. | |

95y errors

95y error messages

| Error code | Description | Action |
|------------|---|--|
| 950.xx | The controller EEPROM and mirror are mismatched. • 950.00 through 950.29 codes: mismatch between the controller and mirror | See <u>"950.xx NVRAM failure service check" on page 149</u> . |
| | 950.30 through 950.60 codes: mismatch between secure NVRAM and controller | |
| 951.xx | Error NV part on system board. | See "Controller board removal" on page 345. |
| 952.xx | A recoverable NVRAM Cyclic Redundancy Check (CRC) error occurred. <i>n</i> is the offset at which the error occurred. | Performing a POR clears this error. |
| 953.xx | NVRAM chip failure with mirror.1 POR the printer.2 If the problem persists, then replace the UICC card. | See <u>"2-line control panel top cover removal" on page 296, "2.4-inch control panel top cover removal" on page 297, or <u>"4.3-inch control panel top cover removal" on page 299.</u></u> |

| Error code | Description | Action |
|------------|--|---|
| 954.xx | The NVRAM chip failure with controller part. | See <u>"950.xx NVRAM failure service</u> |
| 955.xx | The Code ROM or NAND flash failed the Cyclic Redundancy Check (CRC) check or the NAND experienced an uncorrectable multibit failure. <loc> indicates the source of the failure and has one of the following values: • CRC Failure—The source is a failing</loc> | check" on page 149. |
| | package indicated by Pn where n is the package number. This error can occur on a controller with ROM or NAND flash and can occur as a result of the CRC check done when the machine is powered on. The range of package numbers is from 0–15. | |
| | • Error Correction Code (ECC) Failure—The source is a failing page indicated by Bn where n is the page number. This error occurs only if a multi-bit failure is detected during the ECC execution. Single bit failures are corrected automatically and will not result in a service error. The range of page numbers is from 0–1023. | |
| 956.xx | Controller board failure. Processor failure. Check on .02 for fan error. | |
| 957.xx | Controller board failure. ASIC failure. | |
| 958.xx | Printer has performed more than 100 shift and reflash operations as a result of ECC bit corrections. | |
| 959.xx | Controller verification failure of system boot code. | See <u>"Invalid firmware/controller board</u> service check" on page 150. |
| 959.0x | System hardware failure. | See "Controller board removal" on page 345. |

950.xx NVRAM failure service check

Warning—Potential Damage: When replacing any of the following components, replace only one component at a time or the printer will be inoperable:

Notes:

- This error indicates that the control panel and the controller board are mismatched.
- Replace the required component, enter the Diagnostics menu, and then verify that the problem is fixed before performing a POR.

| Actions | Yes | No |
|--|---------------|----------------|
| Step 1 | Go to step 2. | Go to step 3. |
| Check if the control panel has been replaced. | | |
| Has the control panel been replaced? | | |
| Step 2 | Go to step 3. | The problem is |
| Replace the control panel with a new, and not previously installed UICC card. See <u>"2-line control panel top cover removal" on page 296</u> , <u>"2.4-inch control panel top cover removal" on page 297</u> , or <u>"4.3-inch control panel top cover removal" on page 299</u> . | | solved. |
| Does the problem remain? | | |
| Step 3 | Go to step 4. | Go to step 5. |
| Check if the controller board has been replaced. | | |
| Has the controller board been replaced? | | |
| Step 4 | Go to step 5. | The problem is |
| Replace the controller board with a new, and not previously installed controller board. See "Controller board removal" on page 345. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Perform a POR. | | solved. |
| Does the problem remain? | | |

| Actions | Yes | No |
|---|------------------------------------|------------------------|
| Step 6 Clear the NVRAM of the printer: a Turn the printer off. b With the printer off, press and hold buttons 6, 7, and 8 on the numeric keypad. c Turn on the printer. d When Clear NVRAM appears, release the buttons. Notes: If the printer looks up on the Restoring Factory Defaults, wait for two minutes, and then turn off the printer. After 10 seconds, turn on the printer. Does the problem remain? | Go to step 7. | The problem is solved. |
| Step 7 Replace the control panel. See <u>"2-line control panel top cover removal" on page 296</u> , <u>"2.4-inch control panel top cover removal" on page 297</u> , or <u>"4.3-inch control panel top cover removal" on page 299</u> . Does the problem remain? | Go to step 8. | The problem is solved. |
| Step 8 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Invalid firmware/controller board service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Update the firmware. | Go to step 2. | The problem is solved. |
| Note: Contact the next level of support for the correct firmware level. | | |
| Does the problem remain? | | |
| Step 2 Replace the controller board. See <u>"Controller board removal" on page 345</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

96y errors

96y error messages

| Error code | Description | Action |
|------------|--|---|
| 960.xx | RAM memory error—The RAM soldered on the board is bad. | See <u>"Controller board removal" on page 345</u> . |
| 964.xx | A download emulation cyclic redundancy check (CRC) failure has occurred. A checksum failure was detected in the emulation header or emulation file. | See "Download emulation cyclic redundancy service check" on page 151. |

Download emulation cyclic redundancy service check

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 1 Disable the download emulation, and then program the download emulation into the firmware card again. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Replace the firmware card, and then download the emulation to the new card. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

97y errors

97y error messages

| Error code | Description | Action |
|------------------|---|--|
| 975.xx 975.xx | Network error—Unrecognizable network port. | Replace the standard network card, or the card in the specified slot. |
| 976.xx | Unrecoverable software or error in the network or network card [x]. | See <u>"Standard network/network card</u> error service check" on page 152. |
| 978.xx | Bad checksum while programming the standard network or network card [x] port. | See "Standard network/network card programming error service check" on page 152. |
| 979.xx | Flash parts failed while programming the standard network or network card [x] port. | See "Standard network/network card error service check" on page 152. |

Standard network/network card error service check

| Action | Yes | No |
|--|-------------------|----------------|
| Step 1 | Go to step 2. | Go to step 3. |
| Check if the network card is installed. | | |
| Is the network card installed? | | |
| Step 2 | Contact the next | The problem is |
| Make sure that the network card is properly installed. | level of support. | solved. |
| Does the problem remain? | | |
| Step 3 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on</u> | level of support. | solved. |
| <u>page 345</u> . | | |
| Does the problem remain? | | |

Standard network/network card programming error service check

| Action | Yes | No |
|--|-------------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| Make sure that you downloaded the code in binary mode and not in ASCII, and then reprogram the network card. | | solved. |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the network card is installed. | | |
| Is the network card installed? | | |
| Step 3 | Contact the next | The problem is |
| Make sure that the network card is properly installed. | level of support. | solved. |
| Does the problem remain? | | |
| Step 4 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

980-984 errors

980-984 error messages

| Error code | Description | Action |
|------------|--|--|
| 980.xx | The engine is experiencing unreliable communication with the specified device. | See "Options communication error service check" on page 154. |
| | Note: <device> can be one of the following:</device> | |
| | • Tray 2 | |
| | • Tray 3 | |
| 981.xx | The specified device detects an engine protocol violation. | |
| | Note: <device> can be one of the following:</device> | |
| | • Tray 2 | |
| | • Tray 3 | |
| 982.xx | The specified device detects a communication error. | |
| | Note: <device> can be one of the following:</device> | |
| | • Tray 2 | |
| | • Tray 3 | |
| 983.xx | The specified device receives an invalid command. | |
| | Note: <device> can be one of the following:</device> | |
| | • Tray 2 | |
| | • Tray 3 | |
| 984.xx | The specified device receives an invalid command parameter. | |
| | Note: <device> can be one of the following:</device> | |
| | • Tray 2 | |
| | • Tray 3 | |

99y errors

99y error messages

| Error code | Description | Action |
|------------|--|---|
| 990.xx | An equipment check condition occurred, but the exact component failure was not determined. | See <u>"Options communication error</u> service check" on page 154. |
| 991.xx | An equipment check condition occurred in the controller card. | |
| 992.xx | General software error. | |

Options communication error service check

| Action | Yes | No |
|--|------------------------------------|------------------------------------|
| Step 1 a Check if the firmware is updated, and update if necessary. b Make sure that the printer supports the option. See the <i>Printer</i>, <i>Option</i>, <i>and Stand Compatibility Guide</i>. c Make sure that the option is properly attached to the printer or adjacent option. d Perform a POR. Does the problem remain? | Go to step 2. | The problem is solved. |
| Step 2 Reseat the printer interface cable on the printer controller board. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 Do the following to each option: a Reinstall the option. b Print a test page, and then check if the option is properly working. Are all options properly working? | Go to step 4. | Contact the next level of support. |
| Step 4 Reseat the option interface cable. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 Check the option interface cable for proper connection and damage, and replace if necessary. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Other symptoms

Base printer symptoms

Base printer symptoms

| Symptom | Action |
|--|---|
| Printer does not have power. | See "Dead printer service check" on page 155. |
| False values for the front door appear on the display. | See "Interlock service check" on page 159. |

| Symptom | Action |
|--|--|
| Bin is full or sensor (narrow media) service check. | See "Sensor (narrow media) service check" on page 163. |
| TMC card service check. | See "TMC card service check" on page 103. |
| The printer is not communicating with the USB host. | See "USB service check" on page 164. |
| The printer not communicating with the network host. | See "Network service check" on page 165. |

Dead printer service check

A dead printer is one which, when powered on from a known good electrical outlet, displays no indication of power to the printer by changes to the control panel display, or any movement of the fan or motors.

If a 650-sheet duo tray is installed, remove the tray and then check the base printer for correct operation. If the base printer operates correctly, then replace the 650-sheet duo tray.

Warning—Potential Damage: Observe all necessary ESD precautions when removing and handling the controller board or any installed option cards or assemblies.

Note: Remove any input option from the printer.

| Action | Yes | No |
|--|----------------|----------------|
| Step 1 | The problem is | Go to step 2. |
| Turn on the printer. | solved. | |
| Did the printer turn on? | | |
| Step 2 | Go to step 4. | Go to step 3. |
| Check the AC power voltage. | | |
| Is the line voltage correct? | | |
| Step 3 | Go to step 4. | The problem is |
| Inform the customer of possible issues with the line voltage. | | solved. |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | The problem is |
| Check the AC power cord for damage, and replace if necessary. | | solved. |
| Does the problem remain? | | |
| Step 5 | Go to step 6. | The problem is |
| Check the USB ground contacts on the controller board for damage, and repair if necessary. | | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 6 | Go to step 7. | The problem is |
| Make sure that the voltage switch on the LVPS is properly set, and | | solved. |
| change if necessary. | | |
| Does the problem remain? | | |
| Step 7 | Go to step 8. | The problem is |
| a Turn off the printer. | · | solved. |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Check the cable connection at the JLVPS1 connector on the controller board for proper connection, and reseat if necessary. | | |
| Does the problem remain? | | |
| Step 8 | Go to step 9. | Go to step 10. |
| Turn on the printer, and then check the following voltages at the JLVPS1 connector on the controller board: | | |
| Note: Test one connector pin at a time. | | |
| • Pin 1: +6.5 V | | |
| Pin 2: Ground | | |
| • Pin 3: +6.5 V | | |
| Pin 4: Ground | | |
| • Pin 5: +6.5 V | | |
| Pin 6: Ground | | |
| • Pin 7: +24 V_RAW | | |
| Pin 8: Ground | | |
| • Pin 9: +24 V_RAW | | |
| Pin 10: Ground | | |
| • Pin 11: +24 V_RAW | | |
| Pin 12: Ground | | |
| Pin 13: RELAY_DRIVE | | |
| Pin 14: PS_ZERO_XING_IN | | |
| Pin 15: HEAT1_ON_R | | |
| • Pin 16: +24 V_ON_R+ | | |
| Are the voltage values approximately the same? | | |
| Step 9 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 10 Replace the LVPS. See <u>"LVPS removal" on page 250</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Control panel service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the indicator light on the control panel. | Go to step 3. | Go to step 4. |
| Is the indicator light on? | | |
| Step 3 Check the Ethernet and controller board LEDs on the control panel. | Go to step 4. | Go to step 9. |
| Are the LEDs on? | | |
| Step 4 Check the ribbon cable connection on the control panel and controller board. | Go to step 6. | Go to step 5. |
| Is the cable properly connected at both ends? | | |
| Step 5 Reconnect the cable. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 Check the cable for damage, and replace if necessary. | Go to step 7. | The problem is solved. |
| Does the problem remain? | | |
| Step 7 Replace the control panel cable. | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 8 Replace the control panel. See <u>"2-line control panel top cover removal" on page 296, "2.4-inch control panel top cover removal" on page 297, or "4.3-inch control panel top cover removal" on page 299.</u> | Go to step 12. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 Disconnect the LVPS cable from the controller board, and then measure the voltages of the red and orange wires. | Go to step 12. | Go to step 10. |
| Is the reading on the red wire $+6.5 \text{ V}$, and the orange wire $+25 \text{ V}$? | | |
| Step 10 Replace the LVPS cable. Does the problem remain? | Go to step 11. | The problem is solved. |
| Step 11 | Go to step 12. | The problem is |
| Replace the LVPS. See <u>"LVPS removal" on page 250</u> . | GO to step 12. | solved. |
| Does the problem remain? | | |
| Step 12 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

HVPS service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the cable at the JHVPS1 connector on the controller board for proper connection and damage, and replace if necessary. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 3 a Remove the transfer module, and then check if the three contacts move up and down, and are making contact with the transfer module. b Reposition the transfer module so that the contacts move up and down. Does the problem remain? | Go to step 4. | The problem is solved. |
| Step 4 Replace the HVPS. See "HVPS removal" on page 267. Does the problem remain? | Go to step 5. | The problem is solved. |
| Step 5 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Interlock service check

| Action | Yes | No |
|--|---------------|---------------|
| Step 1 | Go to step 2. | Go to step 7. |
| a Open the front door, and then locate the sensor (Door interlock). | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Printer diagnostics & adjustments > Sensor tests | | |
| c Find the sensor (Door interlock). | | |
| | | |
| Does the sensor status change while toggling the sensor? | | |

| Action | Yes | No |
|---|---------------|------------------------|
| Step 2 | Go to step 3. | Go to step 4. |
| a Open the front door, and then check the thin, tall, plastic web pivot plate (A) at the top right corner of the printer. | | |
| Note: With the other covers in place and closed, the web interacts with switches in the door. | | |
| b Open the toner cover, and then check the motion of the web. | | |
| Is the web loose, damaged, or missing? | | |
| Step 3 Replace the right cover. See <u>"Right cover removal" on page 257</u> . | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Open the toner door, and then check the vertical web (B) that pushes and rotates the pivot plate. | Go to step 5. | Go to step 6. |
| B | | |
| Is the web damaged? | | |

| Action | Yes | No |
|---|---------------|------------------------|
| Step 5 Replace the toner cover. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 a Open the front door. b Using a spring hook, push the metal arms (C) to check the movement of the two switches. | Go to step 8. | Go to step 7. |
| Are the switches and surrounding area damaged? | | |
| Step 7 Check the cable connections (D) on the sensor. Are the cables properly connected to the switch? | Go to step 9. | Go to step 8. |
| Step 8 Replace the interlock switch cover assembly. See "Interlock switch cover assembly removal" on page 288. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 9 a Turn off the printer. b Remove the rear cover. See "Rear cover removal" on page 343. c Turn on the printer, and then verify if the pin 1 value of the JCVR1 connector on the controller board is +25 V dc. ls the value approximately the same? | Go to step 10. | Go to step 12. |
| Step 10 a Close the front door, and then close the toner door. b Make sure that the right cover is in place. c Turn off the printer, and then disconnect the cable at the JCVR1 connector on the controller board. d Test the JCVR1 connector on the controller board under the following conditions: Close the front cover and toner door, and then test if pin 1 and pin 2 has continuity. With one or both doors open, pin 1 and pin 2 should not have continuity. | Contact the next level or support. | Go to step 11. |
| Are the tests verified? Step 11 Replace the front door. See "Front door removal" on page 282. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 12 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level or support. | The problem is solved. |

Invalid input option type or ID is detected service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Make sure to update to the latest printer firmware version. b Make sure that the options configuration is supported. c Perform a POR. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|--|------------------------------------|------------------------|
| Step 2 Check the option interface cable for proper connection and damage, and replace if necessary. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Check the printer interface cable and adjacent options for proper connection and damage, and replace if necessary. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Perform a POR. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Sensor (narrow media) service check

| Action | Yes | No |
|--|---------------|------------------------|
| Step 1 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (Narrow media). c Open the front door, and then toggle the sensor (A). | Go to step 3. | Go to step 2. |
| Does the sensor status change while toggling the sensor? | | |
| Step 2 Replace the sensor (narrow media). See <u>"Sensor (narrow media/output bin full) removal" on page 350</u> . | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|-------------------------------------|------------------------|
| Step 3 Check the sensor flag for proper installation and damage, and replace if necessary. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Check the sensor cable for proper connection or damage, and replace if necessary. | Go to step 5. | The problem is solved. |
| Does the problem remain? | | |
| Step 5 a Enter the Diagnostics menu, and then navigate to: Printer diagnostics & adjustments > Sensor tests b Find the sensor (Bin full). c Open, and then close the front door to toggle the sensor. Does the sensor status change while toggling the sensor? | Contact the next level or support. | Go to step 6. |
| Step 6 Check the sensor cable for proper connection and damage, and replace if necessary. Does the problem remain? | Go to step 7. | The problem is solved. |
| Step 7 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact your next level or support. | The problem is solved. |

USB service check

| Actions | Yes | No |
|--|---------------|----------------|
| Step 1 | Go to step 3. | Go to step 2. |
| Check if the USB cable is properly connected to the printer and host PC. | | |
| Is the cable properly connected? | | |
| Step 2 | Go to step 3. | The problem is |
| Properly connect the cable at both ends. | | solved. |
| Does the problem remain? | | |

| Actions | Yes | No |
|--|------------------------------------|------------------------------------|
| Step 3 Use a different USB cable. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 Connect a different device to the USB cable, and then check if the host PC detects the device. Did the host PC detect the device? | Go to step 5. | Contact the next level of support. |
| Step 5 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Network service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 Check if the printer is using an Ethernet network. | Go to step 2. | Go to step 3. |
| Is the printer using an Ethernet network? | | |
| Step 2 Make sure that the Ethernet cable is properly connected at both ends. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 a Make sure that the printer is not physically connected to a wired LAN. b If the printer is connected using an Ethernet connection, unplug the cable from the printer, and then perform a POR to connect the printer to a wireless network. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 a From the home screen, navigate to Settings > Network/Ports > Active Adapters. b Check if the adapter that appears matches the adapter used in the printer. | Go to step 6. | Go to step 5. |
| Do the adapters match? | | |

| Action | Yes | No |
|--|----------------|------------------------|
| Step 5 Change the active adapter setting to match the adapter used in the printer. | Go to step 6. | The problem is solved. |
| Does the problem remain? | | |
| Step 6 a Check the online status of the printer under Printers and Faxes on the host computer. b Delete all print jobs in the print queue. | Go to step 8. | Go to step 7. |
| Is the printer online and in the Ready state? | | |
| Step 7 Change the printer status to Online. | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |
| Step 8 Check the printer IP address on the Network Settings Page. | Go to step 13. | Go to step 9. |
| Does it match the IP address in the drivers port using the printer? | | |
| Step 9 Check if the printer uses a static IP address on a network. | Go to step 10. | Go to step 12. |
| Is the printer using a DHCP IP address? | | |
| Step 10 Check the first two segments of the IP address. | Go to step 11. | Go to step 12. |
| Does the IP address start with 169.254? | | |
| Step 11 Perform a POR. | Go to step 13. | The problem is solved. |
| Does the problem remain? | | |
| Step 12 Reset the IP address on the printer to match the IP address on the driver. | Go to step 13. | The problem is solved. |
| Does the problem remain? | | |
| Step 13 Check if the printer and computer IP addresses have the same subnet address. | Go to step 15. | Go to step 14 |
| Does the printer and computer IP addresses have the same subnet address? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 14 Using the subnet address supplied by the network administrator, assign a unique IP address to the printer. Note: The printer IP address should match the IP address on the print driver. | Go to step 15. | The problem is solved. |
| Does the problem remain? | | |
| Step 15 Check if the printer is physically connected to the network. | Go to step 16. | Go to step 23. |
| Is the printer physically connected to the network? | | |
| Step 16 Use a different Ethernet cable. | Go to step 17. | The problem is solved. |
| Does the problem remain? | | |
| Step 17 Have the network administrator check the network drop for activity. | Go to step 19. | Go to step 18. |
| Is the network drop functioning properly? | | |
| Step 18 Try a known and functioning network drop. Does the problem remain? | Go to step 19. | The problem is solved. |
| Step 19 | Go to step 22. | Go to step 20. |
| Check if the bulit-in Ethernet port on the controller board is used to connect to the network. | 00 to 5top 22. | 00 to stop 20. |
| Is the built-in Ethernet port on the controller board used to connect to the network? | | |
| Step 20 Make sure that the option Ethernet card is properly installed, and reseat if necessary | Go to step 21. | The problem is solved. |
| Does the problem remain? | | |
| Step 21 Replace the option Ethernet card. | Go to step 22. | The problem is solved. |
| Does the problem remain? | | |
| Step 22 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 23 Check if the printer is on the same wireless network as the other devices. | Go to step 25. | Go to step 24. |
| Is the printer on the same wireless network as the other devices? | | |
| Step 24 Assign the correct wireless network to the printer. Does the problem remain? | Go to step 25. | The problem is solved. |
| Step 25 | Go to step 26. | Contact the network |
| Check if the other devices on the wireless network are properly communicating. | Go to step 26. | administrator. |
| Are the other devices on the wireless network properly communicating? | | |
| Step 26 Make sure that the wireless card on the printer is properly installed. | Go to step 27. | The problem is solved. |
| Does the problem remain? | | |
| Step 27 Check if an antenna is attached to the wireless card. | Go to step 28. | Go to step 29. |
| Is an antenna attached to the wireless card? | | |
| Step 28 Check the antenna for proper installation and damage, and replace if necessary. | Go to step 29. | The problem is solved. |
| Does the problem remain? | | |
| Step 29 Replace the wireless card. See <u>"Wireless card removal" on page 306</u> . | Go to step 30. | The problem is solved. |
| Does the problem remain? | | |
| Step 30 Replace the controller board. See "Controller board removal" on page 345. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

TPS service check

| Action | Yes | No |
|--|-------------------|------------------------|
| Step 1 Check the cable on the JTPS1 and JTPS2 connector on the controller board for proper connection and damage, and replace if necessary. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check the cables on the left and right TPS sensors for proper connection and damage, and replace if necessary. | Go to step 3. | The problem is solved. |
| Does the problem remain? | | |
| Step 3 Check the left and right TPS sensors for proper installation and damage, and replace if necessary. See "Sensors (toner patch) removal" on page 264. | Go to step 4. | The problem is solved. |
| Does the problem remain? | | |
| Step 4 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

Weather station service check

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 1 Make sure that the cable on the JWS1 connector on the controller board is properly connected. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Make sure that the weather station cable is properly connected. Does the problem remain? | Go to step 3. | The problem is solved. |
| Step 3 Replace the sensor (weather station). See <u>"Weather station removal" on page 303</u> . | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

2.4-inch control panel keypad false navigation key press service check

| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | Go to step 3. |
| a Remove the 2.4-inch keypad from the control panel assembly. See "2.4-inch control panel keypad removal" on page 302. b Check the four bosses on the navigation key for excessive flashing on their ends. | Go to steμ 2. | Go to step 3. |
| Is there excessive flashing? | | |
| Step 2 | Go to step 3. | The problem is |
| a Release the four tabs (A) on the navigation key from the keypad assembly. b Remove the flashing from the ends of the bosses. c Reinstall the keypad into the control panel assembly. Does the problem remain? | | solved. |

| Action | Yes | No |
|---|------------------------------------|------------------------|
| Step 3 Replace the 2.4-inch control panel. See <u>*2.4-inch control panel bezel removal*</u> on page 292. | Contact the next level of support. | The problem is solved. |
| Does the problem remain? | | |

Input option symptoms

550-sheet tray and 650-sheet duo tray input option symptoms

Note: The C2325, MC2325, CS421, CX421, C2425, and MC2425 does not support the 550-sheet tray.

| Symptom | Action |
|---|---|
| The printer fails to recognize an installed option. | See "Option and paper size not recognized service check" on page 173. |
| Tray [x] does not recognize the paper size loaded. | See <u>"Option and paper size not recognized service check" on page 173</u> . |
| A Tray missing message appears even if the tray is installed. The tray insert does not fit in the tray base. | See "Sensor (tray [x]) service check" on page 172. |
| Double feed. | See "Double feed and printout skewed service check" on page 176. |
| The printout is skewed. | See "Double feed and printout skewed service check" on page 176. |
| The printer failed to feed from the option tray. | See "Failed to feed from option tray and leading edge damaged service check" on page 182. |
| The leading edge is damaged. | See "Failed to feed from option tray and leading edge damaged service check" on page 182. |
| The printer failed to feed from the MPF. | See "Failed to load/feed from the multipurpose feeder service check" on page 179. |
| Load MPF with plain letter-size paper. | See "Failed to load/feed from the multipurpose feeder service check" on page 179. |
| Tray 2 or tray 3 is missing. | See "Tray 2 or tray 3 missing service check" on page 188. |
| Tray 2 or tray 3 is not detected. | See "Tray 2 or tray 3 not detected service check" on page 185. |
| Tray 2 or tray 3 is empty. | See "Tray 2 or tray 3 empty service check" on page 191. |
| Incompatible tray 3. | See "Incompatible tray 3 service check" on page 194. |

Sensor (tray [x]) service check

| Actions | Yes | No |
|--|---------------|------------------------|
| Step 1 | Go to step 2. | Problem resolved. |
| a Perform a POR. | | |
| b Reseat the printer on the input option. | | |
| c Make sure that the input option configuration is supported. See the <i>Printer, Option, and Stand Compatibility Guide</i> . | 9 | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 6. |
| When the printer is in the Ready state, remove and then insert the tray. | | |
| Did a Keep the current configuration message appear? | , | |
| Step 3 | Go to step 4. | The problem is |
| Check the vertical wall at the left side of the tray for damage, and replace the tray if necessary. | 1 | solved. |
| Does the problem remain? | | |
| Step 4 | Go to step 5. | Contact the next |
| Check the metal leaf (A) spring for damage. | | level of support. |
| A | | |
| Is the spring damaged and unable to actuate the sensor? | | |
| Step 5 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. | Go to step 6. | The problem is solved. |
| If a 550-sheet tray insert is affected, then replace the 550-sheet tray. | | |
| Does the problem remain? | | |

| Actions | Yes | No |
|---|------------------------------------|------------------------|
| Step 6 Check if a Keep the current configuration message appears. | Go to step 7. | The problem is solved. |
| Did a Keep the current configuration message appear? | | |
| Step 7 a Turn off the printer. b Remove the rear cover. See <u>"Rear cover removal" on page 343</u>. c Disconnect the following cables on the controller board: | The problem is solved. | Go to step 8. |
| JTRAY1 cable for tray 1 JOPT1 cable for tray 2 and tray 3 d Turn on the printer, and then measure the following voltage values: | | |
| For tray 1, check the following pins on the JTRAY1 connector on the controller board: • Pin 1: +5 V dc • Pin 2: +5 V dc • Pin 3: Ground For tray 2, check the following pins on the JOPT1 connector on the controller board: • Pin 2: Ground • Pin 3: Ground • Pin 5: +24 V dc Are the voltage values approximately the same? | | |
| Step 8 Replace the controller board. See "Controller board removal" on page 345. Does the problem remain? | Contact the next level of support. | The problem is solved. |

Option and paper size not recognized service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Perform a POR. | Go to step 2. | The problem is solved. |
| b Reseat the printer on the input option. c Make sure that the input option configuration is supported. See the <i>Printer, Option, and Stand Compatibility Guide</i>. | | |
| Does the problem remain? | | |

| Action | Yes | No |
|--|---------------|------------------------------|
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |
| Step 3 | Go to step 9. | Go to step 4. |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: | · | duo tray insert is |
| For the 550-sheet tray | | affected, then |
| Tray insert | | replace the 650-sheet duo |
| Paper restraints | | tray. |
| Paper dams | | • If a 550-sheet |
| Pick pads | | tray insert is |
| For the 650-sheet duo tray | | affected, then replace the |
| Tray insert | | 550-sheet tray. |
| Paper restraints | | |
| Paper dams | | |
| Pick pads | | |
| MPF gear | | |
| MPF pick assembly | | |
| MPF tray | | |
| Is the tray free of damage? | | |

| Action | Yes | No |
|--|----------------|--|
| Step 6 | Go to step 7. | Go to step 8. |
| Check the pick tires for wear, damage, contamination, and proper installation. | | |
| Is the pick tire properly installed and free of wear or damage? | | |
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 Replace the pick tire. See "Pick tire removal" on page 358. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 | Go to step 10. | Go to step 11. |
| a Turn off the printer. | · | · |
| b Remove the printer from the optional trays. | | |
| c Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| d Reseat the JOPT1 cable on the controller board. | | |
| e Check the JOPT1 cable for damage, and replace if necessary. | | |
| f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. | | |
| Is the autoconnect/option tray cable damaged? | | |
| Step 10 | Go to step 12. | The problem is |
| • If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. | | solved. |
| If the option tray autoconnector is damaged, then go to step 12. | | |
| Does the problem remain? | | |
| Step 11 | Go to step 12. | The problem is |
| If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. | | solved. |
| If a 550-sheet tray insert is affected, then replace the 550-sheet tray. | | |
| Does the problem remain? | | |

| Ac | tion | Yes | No |
|-----|--|-------------------|----------------|
| Ste | p 12 | Contact the next | Go to step 13. |
| а | Turn off the printer. | level of support. | |
| b | Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| С | Disconnect the cable at the JOPT1 connector on the controller board. | | |
| d | Turn on the printer. | | |
| е | Measure the following voltages on the JOPT1 connector on the controller board: | | |
| | • Pin 2: Ground | | |
| | Pin 3: Ground | | |
| | • Pin 5: +24 V dc | | |
| | • Pin 6: Ground | | |
| | • Pin 7: +5 V dc | | |
| | Pin 9: Ground | | |
| | • Pin 10: Ground | | |
| Are | e the voltage readings approximately the same? | | |
| Ste | p 13 | Contact the next | The problem is |
| | place the controller board. See <u>"Controller board removal" on</u> ge 345. | level of support. | solved. |
| Do | es the problem remain? | | |

Double feed and printout skewed service check

| Action | Yes | No |
|--|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Fan the paper. | | solved. |
| b Verify the proper tray settings for the paper. | | |
| c Check the condition of all the option tray pick tires. | | |
| d Make sure that the tray is fully inserted. | | |
| e Make sure that the paper guides are properly adjusted to the paper size being loaded. | | |
| f Make sure that the printer and option trays are on a flat surface. | | |
| g Make sure that the printer is sitting flat on the option trays. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |

| Action | Yes | No |
|--|---------------|--|
| Step 3 | Go to step 9. | Go to step 4. |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. | | |
| b Enter the Diagnostics menu, and then navigate to: Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: | | duo tray insert is |
| For the 550-sheet tray | | affected, then replace the 650-sheet duo |
| Tray insert | | |
| Paper restraints | | tray. |
| Paper dams | | • If a 550-sheet |
| Pick pads | | tray insert is |
| For the 650-sheet duo tray | | affected, then replace the |
| Tray insert | | 550-sheet tray. |
| Paper restraints | | - |
| Paper dams | | |
| Pick pads | | |
| MPF gear | | |
| MPF pick assembly | | |
| MPF tray | | |
| Is the tray free of damage? | | |
| Step 6 | Go to step 7. | Go to step 8. |
| Check the pick tires for wear, damage, contamination, and proper installation. | | |
| Is the pick tire properly installed and free of wear or damage? | | |

| Action | Yes | No |
|---|----------------|--|
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 Replace the pick tire. See <u>"Pick tire removal" on page 358.</u> Does the problem remain? | Go to step 9. | The problem is solved. |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage, and replace if necessary. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. Is the autoconnect/option tray cable damaged? | Go to step 10. | Go to step 11. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Ac | tion | Yes | No |
|-----|---|-------------------|----------------|
| Ste | ep 12 | Contact the next | Go to step 13. |
| а | Turn off the printer. | level of support. | |
| b | Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| С | Disconnect the cable at the JOPT1 connector on the controller board. $\label{eq:connector}$ | | |
| d | Turn on the printer. | | |
| е | Measure the following voltages on the JOPT1 connector on the controller board: | | |
| | • Pin 2: Ground | | |
| | Pin 3: Ground | | |
| | • Pin 5: +24 V dc | | |
| | Pin 6: Ground | | |
| | • Pin 7: +5 V dc | | |
| | Pin 9: Ground | | |
| | • Pin 10: Ground | | |
| Are | e the voltage readings approximately the same? | | |
| Ste | ep 13 | Contact the next | The problem is |
| | place the controller board. See <u>"Controller board removal" on</u> ge 345. | level of support. | solved. |
| ha | ye 373 . | | |
| Do | es the problem remain? | | |

Failed to load/feed from the multipurpose feeder service check

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Make sure that the 650-sheet duo tray is tray 2. b Make sure that the 650-sheet duo tray is properly installed. c Fan the paper. d Make sure that the correct tray setting is set for the paper. e Verify the paper source. f Check the MPF pick tires for wear or damage, and replace if necessary. g Make sure that the tray insert is fully inserted. h Make sure that the paper is free from damage and defects. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|---------------|--|
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |
| Step 3 a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. b Enter the Diagnostics menu, and then navigate to: Additional input tray diagnostics > Motor tests | Go to step 9. | Go to step 4. |
| c Select a motor, and the select Start . | | |
| Select a motor, and the select Start. | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one option tray to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and the select Start . | | |
| Does the motor run on each input option? | | |
| Step 5 Check the following for any damage: Input tray Paper restrains Paper dams Pick pads MPF gear MPF pick assembly MPF tray Is the option tray free of damage? | Go to step 6. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 6 | Go to step 9. | Go to step 7. |
| a Make sure that the pick tire is free of contamination. | | |
| b Check the pick tire for proper installation and damage. | | |
| Is the pick tire properly installed and free of damage? | | |
| | | The much be at the |
| Step 7 Replace the pick tire. See <u>"Pick tire removal" on page 358</u> . | Go to step 8. | The problem is solved. |
| Does the problem remain? | | |

| Action | Yes | No |
|---|----------------|--|
| Step 8 a Check the tray insert for damage or contamination. b Check the following for damage or contamination: • Top and bottom autoconnector • Sensor (pass-through) • Feed rollers • Input option pick assembly Is the tray insert free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage, and replace if necessary. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. Is the autoconnect/option tray cable damaged? | Go to step 10. | Go to step 12. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 11. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Ac | tion | Yes | No |
|-----|--|-------------------|----------------|
| Ste | ep 12 | Contact the next | Go to step 13. |
| а | Turn off the printer. | level of support. | |
| b | Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| С | Disconnect the JOPT1 cable on the controller board. | | |
| d | Turn on the printer. | | |
| е | Measure the following voltages on the JOPT1 connector on the controller board: | | |
| | • Pin 2: Ground | | |
| | Pin 3: Ground | | |
| | • Pin 5: +24 V dc | | |
| | Pin 6: Ground | | |
| | • Pin 7: +5 V dc | | |
| | Pin 9: Ground | | |
| | • Pin 10: Ground | | |
| Are | e the voltage readings approximately the same? | | |
| Ste | p 13 | Contact the next | The problem is |
| | place the controller board. See <u>"Controller board removal" on</u> ge 345. | level of support. | solved. |
| Do | es the problem remain? | | |

Failed to feed from option tray and leading edge damaged service check

| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Fan the paper. | | solved. |
| b Verify the proper tray settings for the paper. | | |
| c Verify the paper source. | | |
| d Check the MPF pick tires for wear or damage, and replace if necessary. | | |
| e Make sure that the tray is fully inserted. | | |
| f Refer to the paper specifications and check the paper condition. | | |
| g Make sure that the paper is free from damage and defects. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |

| | v | |
|---|---------------|-----------------------------------|
| Action | Yes | No |
| Step 3 | Go to step 9. | Go to step 4. |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test vin suggestible on each ention? | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: | | duo tray insert is affected, then |
| For the 550-sheet tray | | replace the |
| • Tray insert | | 650-sheet duo |
| Paper restraints | | tray. |
| Paper dams The second | | • If a 550-sheet |
| Pick pads | | tray insert is affected, then |
| For the 650-sheet duo tray | | replace the |
| • Tray insert | | 550-sheet tray. |
| Paper restraints | | |
| Paper dams | | |
| Pick pads | | |
| MPF gear | | |
| MPF pick assembly | | |
| MPF tray | | |
| Is the tray free of damage? | | |
| Step 6 | Go to step 7. | Go to step 8. |
| Check the pick tires for wear, damage, contamination, and proper installation. | | |
| Is the pick tire properly installed and free of wear or damage? | | |

| Action | Yes | No |
|---|----------------|--|
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 | Go to step 9. | The problem is |
| Replace the pick tire. See "Pick tire removal" on page 358. | | solved. |
| Does the problem remain? | | |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. Is the autoconnect/option tray cable damaged? | Go to step 10. | Go to step 11. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Ac | tion | Yes | No |
|-----|---|-------------------|----------------|
| Ste | ep 12 | Contact the next | Go to step 13. |
| а | Turn off the printer. | level of support. | |
| b | Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| С | Disconnect the cable at the JOPT1 connector on the controller board. $\label{eq:connector}$ | | |
| d | Turn on the printer. | | |
| е | Measure the following voltages on the JOPT1 connector on the controller board: | | |
| | • Pin 2: Ground | | |
| | • Pin 3: Ground | | |
| | • Pin 5: +24 V dc | | |
| | Pin 6: Ground | | |
| | • Pin 7: +5 V dc | | |
| | • Pin 9: Ground | | |
| | • Pin 10: Ground | | |
| Are | e the voltage readings approximately the same? | | |
| Ste | ep 13 | Contact the next | The problem is |
| | place the controller board. See <u>"Controller board removal" on</u> ge 345. | level of support. | solved. |
| Do | es the problem remain? | | |

Tray 2 or tray 3 not detected service check

| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Perform a POR. | | solved. |
| b Reseat the option trays. | | |
| | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |

| Action | Yes | No |
|--|---------------|---|
| Step 3 | Go to step 9. | Go to step 4. |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. | | |
| b Enter the Diagnostics menu, and then navigate to: Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start. | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: | | duo tray insert is affected, then replace the |
| For the 550-sheet tray | | |
| Tray insert | | 650-sheet duo |
| Paper restraints | | tray. |
| Paper dams | | • If a 550-sheet |
| Pick pads | | tray insert is |
| For the 650-sheet duo tray | | affected, then replace the |
| Tray insert | | 550-sheet tray. |
| Paper restraints | | , |
| Paper dams | | |
| Pick pads | | |
| MPF gear | | |
| MPF pick assembly | | |
| MPF tray | | |
| Is the tray free of damage? | | |
| Step 6 | Go to step 7. | Go to step 8. |
| Check the pick tires for wear, damage, contamination, and proper installation. | | |
| Is the pick tire properly installed and free of wear or damage? | | |

| Action | Yes | No |
|--|----------------|--|
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 Replace the pick tire. See "Pick tire removal" on page 358. | Go to step 9. | The problem is solved. |
| Does the problem remain? | | |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage, and replace if necessary. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. Is the tray autoconnect/option tray cable damaged? | Go to step 10. | Go to step 11. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Action | Yes | No |
|---|----------------------|----------------|
| Step 12 | Contact the next | Go to step 13. |
| a Turn off the printer. | level of support. | |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Disconnect the cable at the JOPT1 connector on the control board. | ller | |
| d Turn on the printer. | | |
| Measure the following voltages on the JOPT1 connector on to controller board: | the | |
| Pin 2: Ground | | |
| Pin 3: Ground | | |
| • Pin 5: +24 V dc | | |
| Pin 6: Ground | | |
| • Pin 7: +5 V dc | | |
| Pin 9: Ground | | |
| • Pin 10: Ground | | |
| Are the voltage readings approximately the same? | | |
| Step 13 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal"</u> page 345. | on level of support. | solved. |
| Does the problem remain? | | |

Tray 2 or tray 3 missing service check

| Action | Yes | No |
|---|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Perform a POR. | | solved. |
| b Reseat the option trays. | | |
| c Reseat the tray inserts. | | |
| d Make sure that the paper pick assembly can be manually triggered. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |

| | v | |
|---|---------------|-----------------------------------|
| Action | Yes | No |
| Step 3 | Go to step 9. | Go to step 4. |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 9. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test vin suggestible on each ention? | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: | | duo tray insert is affected, then |
| For the 550-sheet tray | | replace the |
| • Tray insert | | 650-sheet duo |
| Paper restraints | | tray. |
| Paper dams The second | | • If a 550-sheet |
| Pick pads | | tray insert is affected, then |
| For the 650-sheet duo tray | | replace the |
| • Tray insert | | 550-sheet tray. |
| Paper restraints | | |
| Paper dams | | |
| Pick pads | | |
| MPF gear | | |
| MPF pick assembly | | |
| MPF tray | | |
| Is the tray free of damage? | | |
| Step 6 | Go to step 7. | Go to step 8. |
| Check the pick tires for wear, damage, contamination, and proper installation. | | |
| Is the pick tire properly installed and free of wear or damage? | | |

| Action | Yes | No |
|---|----------------|--|
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 | Go to step 9. | The problem is |
| Replace the pick tire. See "Pick tire removal" on page 358. | | solved. |
| Does the problem remain? | | |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage, and replace if necessary. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. ls the autoconnect/option tray cable damaged? | Go to step 10. | Go to step 11. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Action | Yes | No |
|---|-------------------|----------------|
| Step 12 | Contact the next | Go to step 13. |
| a Turn off the printer. | level of support. | |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Disconnect the cable at the JOPT1 connector on the controller board. | | |
| d Turn on the printer. | | |
| e Measure the following voltages on the JOPT1 connector on the controller board: | | |
| Pin 2: Ground | | |
| Pin 3: Ground | | |
| • Pin 5: +24 V dc | | |
| Pin 6: Ground | | |
| • Pin 7: +5 V dc | | |
| Pin 9: Ground | | |
| Pin 10: Ground | | |
| Are the voltage readings approximately the same? | | |
| Step 13 | Contact the next | The problem is |
| Replace the controller board. See "Controller board removal" on page 345. | level of support. | solved. |
| Does the problem remain? | | |

Tray 2 or tray 3 empty service check

| Action | Yes | No |
|--|---------------|----------------|
| Step 1 | Go to step 2. | The problem is |
| a Add paper in the tray. | | solved. |
| b Properly set the paper restraints in the tray. | | |
| c Perform a POR. | | |
| d Reseat the option trays. | | |
| e Refer to the paper specifications and check the condition of the paper. | | |
| f Make sure that the paper is free from damage and defects. | | |
| Does the problem remain? | | |
| Step 2 | Go to step 3. | Go to step 4. |
| Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | | |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |

| Astion | Vac | N- |
|--|---------------|---|
| Action | Yes | No |
| a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. b Enter the Diagnostics menu, and then navigate to: Additional input tray diagnostics > Motor tests c Select a motor, and then select Start. | Go to step 9. | Go to step 4. |
| Does the test run successfully on each option? | | |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. b Enter the Diagnostics menu, and then navigate to: Additional input tray diagnostics > Motor tests c Select a motor, and then select Start. Does the test run successfully on each option? | Go to step 9. | Go to step 5. |
| Step 5 | Go to step 6. | • If a 650-sheet |
| Check the following for any damage: For the 550-sheet tray Tray insert Paper restraints Paper dams Pick pads For the 650-sheet duo tray Tray insert Paper restraints Paper dams Pick pads MPF gear MPF pick assembly MPF tray | | duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Is the tray free of damage? | | |
| Step 6 Check the pick tires for wear, damage, contamination, and proper installation. Is the pick tire properly installed and free of wear or damage? | Go to step 7. | Go to step 8. |

| Action | Yes | No |
|---|----------------|--|
| Step 7 Check the tray and the following for any damage or contamination: Top and bottom autoconnector Sensor (pass-through) Feed rollers Input option pick assembly (if it can go down every time the tray is inserted) Is the tray free of damage or contamination? | Go to step 9. | If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. |
| Step 8 Replace the pick tire. See <u>"Pick tire removal" on page 358.</u> Does the problem remain? | Go to step 9. | The problem is solved. |
| Step 9 a Turn off the printer. b Remove the printer from the trays. c Remove the rear cover. See "Rear cover removal" on page 343. d Reseat the JOPT1 cable on the controller board. e Check the JOPT1 cable for damage, and replace if necessary. f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. Is the autoconnect/option tray cable damaged? | Go to step 10. | Go to step 11. |
| Step 10 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. If the option tray autoconnector is damaged, then go to step 12. Does the problem remain? | Go to step 12. | The problem is solved. |
| Step 11 If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. If a 550-sheet tray insert is affected, then replace the 550-sheet tray. Does the problem remain? | Go to step 12. | The problem is solved. |

| Ac | tion | Yes | No |
|-----|---|-------------------|----------------|
| Ste | ep 12 | Contact the next | Go to step 13. |
| а | Turn off the printer. | level of support. | |
| b | Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| С | Disconnect the cable at the JOPT1 connector on the controller board. $\label{eq:connector}$ | | |
| d | Turn on the printer. | | |
| е | Measure the following voltages on the JOPT1 connector on the controller board: | | |
| | • Pin 2: Ground | | |
| | Pin 3: Ground | | |
| | • Pin 5: +24 V dc | | |
| | Pin 6: Ground | | |
| | • Pin 7: +5 V dc | | |
| | • Pin 9: Ground | | |
| | • Pin 10: Ground | | |
| Are | e the voltage readings approximately the same? | | |
| Ste | ep 13 | Contact the next | The problem is |
| | place the controller board. See <u>"Controller board removal" on</u> ge 345. | level of support. | solved. |
| Do | es the problem remain? | | |

Incompatible tray 3 service check

Note: The C2325, MC2325, CS421, CX421, C2425, and MC2425 does not support the 550-sheet option tray.

| Action | Yes | No |
|---|---------------|------------------------|
| Step 1 a Make sure that the sequence of the option trays is correct. The 650-sheet duo tray should be tray 2, and the 550-sheet tray should be tray 3. b Reseat the option trays. | Go to step 2. | The problem is solved. |
| Does the problem remain? | | |
| Step 2 Check if the printer is using both the 650-sheet duo tray and 550-sheet tray. | Go to step 3. | Go to step 4. |
| Is the printer using both the 650-sheet duo tray and 550-sheet tray? | | |


| Action | Yes | No |
|--|---------------|--|
| Step 3 | Go to step 7. | Go to step 4. |
| a Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| b Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 4 | Go to step 7. | Go to step 5. |
| a Isolate the problem. Verify the problem by installing only one input option to the printer at a time. | | |
| b Enter the Diagnostics menu, and then navigate to: | | |
| Additional input tray diagnostics > Motor tests | | |
| c Select a motor, and then select Start . | | |
| Does the test run successfully on each option? | | |
| Step 5 | Go to step 7. | • If a 650-sheet |
| Check the tray and the following for any damage or contamination: | | duo tray insert is |
| Top and bottom autoconnector | | affected, then |
| Sensor (pass-through) | | replace the 650-sheet duo |
| Feed rollers | | tray. |
| Input option pick assembly (if it can go down every time the tray is inserted) | | If a 550-sheet tray insert is affected, then |
| Is the tray free of damage or contamination? | | replace the 550-sheet tray. |
| Step 6 | Go to step 7. | The problem is |
| Replace the pick tire. See "Pick tire removal" on page 358. | | solved. |
| Does the problem remain? | | |
| Step 7 | Go to step 8. | Go to step 9. |
| a Turn off the printer. | ' | , i |
| b Remove the printer from the trays. | | |
| c Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| d Reseat the JOPT1 cable on the controller board. | | |
| e Check the JOPT1 cable for damage, and replace if necessary. | | |
| f Position the printer to partially hang on the side of a table, and then check the autoconnect/option tray cable for damage. | | |
| Is the autoconnect/option tray cable damaged? | | |

| Action | Yes | No |
|---|-------------------|------------------------|
| Step 8 If the printer autoconnector is damaged, then replace the tray 2 to controller board cable. | Go to step 10. | The problem is solved. |
| If the option tray autoconnector is damaged, then go to step 12. | | |
| Does the problem remain? | | |
| Step 9 | Go to step 10. | The problem is |
| If a 650-sheet duo tray insert is affected, then replace the 650-sheet duo tray. | | solved. |
| If a 550-sheet tray insert is affected, then replace the 550-sheet tray. | | |
| Does the problem remain? | | |
| Step 10 | Contact the next | Go to step 11. |
| a Turn off the printer. | level of support. | |
| b Remove the rear cover. See <u>"Rear cover removal" on page 343</u> . | | |
| c Disconnect the cable at the JOPT1 connector on the controller board. | | |
| d Turn on the printer. | | |
| e Measure the following voltages on the JOPT1 connector on the controller board: | | |
| Pin 2: Ground | | |
| Pin 3: Ground | | |
| • Pin 5: +24 V dc | | |
| Pin 6: Ground | | |
| • Pin 7: +5 V dc | | |
| Pin 9: Ground | | |
| • Pin 10: Ground | | |
| Are the voltage readings approximately the same? | | |
| Step 11 | Contact the next | The problem is |
| Replace the controller board. See <u>"Controller board removal" on page 345</u> . | level of support. | solved. |
| Does the problem remain? | | |

Service menus


Using the control panel

Lexmark C2325




| | Use the | То |
|---|-----------------------|---|
| 1 | Display | View printer messages and supply status. |
| | | Set up and operate the printer. |
| 2 | Menu button | Access the printer menus. |
| 3 | Power button | Turn on or turn off the printer. |
| | | Note: To turn off the printer, press and hold the power button for five seconds. |
| | | Set the printer to Sleep or Hibernate mode. |
| | | Wake the printer from Sleep or Hibernate mode. |
| 4 | Stop or Cancel button | Stop the current printer task. |
| 5 | Indicator light | Check the printer status. |
| 6 | Back button | Return to the previous screen. |
| 7 | Right arrow button | Scroll through menus or move between screens and menu options. |
| | | Increase the numeric value of a setting. |
| 8 | Select button | Select a menu option. |
| | | Save the changes in a setting. |
| 9 | Left arrow button | Scroll through menus or move between screens and menu options. |
| | | Decrease the numeric value of a setting. |

Lexmark CS421, Lexmark CS521, Lexmark C2425, and Lexmark C2535



| | Use the | То | |
|----|-----------------------|---|--|
| 1 | Display | View printer messages and supply status. | |
| | | Set up and operate the printer. | |
| 2 | Select button | Select a menu option. | |
| | | Save the changes in a setting. | |
| 3 | Arrow buttons | Scroll through menus or move between screens and menu options. | |
| | | Adjust the numeric value of a setting. | |
| 4 | Numeric keypad | Enter numbers or symbols in an input field. | |
| 5 | Power button | Turn on or turn off the printer. | |
| | | Note: To turn off the printer, press and hold the power button for five seconds. | |
| | | Set the printer to Sleep or Hibernate mode. | |
| | | Wake the printer from Sleep or Hibernate mode. | |
| 6 | Backspace button | Move the cursor backward and delete a character in an input field. | |
| 7 | Stop or Cancel button | Stop the current printer task. | |
| 8 | Indicator light | Check the printer status. | |
| 9 | Back button | Return to the previous screen. | |
| 10 | Home button | Go to the home screen. | |

Lexmark CS622 and Lexmark C2240



| | Use the | То |
|---|-----------------------|---|
| 1 | Display | View printer messages and supply status. |
| | | Set up and operate the printer. |
| 2 | Home button | Go to the home screen. |
| 3 | Numeric keypad | Enter numbers or symbols in an input field. |
| 4 | Power button | Turn on or turn off the printer. |
| | | Note: To turn off the printer, press and hold the power button for five seconds. |
| | | Set the printer to Sleep or Hibernate mode. |
| | | Wake the printer from Sleep or Hibernate mode. |
| 5 | Stop or Cancel button | Stop the current printer task. |
| 6 | Indicator light | Check the printer status. |
| 7 | Back button | Return to the previous screen. |
| | | Select a menu option. |
| | | Save the changes in a setting. |

Understanding the status of the power button and indicator light

| Indicator light | Printer status |
|-----------------|--|
| Off | The printer is off or in Hibernate mode. |
| Blue | The printer is ready or processing data. |
| Red | The printer requires user intervention. |

| Power button light | Printer status |
|--------------------|--|
| Off | The printer is off, ready, or processing data. |
| Solid amber | The printer is in Sleep mode. |
| Blinking amber | The printer is in Hibernate mode. |

Using the home screen

Note: Your home screen may vary depending on your home screen customization settings, administrative setup, and active embedded solutions.



| Touch | | То |
|-------|-----------------|--|
| 1 | Status/Supplies | Show a warning or error message whenever the printer requires intervention to continue processing. |
| | | View more information on the printer warning or message, and on how to clear it. |
| | | Note: You can also access this setting by touching the top section of the home screen. |
| 2 | Job Queue | Show all the current print jobs. |
| | | Note: You can also access this setting by touching the top section of the home screen. |
| 3 | Change Language | Change the language on the display. |
| 4 | Settings | Access the printer menus. |
| 5 | Eco-Settings | Manage energy consumption, noise, toner, and paper usage settings. |
| 6 | Held Jobs | Show the print jobs that are held in the printer memory. |
| 7 | USB Drive | Print photos and documents from a flash drive. |
| 8 | Address Book | Manage a contact list that other applications on the printer can access. |

Configuring the door interlock bypass jumpers

Note: The interlock bypass jumpers are only used with the following motors:

- Motor (fuser)
- Motor (K developer)

- Motor (transfer module)
- Motor (duplex/MPF)

The controller board has two door interlock bypass jumpers. These jumpers allow you to remove the motor cover and open the toner door to see the motors in operation while being tested in Diagnostics mode. The JMTREN1 jumper connector allows you to bypass the interlock switches, and test the motor (fuser) and motor (K developer/transfer module). The JMTREN2 jumper connector allows you to bypass the interlock switches, and test the motor (duplex/MPF).

Note: If the jumpers are not set to the bypass position, and a motor test is performed while the toner door is open, then a 1yy.80 error occurs.


Jumper configurations




Interlock bypass disabled (default)



Interlock bypass enabled



Interlock bypass disabled (default)



Interlock bypass enabled

Setting the jumper

- **1** Turn off the printer.
- 2 Remove the rear cover. See "Rear cover removal" on page 343.
- **3** Locate the jumper connectors on the controller board.
- **4** Move the jumper of the motor being tested to the bypass position.
- **5** From the control panel, press and hold the **3** and **6** buttons while turning on the printer to enter the Diagnostics menu.
- 6 Select Printer diagnostics & adjustments > Motor tests.

- 7 Select a motor, and then press **OK** or touch **Start**.
- **8** After the test, turn off the printer, and then move the jumpers back to the default position.

Note: If the jumpers are not moved to the default position, then a **False door open** message appears on the screen.

Diagnostics menu

Entering the Diagnostics menu

The Diagnostics menu contains tests that are used to help isolate issues with the printer. To access some of these tests, avoid POST tests that run at POR. Some POST tests can generate errors that prevent a diagnostic test from running.

To access the Diagnostics menu from the home screen, press ** 3 6 on the control panel.

For 2-line control panels, press the left arrow button twice, press **OK**, and then press the right arrow button.

Reports

Device Settings

This report lists all the current printer settings.

Enter the Diagnostics menu, and then navigate to:

Reports > Device > Device Settings

For non-touch-screen printer models, press on avigate through the settings.

Installed Licenses

This setting lists all the installed licenses and their feature data.

Enter the Diagnostics menu, and then navigate to:

Reports > Licenses > Installed Licenses

For non-touch-screen printer models, press OK to navigate through the settings.

Advanced Print Quality Samples

This setting prints a list of the printer settings and sample pages to check print quality.

Enter the Diagnostics menu, and then navigate to:

Advanced Print Quality Samples > Advanced Print Quality Test Pages

For non-touch-screen printer models, press on avigate through the settings.

Event Log

Display Log

This setting displays the panel text that appears when the event occurs.

Enter the Diagnostics menu, and then navigate to:

Event Log > Display Log

For non-touch-screen printer models, press ok to navigate through the settings.

Print Log

This setting lists an extended version of the various printer events.

1 Enter the Diagnostics menu, and then navigate to:

Event Log > Print Log

For non-touch-screen printer models, press ok to navigate through the settings.

2 Press OK or touch Start.

Note: The events that appear in the report vary depending on the operational history of the printer.

Print Log Summary

This setting lists a brief summary of the various printer events.

1 Enter the Diagnostics menu, and then navigate to:

Event Log > Print Log Summary

For non-touch-screen printer models, press ok to navigate through the settings.

2 Press OK or touch Start.

Note: The events that appear in the report vary depending on the operational history of the printer.

Mark Log

This setting allows you to create a service, maintenance, or custom log entry. Each log entry is added in the printer event log.

1 Enter the Diagnostics menu, and then navigate to:

Event Log > Mark Log

For non-touch-screen printer models, press OK to navigate through the settings.

2 Select a log that you want to create, and then press OK or touch Start.

Input tray quick print

This setting lets you print a single or continuous Quick Test page in either duplex or simplex mode.

- 1 Enter the Diagnostics menu, and then select Input tray quick print.
- **2** Select where you want to print the pages from.
- 3 Select whether to print a single or continuous test page, and then select Start.

Printer Setup

Printed page count (mono)

This setting displays the amount of pages printed in mono.

- 1 Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the printed page count for mono.

Printed page count (color)

This setting displays the amount of pages printed in color.

- 1 Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the printed page count for color.

Permanent page count

This setting displays the total number of pages printed in mono and color. After all the print tests are completed, this value resets to zero.

- **1** Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the permanent page count.

Processor ID

This setting indicates the ID of the processor on the controller board.

- 1 Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the processor ID.

Serial number

This setting displays a read-only value of the serial number.

- 1 Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the serial number.

Model name

This setting displays the model name of the printer.

- 1 Enter the Diagnostics menu, and then select **Printer Setup**.
- **2** View the model name.

Engine setting [x]

Warning—Potential Damage: Do not change this setting without specific instructions from the next level of support.

This setting allows you to select a printer engine setting. Possible values are 0–255. 0 is the default.

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > Engine setting [x]

2 Select a setting, enter a value, and then press OK or touch **OK**.

EP setup

Warning—Potential Damage: Do not change these settings without specific instructions from the next level of support. Changing these settings may cause other problems to occur aside from the one being resolved.

This setting allows you to adjust the EP setup of the printer.

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup

2 Select a setting.

Charge adjust, Developer adjust, and Transfer adjust

These settings enable you to adjust the high voltage levels controlling the electrophotographic process. Use these settings to compensate for unusual operating circumstances such as high humidity.

To adjust the voltage levels:

- **1** Select a component to adjust:
 - To adjust the photoconductor, enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Charge adjust

• To adjust the developer unit, enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Developer adjust

• To adjust the transfer module, enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Transfer adjust

2 Select a color to adjust.

Fuser adjust

This adjustment can be used to help solve some customer problems with paper curl or fuse quality on certain non-standard paper or unique run modes.

To adjust the fuser temperature:

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Fuser adjust

2 Select Normal, High, or Low. The default is Normal.

Toner patch sensor adjust

This setting allows you to calibrate or adjust the toner patch sensor settings.

To calibrate or adjust the toner patch sensor:

1 Enter the Diagnostics menu, and then navigate to:

Printer Setup > EP setup > Toner patch sensor adjust

2 Select a setting to adjust or calibrate.

Printer diagnostics and adjustments

Sensor tests

- 1 Enter the Diagnostics menu, and then select Printer diagnostics & adjustments.
- **2** From the Sensor tests section, select **Start**.

A list of sensor tests appears.

3 Find, and then manually toggle the sensor.

Notes:

- The sensor status on the screen toggles between **1** and **0** when the sensor is properly working.
- If a sensor test fails, the test failure may not indicate a failed sensor. Further troubleshooting may be required. Check the boards and cables for possible issues.
- For the fuser exit sensor actuator, toggle it toward the rear door.

List of sensor tests

| Test Control of the C |
|--|
| Tray 1 pick |
| Input |
| Redrive/Duplex path 1 |
| Output bin/Narrow media |
| Fuser exit |
| Door interlock |
| K Toner meter |

| est |
|--------------------|
| Conner meter |
| 1 Toner meter |
| Toner meter |
| ray present |
| PS L and R |
| Vaste Toner Bottle |

Motor tests

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Motor tests

2 Select a motor, and then press OK or touch **Start**.

Notes:

- If the motor is activated, then it is properly working.
- Some motors require automatic deactivation to avoid secondary issues such as possible damage and contamination.
- Some tests require a special action to activate a motor such as removing a major component.
- If the motor fails, the test failure may not indicate a failed motor. Further troubleshooting may be required. Check the boards and cables for possible issues.
- To stop a running motor in non-touch-screen printer models, press OK

List of motor tests

| Test |
|-----------------------|
| Pick (tray 1) picking |
| Pick (tray 1) duplex |
| Fuser (fusing) |
| Fuser (retracting) |
| CMY developer |
| K developer-transfer |
| Fan (main) |

Registration adjust

This setting lets you adjust the skew, margins, or perform a Quick Test.

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:
Printer diagnostics & adjustments > Registration adjust

2 Select a setting to adjust.

Color alignment adjust

This setting allows you to adjust the color alignments and to print or reset the default settings.

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:Printer diagnostics & adjustments > Color alignment adjust

2 Select a setting.

Supply reset

The setting resets the fuser and ITM counter values to zero.

For non-touch-screen printer models, press ok to navigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:
Printer diagnostics & adjustments > Supply reset

2 Select a setting, and then press OK or touch **Start**.

Add-on cards tests

This setting allows you to test the add-on cards installed on the printer.

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:
Printer diagnostics & adjustments > Add-on cards tests

2 Select a card.

Weather station

This setting lets you view the temperature and humidity reported by the weather station.

For non-touch-screen printer models, press ok to navigate through the settings.

- 1 Enter the Diagnostics menu, and then touch **Printer diagnostics & adjustments**.
- **2** From the Weather station section, press OK or touch **Start**.

Universal Override

This setting allows the user to feed custom media sizes to a Custom Media Tray.

For non-touch-screen printer models, press ok to navigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Universal Override

2 Select a setting to adjust.

Additional input tray diagnostics

Sensor tests

- 1 Enter the Diagnostics menu, and then select Additional input tray diagnostics.
- **2** From the Sensor tests section, press OK or touch **Start**. A dialog listing the sensor tests appears.
- **3** Find, and then manually toggle the sensor.

Notes:

- The sensor status on the screen toggles between **1** and **0** when the sensor is properly working.
- If a sensor test fails, the test failure may not indicate a failed sensor. Further troubleshooting may be required. Check the boards and cables for possible issues.

List of sensor tests

| Test |
|-------------------------|
| Pass-through (tray [x]) |
| Media out (tray [x]) |
| Media level (tray [x]) |
| Tray present (tray [x]) |
| MPF media present |

Motor tests

For non-touch-screen printer models, press on avigate through the settings.

1 Enter the Diagnostics menu, and then navigate to:

Additional input tray diagnostics > Motor tests

2 Select a motor, and then press OK or touch **Start**.

Notes:

• If the motor is activated, then it is properly working.

- Some motors require automatic deactivation in order to avoid secondary issues such as possible damage and contamination.
- Some tests require a special action to activate a motor such as removing a major component.
- If the motor fails, the test failure may not indicate a failed motor. Further troubleshooting may be required. Check the boards and cables for possible issues.

Configuration Menu

| Menu item | Description |
|--|--|
| USB Configuration USB PnP | Change the USB driver mode of the printer to improve its compatibility with a personal computer. |
| 1* 2 | Note: This menu item appears only in some printer models. |
| USB Configuration USB Speed | Set the USB port to run at full speed and disable its high-speed capabilities. |
| Full Auto* | Note: This menu item appears only in some printer models. |
| Tray Configuration Tray Linking Automatic* Off | Set the printer to link the trays that have the same paper type and paper size settings. |
| Tray Configuration Show Tray Insert Message Off Only for unknown sizes* Always | Show the Tray Insert message. |
| Tray Configuration Paper Prompts | Set the paper source that the user fills when a prompt to load paper appears. |
| Auto* Multipurpose Feeder Manual Paper | Note: The multipurpose feeder is available only in some printer models. |
| Tray Configuration Envelope Prompts | Set the paper source that the user fills when a prompt to load envelope appears. |
| Auto* Multipurpose Feeder Manual Envelope | Note: The multipurpose feeder is available only in some printer models. |
| Tray Configuration Action for Prompts Prompt user* Continue Use current | Set the printer to resolve paper- or envelope-related change prompts. |

| Menu item | Description |
|--|---|
| Reports Menu Settings Page Event Log Event Log Summary HealthCheck Statistics | Print reports about printer menu settings, status, and event logs. |
| Supply Usage And Counters Clear Supply Usage History | Reset the supply usage history, such as number of pages and days remaining, to the factory shipped level. |
| Supply Usage And Counters Reset Color Imaging Kit Counter | Reset the counter after installing a new color imaging kit. Note: This menu item appears only in some printer models. |
| Supply Usage And Counters Reset Maintenance Counter | Reset the counter after installing a new maintenance kit. |
| Supply Usage And Counters Tiered Coverage Ranges | Adjust the range for the amount of color coverage on the printed page. |
| Printer Emulations PPDS Emulation Off* On | Set the printer to recognize and use the PPDS data stream. |
| Print Configuration Black Only Mode Off* On | Print color content in grayscale. |
| Print Configuration Color Trapping Off 1 2* 3 4 5 | Enhance the printed output to compensate for misregistration in the printer. |
| Print Configuration Font Sharpening 0–150 (24*) | Set a text point-size value below which the high-frequency screens are used when printing font data. For example, if the value is 24, then all fonts sized 24 points or less use the high-frequency screens. |
| Device Operations Quiet Mode Off* On | Set the printer to operate in Quiet Mode. Note: Enabling this setting slows down the printer performance. |
| Device Operations Panel Menus Off On* | Enable access to the control panel menus. |

| Menu item | Description |
|--|---|
| Device Operations Custom Supply Levels Off* On | Let <i>printservice</i> read and edit values from the Embedded Web Server. |
| Device Operations Safe Mode Off* On | Set the printer to operate in a special mode, in which it attempts to continue offering as much functionality as possible, despite known issues. For example, when set to On and the duplex motor is nonfunctional, the printer performs one-sided printing for a two-sided print job. |
| Device Operations Clear Custom Status | Erase user-defined strings for the Default or Alternate custom messages. |
| Device Operations Clear all remotely-installed messages | Erase messages that were remotely installed. |
| Device Operations Automatically Display Error Screens Off On* | Show existing error messages on the display after the printer remains inactive on the home screen for a length of time equal to the Screen Timeout setting. |
| Device Operations Enable Optional Parallel Port Off* On | Enable an optional parallel port. Note: When set to On, the printer restarts. |
| Toner patch sensor setup Calibration frequency preference Disabled Fewest color adjustment Fewer color adjustment Normal* Better color accuracy Best color accuracy | Set the printer to put down the correct amount of toner to maintain color consistency. |
| Toner patch sensor setup Full calibration | Run the full color calibration. |
| Toner patch sensor setup Print TPS information page | Print a diagnostic page that contains information on toner patch sensor calibration. |
| App Configuration LES Applications Off On* | Enable the Lexmark Embedded Solutions (LES) applications. Notes: This menu item is available only in some printer models. When set to On, this setting does not affect built-in applications. |

Service Engineer menu

Entering the Service Engineer (SE) menu

To access the Service Engineer (SE) menu:

- **1** Turn on the printer.
- When the home screen appears, press * * 411 on the control panel.
 For 2-line control panels, press the right arrow button twice, press OK, and then press the left arrow button.

General SE

This setting allows you to save a log file to a USB drive.

Enter the Service Engineer (SE) menu, and then navigate to:

General SE > Capture Logs to USB Drive

Network SE

Enter the Service Engineer (SE) menu, and then touch Network SE.

Note: Use these settings as directed by the next level of support.

| Top level menu | Intermediate menu |
|----------------|--|
| Print SE Menus | Print SE Menus |
| History | Print HistoryMark History |
| MAC | Set Card SpeedLAAKeep Alive |
| NPAP | Print Alerts |
| TCP/IP | netstat arp Allow SNMP Set MTU Meditech Mode RAW LPR Mode |
| Wireless | Enable Wi-Fi Direct Sigma Control Agent |
| Ping Test | • Ping • Ping6 |

| Top level menu | Intermediate menu |
|----------------|---------------------------|
| Other Actions | • ifconfig |
| | IPtables [Firewall Dump] |
| | IP6tables [Firewall Dump] |
| | IPsec Dump |

Entering Invalid engine mode

This mode allows the printer to load the correct firmware code.

- **1** Turn off the printer.
- 2 From the control panel, press and hold the 3, 4, and 6 while turning on the printer.
- **3** Release the buttons after 10 seconds.

Entering Recovery mode

This mode allows the printer to boot from a secondary set of instructions and flash firmware code. While in this mode, you can only flash firmware code through a USB cable directly connected to a PC.

Depending on your printer model, do any of the following:


For LED display

- 1 Turn off the printer.
- **2** Open the front door.
- **3** Press and hold the **Stop** button.
- **4** Turn on the printer.
- **5** When all the icons flash, release the button.

For 2-line display


- 1 Turn off the printer.
- 2 Press and hold the OK and Back buttons.
- **3** Turn on the printer.

When the display shows the following icon, release the buttons.




For 2.4-, 4.3-, 7-, and 10-inch displays

- Turn off the printer.
- 2 Press and hold the 2, 7, and 8 buttons.
- Turn on the printer.
- When the display shows the following icon, release the buttons.



For 2.8-inch display

- Turn off the printer.
- 2 Open tray 1.
- Make sure that paper is loaded in tray 1.
- Turn on the printer.
- When the display shows the following icon, close tray 1.



Service menus

Note: If tray 1 is not closed, then the printer will boot normally.

 $\textbf{6} \ \ \textbf{A screen with red selection items appears}.$

Touch -> to navigate to Recovery mode.

7 Touch Boot or RECOVERY.

Parts removal

Data security notice

Identifying printer memory

- **Volatile memory**—The printer uses standard random access memory (RAM) to buffer user data temporarily during simple print and copy jobs.
- Nonvolatile memory—The printer may use two forms of nonvolatile memory: EEPROM and NAND (flash memory). Both types are used to store the operating system, printer settings, network information, scanner and bookmark settings, and embedded solutions.
- Hard disk memory—Some printers have a hard disk drive installed. The hard disk is designed for printer-specific functionality and cannot be used for long-term storage of data that is not print-related. The hard disk does not let users extract information, create folders, create disk or network file shares, or transfer FTP information directly from a client device. The hard disk can retain buffered user data from complex print jobs, form data, and font data.

The following parts can store memory:

- Printer control panel
- User interface controller card (UICC)
- Controller board
- Optional hard disks

Note: The printer control panel and controller board contain NVRAM.

Erasing printer memory

To erase volatile memory, turn off the printer.

To erase nonvolatile memory, do the following:

- 1 From the control panel, navigate to Settings > Device > Maintenance > Out of Service Erase > Sanitize all information on nonvolatile memory.
- 2 Select Sanitize all information on nonvolatile memory, and then select ERASE.
- **3** Follow the instructions on the screen.

To erase hard disk memory, do the following:

- 1 From the control panel, navigate to Settings > Device > Maintenance > Out of Service Erase > Sanitize all information on hard disk.
- 2 Select Sanitize all information on hard disk, and then select ERASE.
- **3** Follow the instructions on the screen.

Note: This process can take from several minutes to more than an hour, making the printer unavailable for other tasks.

If a hard disk is replaced, then do the following:

- **1** Remove the hard disk, and then return it to the customer.
- **2** Request the customer to sign the *Customer Retention* form.

Note: You can get printed copies of the form from your Lexmark partner manager.

- 3 Take a photo of the signed form, and then upload it to the Service Request debrief tool.
- 4 Fax or e-mail the signed form to the number or e-mail address shown at the bottom of the form.

Removal precautions



CAUTION—SHOCK HAZARD: The low-voltage power supply (LVPS) and the high-voltage power supply (HVPS) may have residual voltage present. To avoid the risk of electrical shock, do not touch their circuit components or the solder side of the board. Only handle them by their outer edges or metal housing.



CAUTION—SHOCK HAZARD: This product uses an electronic power switch. It does not physically disconnect the input AC voltage. To avoid the risk of electrical shock, always remove the power cord from the printer when removal of the input AC voltage is required.



CAUTION—SHOCK HAZARD: To avoid the risk of electrical shock and to prevent damage to the printer, remove the power cord from the electrical outlet and disconnect all connections to any external devices before you connect or disconnect any cable, electronic board, or assembly.



CAUTION—HOT SURFACE: The inside of the printer might be hot. To reduce the risk of injury from a hot component, allow the surface to cool before touching it.



CAUTION—PINCH HAZARD: To avoid the risk of a pinch injury, use caution in areas marked with this label. Pinch injuries may occur around moving parts, such as gears, doors, trays, and covers.

Précautions de retrait



ATTENTION—RISQUE D'ELECTROCUTION: Une tension résiduelle peut être présente dans le bloc d'alimentation basse tension (LVPS) et le bloc d'alimentation haute tension (HVPS). Pour éviter tout risque d'électrocution, ne touchez pas les composants du circuit ou le côté soudure de la carte. Tenez-les uniquement par leurs extrémités ou le boîtier en métal.



ATTENTION—RISQUE D'ELECTROCUTION: Ce produit utilise un commutateur d'alimentation électronique. Il ne déconnecte pas physiquement la tension d'alimentation CA. Pour éviter tout risque d'électrocution, débranchez toujours le cordon d'alimentation de l'imprimante lorsque vous devez déconnecter la tension d'alimentation CA.



ATTENTION—RISQUE D'ELECTROCUTION: Pour éviter tout risque d'électrocution et éviter d'endommager l'imprimante, débranchez le cordon d'alimentation de la prise électrique et déconnectez toute connexion à tout périphérique externe avant de brancher ou débrancher des câbles ou circuits et assemblages électroniques.



ATTENTION—SURFACE CHAUDE : L'intérieur de l'imprimante risque d'être brûlant. pour réduire le risque de brûlure, laissez la surface ou le composant refroidir avant d'y toucher.



ATTENTION : RISQUE DE PINCEMENT : Pour éviter tout risque de blessure par pincement, agissez avec précaution au niveau des zones signalées par cette étiquette. Les blessures par pincement peuvent se produire autour des pièces mobiles telles que les engrenages, portes, tiroirs et capots.

Precauciones durante la extracción



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: La fuente de alimentación de bajo voltaje (LVPS) y la fuente de alimentación de alto voltaje (HVPS) pueden presentar voltaje residual. Para evitar el riesgo de descarga eléctrica, no toque los componentes del circuito ni el lateral soldado de la placa. Manipule solo los bordes exteriores o la carcasa metálica.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Este producto utiliza un interruptor de corriente electrónico. No desconecta físicamente la entrada de voltaje de CA. Para evitar el riesgo de descarga eléctrica, desenchufe siempre el cable de alimentación de la impresora cuando sea necesario retirar la entrada de voltaje de CA.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Para evitar el riesgo de descargas eléctricas y daños en la impresora, retire el cable de alimentación de la toma eléctrica y desconecte todas las conexiones a dispositivos externos antes de conectar o desconectar cualquier cable, placa electrónica o conjunto.



PRECAUCIÓN: SUPERFICIE CALIENTE: El interior de la impresora podría estar caliente. Para evitar el riesgo de heridas producidas por el contacto con un componente caliente, deje que la superficie se enfríe antes de tocarlo.



PRECAUCIÓN: PELIGRO DE ATRAPAMIENTO: Para evitar el riesgo de lesión por atrapamiento, preste atención en las áreas marcadas con esta etiqueta. Las lesiones por atrapamiento se pueden producir en torno a partes móviles, tales como engranajes, puertas, bandejas y cubiertas.

Vorsichtsmaßnahmen bei der Demontage



VORSICHT – STROMSCHLAGGEFAHR: Im Niederspannungsnetzteil (LVPS) und Hochspannungsnetzteil (HVPS) liegt unter Umständen Restspannung vor. Um das Risiko eines elektrischen Schlags zu vermeiden, berühren Sie keine umliegenden Bauteile oder die Lötseite der Platine. Fassen Sie sie nur an den Außenkanten oder am Metallgehäuse an.



VORSICHT – STROMSCHLAGGEFAHR: Dieses Produkt verwendet einen elektronischen Leistungsschalter. Er trennt die Eingangswechselspannung nicht physikalisch. Um das Risiko eines elektrischen Schlags zu vermeiden, ziehen Sie stets das Netzkabel vom Drucker ab, wenn eine Abtrennung der Eingangswechselspannung erforderlich ist.



VORSICHT – STROMSCHLAGGEFAHR: Um das Risiko eines elektrischen Schlags und Schäden am Drucker zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose und trennen Sie alle Verbindungen zu jeglichen externen Geräten, bevor Sie Kabel, Elektronikplatinen oder Baugruppen einstecken oder abziehen.



VORSICHT – HEISSE OBERFLÄCHE: Das Innere des Druckers kann sehr heiß sein. Vermeiden Sie Verletzungen, indem Sie heiße Komponenten stets abkühlen lassen, bevor Sie ihre Oberfläche berühren.



VORSICHT – QUETSCHGEFAHR: Um das Risiko einer Quetschung zu vermeiden, gehen Sie in Bereichen, die mit diesem Etikett gekennzeichnet sind, mit Vorsicht vor. Quetschungen können im Bereich von beweglichen Komponenten auftreten, wie z. B. Zahnrädern, Klappen, Fächern und Abdeckungen.

Handling ESD-sensitive parts

To prevent damage to the electrostatic discharge (ESD)-sensitive parts in the printer, do the following:

- Turn off the printer before removing logic boards.
- Keep the parts in their original packing material until you are ready to install them into the printer.
- Make the least-possible movements with your body to prevent an increase of static electricity from clothing fibers, carpets, and furniture.
- Use the ESD wrist strap. Connect the wrist band to the system ground point. This action discharges any static electricity in your body to the printer.
- Hold the parts by their edge connector shroud. Do not touch its pins. If you are removing a pluggable module, then use the correct tool.
- If possible, keep all parts in a grounded metal cabinet.
- Do not place the parts on the printer cover or on a metal table. If you need to put down the parts, then put them in their packing material.
- Prevent parts from being accidentally touched by other personnel. Cover the printer when you are not working on it.
- Be careful while working with the parts when cold-weather heating is used. Low humidity increases static electricity.

Critical information for controller board or control panel replacement



CAUTION—POTENTIAL INJURY: The lithium battery in this product is not intended to be replaced. There is a danger of explosion if a lithium battery is incorrectly replaced. Do not recharge, disassemble, or incinerate a lithium battery. Discard used lithium batteries according to the manufacturer's instructions and local regulations.



ATTENTION—RISQUE DE BLESSURE: La batterie lithium de ce produit n'est pas destinée à être remplacée. Il existe un risque d'explosion si une batterie lithium est placée de façon incorrecte. Ne rechargez pas, ne démontez pas et n'incinérez pas une batterie lithium. Mettez les batteries lithium usagées au rebut selon les instructions du fabricant et les réglementations locales.



PRECAUCIÓN: POSIBLES DAÑOS PERSONALES: La batería de litio de este producto no debe reemplazarse. Existe riesgo de explosión si se sustituye incorrectamente una batería de litio. No recargue, desmonte ni incinere una batería de litio. Deseche las baterías de litio según las instrucciones del fabricante y las normativas locales.



VORSICHT – MÖGLICHE VERLETZUNGSGEFAHR Die Lithiumbatterie in diesem Produkt darf nicht ausgetauscht werden. Wird eine Lithiumbatterie nicht ordnungsgemäß ausgetauscht, besteht Explosionsgefahr. Lithiumbatterien dürfen auf keinen Fall wieder aufgeladen, auseinander genommen oder verbrannt werden. Befolgen Sie zum Entsorgen verbrauchter Lithiumbatterien die Anweisungen des Herstellers und die örtlichen Bestimmungen.

Warning—Potential Damage: Observe all precautions when handling ESD sensitive parts. See <u>"Handling ESD-sensitive parts" on page 220</u>.

Warning—Potential Damage: Carefully remove the cables and connectors. Make sure they are not damaged.

Warning—Potential Damage: To avoid NVRAM mismatch issues, replace only one of the following components at a time:

- Control panel
- Controller board

To replace a component and to test whether the problem is resolved:

- **1** Replace the affected component.
 - **Warning—Potential Damage:** Do not perform a Power-On Reset (POR) until the problem is resolved. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.
- 2 Enter the Diagnostics Menu. The Diagnostics Menu allows you to temporarily use the replacement part.
 - **Warning—Potential Damage:** Some printers will perform a POR automatically if the Diagnostics Menu is not opened within five seconds. If a POR is performed at this point, then the replacement part can no longer be used in another printer and must be returned to the manufacturer.
- 3 Use the Diagnostics Menu to test the replacement part. Do a feed test to check if the problem is resolved.
 - If the problem is not resolved—Turn off the printer, and then reinstall the old part.
 - If the problem is resolved—Perform a POR.
 - If NVRAM error occurs during the replacement, see <u>"950.xx NVRAM failure service check" on page</u> <u>149</u>.

Restoring the printer configuration after replacing the controller board

Restore the printer to its correct configuration to complete the replacement service. Use the Service Restore Tool to download the software bundle, and then flash the printer settings and embedded solutions.

Note: Perform this procedure only if the printer has an eSF application that is installed from the Virtual Solution Center, during manufacturing, or through customization. If you do not have access to Service Restore Tool, then contact your next level of support.


Note: The software bundle contains the latest version of the firmware, applications, and software licenses from the Lexmark Virtual Solutions Center (VSC). The printer firmware may be at a different level from what was used before replacing the controller board.

Using the Service Restore Tool


- **1** Go to https://cdp.lexmark.com/service-restore-tool/ to access the tool.
- **2** Log in using your Lexmark or partner login.

If your login fails, then contact your next level of support.

3 Enter the printer serial number, and then submit the information.




Note: Make sure that the serial number that appears on the verification screen is correct.



4 Save the zip file.


Note: Make sure that the serial number in the zip file matches the serial number of the printer being restored.



5 Extract the contents of the zip file, open the *Readme* file, and then follow the instructions in the file.

Notes:

- Perform the install instructions on the *Readme* file in the exact order shown. Restart the printer only if the file says so.
- For more information on how to flash the downloaded files, see "Updating the printer firmware" on page 225.
- To load the zip files that are extracted from the Service Restore Tool, see <u>"Restoring solutions, licenses, and configuration settings" on page 224</u>.



6 After performing the installation instructions in the *Readme* file, confirm from the customer if all the eSF apps have been installed.


Notes:

- If you are unable to access the administrative menus to verify that the printer is restored, then ask the customer for access rights.
- If a 10.00 error appears after you restart the printer, then contact the next level of support.


Restoring solutions, licenses, and configuration settings

To load the zip files that are extracted from the Service Restore Tool, do the following:


1 Open a web browser, and then type the printer IP address.



2 Click Import Configuration, and then click Browse.



3 Navigate to the folder where the zip files are extracted from the Service Restore Tool.



- 4 Select the file to import, and then click **Import**.
- **5** Repeat step 2 through step 4 for the other files that are included in the extracted zip file.

Updating the printer firmware

Warning—Potential Damage: Before updating the printer firmware, ask the next level of support for the correct code. Using an incorrect code level may damage the printer.

The printer must be in ready state in order to update the firmware.

Using a flash drive

This option is available only in printer models with front USB port.

Make sure to enable the Enable Drive and Update Code settings. You can find the settings in the Flash drive menu under the Settings menu.

- Insert the flash drive.
 The display lists the files on the thumbdrive.
- **2** Select the file that you need to flash.

Note: Do not turn off the printer while the update is going on.

Using a network computer

Using the File Transfer Protocol (FTP)

Make sure that the printer is in ready state before flashing.

- **1** Turn on the printer.
- 2 Obtain the IP address:
 - From the home screen
 - From the TCP/IP section of the Network/Ports menu
- 3 From the command prompt of a network computer, open an FTP session to the printer IP address.
- **4** Use a PUT command to place the firmware file on the printer.

 The printer performs a POR sequence and terminates the FTP session.
- **5** Repeat step 2 through to step 4 for the other files.

Using the Embedded Web Server

Make sure that the printer is in ready state before flashing.

- 1 Open a web browser, and then type the printer IP address.
- 2 From the home page, navigate to Configuration > Update Firmware.
- 3 Select the file to use.

The printer performs a POR sequence and terminates the FTP session.

4 Repeat step 2 through to step 4 for the other files.

Backing up eSF solutions and settings

Note: Export the eSF solutions and settings from the printer before replacing the controller board.

Exporting eSF solutions and settings file

- 1 Reset the printer into Invalid engine mode. See "Entering Invalid engine mode" on page 214.
- **2** Open a web browser, and then type the printer IP address.


Note: If the web page cannot be accessed or an error occurs when starting the printer into Invalid engine mode, then data backup is not an option. Inform the customer that the data cannot be saved.

- 3 Click Apps, click Export Configuration, and then select one of the options in the dropdown menu.
- 4 Click Export.

Note: The size limit of the export file is 128 KB.

Disconnecting ribbon cables

Warning—Potential Damage: The ribbon cable and its socket may get damaged if it is not properly disconnected. When disconnecting the cable, hold its connector and press its tab before unplugging it.



Ribbon cable connectors

Zero Insertion Force (ZIF) connectors

Zero Insertion Force (ZIF) connectors are used on the boards and cards used in this printer. Before inserting or removing a cable from these connectors, observe the following precautions.

Warning—Potential Damage: Do not insert the cable so that the contacts are facing the locking actuator. The contacts always face away from the actuator.

Warning—Potential Damage: Do not insert the cable diagonally into the ZIF socket. This action can damage the contacts on the cable.

Warning—Potential Damage: Avoid using a fingernail, or sharp object to open the locking mechanism. This action can damage the cable.

Warning—Potential Damage: Avoid pressing against the cable when opening the locking mechanism. This action can also damage the cable.

These are the types of ZIF connectors used in this printer:

- Horizontal top contact connector
- Horizontal bottom contact connector
- Vertical mount contact connector
- Horizontal sliding connector


Horizontal top contact connector

The horizontal top contact connector uses a back flip locking actuator to lock the ribbon cable into the Zero Insertion Force (ZIF) connector. The cable is inserted horizontally into the connector.

Warning—Potential Damage: When opening or closing this type of actuator, gently lift or close the two tabs located on each end of the actuator. The two tabs should be moved simultaneously. Do not close the actuator from the center of the actuator.

Removing a cable from the horizontal top contact connector

1 Place a finger at each end of the locking actuator, and then gently lift the actuator to the unlocked position.



2 Slide the cable out of the connector.


Inserting a cable into the horizontal top contact connector

1 When installing the cable, check the locking actuator to ensure it is in the unlocked position. The tabs on the ends of the actuator are vertical when the actuator is unlocked.




2 Insert the cable with the contacts on the cable facing up. Insert the cable on top of the actuator.

Note: Verify that the cable is installed squarely into the connector. If the cable is not squarely installed, then intermittent failures can occur.



Rotate the locking actuator to the locked position. The cable must not move while this step is performed. If the cable moves, open the actuator, reposition the cable, and then close the actuator to the down position.



Horizontal bottom contact connector

The horizontal bottom contact connector uses a flip locking actuator to lock the ribbon cable into the Zero Insertion Force (ZIF) connector. The cable is inserted horizontally into the connector.

Warning—Potential Damage: When opening or closing this type of actuator, gently lift the center of the actuator using your finger. Do not use a fingernail or screwdriver to open the actuator. This can damage the ribbon cable. Do not close the actuator from the ends of the actuator.

Removing a cable from the horizontal bottom contact connector

1 Place two fingers towards each end of the locking actuator, and then gently lift the actuator to the unlocked position.



2 Slide the cable out of the connector.

Inserting a cable into the horizontal bottom contact connector

1 Check the actuator to verify that it is in the open position.



2 Insert the cable into the ZIF connector with the contacts facing downward and away from the locking actuator. Insert the cable below the actuator.

Note: Verify that the cable is installed squarely into the connector. If the cable is not squarely installed, then intermittent failures can occur.



3 Place your finger in the middle of the actuator, and then rotate the locking actuator to the locked position.




Vertical mount contact connector

The vertical mount contact connector uses a back flip locking actuator to lock the ribbon cable into the Zero Insertion Force (ZIF) connector. The cable is inserted vertically into the connector.

Warning—Potential Damage: When opening or closing this type of actuator, gently lift the center of the actuator using your finger. Do not use a fingernail or screwdriver to open the actuator. This could damage the ribbon cable. Do not close the actuator from the ends of the actuator.

Removing a cable from the vertical mount contact connector

1 Gently rotate the locking actuator from the center of the actuator to the unlocked position.



Parts removal

2 Slide the cable out of the connector.

Inserting a cable into the vertical mount contact connector

1 When installing the cable, check the locking actuator to verify it is in the open position.




2 Insert the cable with the contacts on the cable away from the locking actuator. Insert the cable on top of the actuator.

Note: Verify that the cable is installed squarely into the connector. If the cable is not squarely installed, then intermittent failures could occur.



3 Rotate the locking actuator to the locked position by pressing down on both ends of the actuator. The cable must not move while this step is performed. If the cable moves, open the actuator, reposition the cable, and then close the actuator to the down position.




Horizontal sliding contact connector

The horizontal sliding contact connector uses a slide locking actuator to lock the ribbon cable into the Zero Insertion Force (ZIF) connector. The cable is inserted horizontally into the connector.

Warning—Potential Damage: When opening or closing this type of actuator, gently push or pull the two tabs located on each end of the actuator. Do not close the actuator from the center of the actuator. Do not use a screwdriver to open or close the actuator. Damage to the cable or connector could occur.

Removing a cable from the horizontal sliding contact connector


1 Simultaneously slide the two tabs on the ends of the locking actuator away from the connector.



2 Slide the cable out of the connector.

Inserting a cable into the horizontal sliding contact connector


1 When installing the cable, check the locking actuator to verify it is in the open position. If you are opening the connector, then pull back on both end tabs using equal force to avoid breaking the connector.



2 Insert the cable with the contacts on the cable facing away from the locking actuator. Insert the cable on top of the actuator.



Slide the locking actuator towards the connector, locking the cable into place. The cable must not move while this step is performed. If the cable moves, open the actuator, reposition the cable, and then close the actuator to the down position.




Low Insertion Force (LIF) connector

Warning—Potential Damage: When installing a cable into the LIF connector, make sure to avoid bending the edges of the cables and damaging the contacts on the cables.

Inserting a cable into the LIF connector

1 Looking at the connector, take note on which side the contacts are located. Many boards have the word contacts stamped on them to indicate which side of the LIF has the contacts. When looking at the board, take note that the contacts from the board to the connector are on the side of the connector with the contacts.



2 Insert the cable squarely into the connector.

Note: Verify that the cable is installed straight into the connector. If the cable is not installed properly, then intermittent failures could occur.



Adjustments

Registration adjustment

Image misalignments can occur after printhead replacement. Perform this procedure to correct the position of the image relative to the paper edges.

Note: You cannot perform mechanical registration or skew adjustments on this printhead.

Before performing the procedure, make sure that the tray guides are properly set and the paper settings on the printer match the paper size loaded in the tray.


Adjusting the skew

The skew adjustment changes the angle of the horizontal lines so that the lines can be aligned with the leading edge of the page. As the skew setting is changed, the top line on the test page stays in place at the left end, while its right end tilts up or down. All horizontal lines on the page will tilt at that same angle while the vertical lines will remain vertical. Changing the skew setting moves the right edge of the page up and down, and changes the angle of the top and bottom lines. If the skew is properly adjusted, the horizontal lines at the top of the page will be parallel to the leading edge of the page.

To check for skew:

- **1** Enter the Diagnostics menu, and then navigate to:
 - Printer diagnostics & adjustments > Registration adjust
- 2 Select Quick Test, and then press OK or touch Start.

The printer prints a test page.



Note: If there is no skew on the page, go to Adjusting the margins. See <u>"Adjusting the margins" on page 241</u>.

To adjust the skew:

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Registration adjust > Skew

2 Specify the value. The value range is from -100 to 100.

Notes:

- For 2-line LCD screens, use the left or right arrow buttons to increase or decrease the value.
- Raising the value of the skew rotates the horizontal lines clockwise. The left end of the line remains in the same place and the right end moves downward.
- Decreasing the value of the skew rotates the horizontal lines counterclockwise. The left end of the line remains in the same place and the right end moves upward.
- 3 Select OK.
- **4** Print a Quick test page to verify the change.
- **5** Repeat steps 1 to 4 until the horizontal line is properly aligned with the leading edge of the page.
- 6 Check for proper margin alignment. See "Adjusting the margins" on page 241.

Adjusting the margins

To check for proper margin alignment:


1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Registration adjust

2 Select **Quick Test**, and then press **OK** or touch **Start**.

The printer prints a test page.

3 Check the top and bottom margins of the test page for proper alignment.



To adjust the margins:

1 Refer to the test page, and then check the arrows along the margins.

Notes:

• The arrows should be completely visible along the edges.

- The tip of the arrows should point to the edges of the paper.
- **2** Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Registration adjust

- **3** Select the field of the margin to adjust.
- **4** Specify value. The value range is from -80 to 80.

Notes:

- For 2-line LCD screens, use the left or right arrow buttons to increase or decrease the value.
- Raising the value of the top margin setting pushes the top edge of the image downward.
- Raising the value of the bottom margin setting pushes the bottom edge of the image upward.
- Raising the value of the left margin setting pushes the left margin to the right.
- Raising the value of the right margin setting pushes the right margin to the left.
- **5** Select **OK**.
- **6** Print a Quick test page to verify the change.
- **7** Repeat step 3 through to step 6 until the margins are properly adjusted.
- 8 Check for proper color alignment. See "Adjusting the color alignment" on page 242.

Adjusting the color alignment

1 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Color alignment adjust

On the AA Adjustment row, press **OK** or touch **Start**.

Note: The Color alignment procedure is performed on the cyan, magenta, and yellow colors.

2 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Color alignment adjust > Cyan > Quick test

Check the alignment markings on the test page generated. Follow the instructions on the test page to correct the color misalignment.

3 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Color alignment adjust > Yellow > Quick test

Check the alignment markings on the test page generated. Follow the instructions on the test page to correct the color misalignment.

4 Enter the Diagnostics menu, and then navigate to:

Printer diagnostics & adjustments > Color alignment adjust > Magenta > Quick test

Check the alignment markings on the test page generated. Follow the instructions on the test page to correct the color misalignment.

5 If color misalignment still occurs, then repeat step 1 through to step 4.

Entering the TPS characterization data

After installing the new left or right TPS, access the Diagnostics menu to enter the 40-character string for the left or right sensor.

To enter the Diagnostics menu:

- For 7-, 4.3-, and 2.4-inch control panels, press * * 3 6.
- For 2-line control panel, press the left arrow button twice, press **OK**, and then press the right arrow button.

For 7-inch and 4.3-inch control panels

1 Enter the Diagnostics menu, and then navigate to:

Printer setup > EP setup > Toner patch sensor adjust

- 2 Touch Right TPS calibration data or Left TPS calibration data.
- **3** Enter the 40-character string for the sensor, and then touch **OK**.

For 2.4-inch control panel

1 Enter the Diagnostics menu, and then navigate to:

Printer setup > EP setup > Toner patch sensor adjust

- 2 Select Right TPS calibration data or Left TPS calibration data, and then press OK.
- **3** Press the backspace button to clear the field.
- **4** Enter the 40-character string for the sensor, and then press **OK**.

For 2-line control panel

1 Enter the Diagnostics menu, and then navigate to:

Printer setup > EP setup > Toner patch sensor adjust

- 2 Select Right TPS calibration data or Left TPS calibration data, and then press OK.
- **3** Press **X** to clear the field.
- **4** Press the right arrow button to enter the 40-character string for the sensor.

Notes:

- Press **OK** after each digit.
- Repeat step 4 for all 20 digits.

Installation notes:

- **a** After entering the data, perform a POR.
- **b** Enter Diagnostics menu, and then navigate to:

Printer setup > EP setup > Toner patch sensor adjust

- **c** Perform the **Sensor gain characterization**.
- **d** Perform the **Sensor gain verification**.

Note: Make sure that there are no red errors on the page.

e Perform a POR, and then perform the Full calibration. For more information, see the Service menus chapter.

Removal procedures

Keep the following tips in mind as you replace parts:


- Some removal procedures require removing cable ties. You must replace cable ties during reassembly to avoid pinching wires, obstructing the paper path, or restricting mechanical movement.
- Remove the toner cartridges, imaging kit, and trays before removing other printer parts. The imaging kit
 must be carefully set on a clean, smooth, and flat surface. It must also be protected from light while out of
 the printer.
- Disconnect all external cables from the printer to prevent possible damage during service.
- Unless otherwise stated, reinstall the parts in reverse order of removal.
- When reinstalling a part held with several screws, start all screws before the final tightening.
- For printers that have a soft power switch, make sure to unplug the power cord after powering off.

Left side removals


Left cover removal

- **1** Remove the tray insert.
- **2** Position the printer with the left side hanging over the edge of the table.

Remove the three screws (A).



4 Flex the cover slightly to unlatch the front bottom corner tab (B), and then remove the cover.




Installation note: When replacing the left cover, slightly flex the cover to engage the tab.

Motor (drive unit) removal

Note: The EP motors must be replaced in pairs.


- 1 Remove the left cover. See "Left cover removal" on page 244.
- **2** Disconnect the cable (A), remove the four screws (B), and then remove the motor.




EP drive assembly removal

- 1 Remove the left cover. See "Left cover removal" on page 244.
- 2 Remove the transfer module. See "Transfer module removal" on page 272.


3 Disconnect the cable (A).




- Disconnect the two cables from the motor (drive unit).
- Remove the cables from the clips on the EP drive assembly, and then remove the two screws (B).




6 Remove the screw (C).



7 Remove the two screws (D).




Remove the EP drive assembly.




LVPS removal


- Turn off the printer, and then unplug the power cord.
- 2 Remove the left cover. See "Left cover removal" on page 244.
- Disconnect the three cables (A).



4 Remove the seven screws (B), and then remove the LVPS.




Warning—Potential Damage: Make sure to set the switch (C) to the correct setting for your voltage requirements before installing the LVPS. The switch can be set to either 115 V or 230 V.




Sensor (fuser exit) removal


- 1 Remove the left cover. See "Left cover removal" on page 244.
- **2** Press to release the tabs (A), and then rotate the deflector to remove.




3 Remove the cable from its retainer (B).




4 Disconnect the cable (C).




5 Disconnect the cable (D).




6 Unhook the two springs (E) from both sides of the fuser.




Disconnect the two thermistor cables (F), and then remove the screw (G).



If the printer is an MFP, then remove the belt (H) from the pulley.




9 Rotate the fuser toward the front, disconnect the cable (I), and then remove the screw (J).



10 Using a flat-head screwdriver, remove the lower end of the sensor, and then gently pull the sensor from the frame.

Speaker (CS622) removal

- 1 Remove the control panel top cover. See <u>"2-line control panel top cover removal" on page 296, "2.4-inch control panel top cover removal" on page 297</u>, or <u>"4.3-inch control panel top cover removal" on page 299</u>.
- **2** Disconnect the cable (A), remove the two screws (B), and then remove the speaker.




Right side removals

Right cover removal

- **1** Open the toner supply door.
- **2** Open the front door.

Release the latches (A), and then remove the cover.




Toner supply door removal

- 1 Open the toner supply door.
- **2** Remove the screw (A), and then remove the door.





Motor (fuser drive) removal

- 1 Remove the right cover. See <u>"Right cover removal" on page 257</u>.
- **2** Disconnect the cable (A).




3 Remove the two screws (B), and then remove the motor.






TMC card removal

- 1 Remove the imaging kit. See "Imaging kit removal" on page 276.
- 2 Remove the rear cover. See "Rear cover removal" on page 343.
- **3** Disconnect the cable (A), and then push the TMC card cable through the frame opening. **Note:** Pay attention to the cable routing.



4 Remove the four screws (B).




5 Insert a flat-head screwdriver into the left side of the frame, and then pry the card loose to remove it.



Installation notes:

• Make sure to run the cable (C) through the retainer.




• The TMC card is a tight fit. Insert the bottom edge inside the frame first, and then push down on the top edge to clear the top cover.

Sensors (toner patch) removal

Note: The left and right sensors are separate FRUs.


- 1 Remove the transfer module. See "Transfer module removal" on page 272.
- 2 Remove the rear cover. See "Rear cover removal" on page 343.
- **3** Disconnect the three cables (A) from the controller board.



Notes:

- If you are removing the sensor (right toner patch), then disconnect the JTPS1 cable on the controller board.
- If you are removing the sensor (left toner patch), then disconnect the JTPS2 cable on the controller board.
- Pay attention to the cable routing.
- **4** Remove the screws at the bottom of the controller board to provide clearance for the cables.
- **5** Remove the two screws (B) from the left or right sensors.

Note: Only remove the screws from the sensor to be replaced.




6 Remove the sensor while carefully routing the cables through the rear of the controller board cage. **Installation note:** After installing the new sensors, make sure to enter the TPS characterization data. See **"Entering the TPS characterization data" on page 242**.

Developer unit removal

Note: The developer units are not FRUs.


- 1 Open the toner access door.
- **2** Remove the toner cartridges.



3 Remove the imaging kit. See "Imaging kit removal" on page 276.


Warning—Potential Damage: Do not touch the underside of the imaging kit.

Remove the developer unit.



HVPS removal


- Turn off the printer, and then unplug the power cord.
- 2 Remove the rear cover. See "Rear cover removal" on page 343.
- Remove the cable cover (A), and then disconnect the HVPS cable (B).



4 Tuck the HVPS cable in.




- **5** Remove the transfer module. See <u>"Transfer module removal" on page 272</u>.
- 6 Remove the screw (C).




7 Remove the left cover. See "Left cover removal" on page 244.

Press down and hold the three transfer module contacts.




9 While pressing down on the contacts, press down on the spring mount, and then carefully slide out the HVPS by pulling from one side and pushing from the other.



- Release the pressure on the spring mount, and then pull and slide out the HVPS to remove it.
- Disconnect the cable (D) from the HVPS board.

Warning—Potential Damage: After disconnecting the HVPS cable from the controller board, make sure that the HVPS connector is not damaged.






Installation notes:

a To install the new HVPS board, insert the spring end of the HVPS board while compressing the spring, as shown below.






b Hold the HVPS on both sides, and then slide the it into position.

Warning—Potential Damage: Do not flex the HVPS board, and do not let it touch the cage.






c Hold the HVPS below the contacts, and then slide it in.





d Check the position of the card at the left side of the printer. The small vertical post (E) in the endcap has to be positioned in the hole above it, as show below.



e Install the new cable, making sure the connector to the board is locked into position.


Note: Reinstall the screw to hold the HVPS to the right side of the printer.

Transfer module removal


Note: For a video demonstration, see <u>Transfer module removal</u>.

- 1 Remove the right cover. See "Right cover removal" on page 257.
- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 3 Remove the imaging kit. See "Imaging kit removal" on page 276.


Disconnect the spring (A) on the right side.




Release the left and right door straps (B).



6 Disconnect the spring (C).




7 Raise the cam (D) and spring (E).



8 Place the tip of a flat-head screwdriver in between the release lever (F) and the frame, and then rotate the screwdriver to rotate the release lever and decouple the transfer module while pulling it toward the front.

Warning—Potential Damage: Make sure that the lever is in the fully released position before removing the transfer module.




- Hold the release lever as you pull out the transfer module for the first four inches (100 mm). A quick and firm pull should overcome the latch at this point.
- Remove the transfer module.



Installation notes:

- **1** Do not rotate the release lever again to install the new transfer module. Doing so could cause the transfer module to be seated incorrectly. The coupler is rotated out of the way as the transfer module slides in.
- **2** Rotate the right side spring clamp (G) and left side cam back to their original positions, and then rehook the springs.



3 Make sure to reset the ITM counter after installing the new transfer module. Enter the diagnostics menu and navigate to:

Printer diagnostics & adjustments > Supply reset > ITM reset


Imaging kit removal

Note: This is not a FRU.


Installation note: The imaging kit contains the photoconductor unit and developer units. When you replace the imaging kit, you are replacing the photoconductor unit and developer units.

- 1 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- **2** Remove the toner cartridges.

3 Lift the two latches (A) to unlock the imaging kit.




4 Pull the two latches.



5 Press and hold the two handles (B) and the latch (C), and then pull the imaging kit to remove.

Note: Do not touch the underside of the imaging kit.




Toner cartridge contacts removal


- 1 Remove the right cover. See "Right cover removal" on page 257.
- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- **3** Remove the imaging kit. See "Imaging kit removal" on page 276.
- 4 Remove the rear cover. See "Rear cover removal" on page 343.
- **5** Remove the screw (A) to allow access to the cable cover.

Note: Do not remove the waste toner bottle contact block.

Remove the four screws (B), and then remove the cable cover.




- Place the printer on its left side.
- Remove the screw (C), and then release the two tabs (D).



Slide the toner cartridge contacts to the left to remove it.

10 Disconnect the cable (E) from the controller board.



Installation note: If used, pay attention to the assembly of the cable and toroid.


- **11** Remove the cable from its retainer at the bottom of the printer.
- **12** Extract the cable through the frame, and then remove the cable with the spring contacts.

Note: If the cable has a toroid, unwrap the cable from the toroid, and then make sure to use the same number of wraps on the new cable.

Waste toner bottle removal

Note: This is not a FRU.


- 1 Remove the right cover. See "Right cover removal" on page 257.
- **2** Press the two tabs (A) to release the waste toner bottle.




Waste toner bottle contact block removal

Note: The waste toner bottle is not a FRU.


- 1 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 2 Remove the rear cover. See "Rear cover removal" on page 343.
- **3** Remove the screw (A).



4 Disconnect the cable (B) from the controller board, and then remove the toroid from the cable. **Installation note:** Use the toroid on the new waste toner bottle contact block.




Remove the waste toner bottle contact block.




Front removals

Front door removal


- Remove the tray insert.
- Open the front door.
- Remove the six screws (A).




4 Remove the three screws (B).




- Remove the cable cover from the right hinge.
- Disconnect the left and right door straps.







Route the interlock switch cover assembly away from the door.



Remove the six screws (C).




Pull the control panel assembly and base to the side.




Remove the wireless card. See "Wireless card removal" on page 306.

Remove the left hinge (D) from the left subframe.




Remove the right hinge (E) from the right subframe.




Front door inner deflector removal

- Open the front door.
- Release the two door straps (A) from the frame.




Remove the nine screws (B), and then remove the deflector.




Interlock switch cover assembly removal

- **1** Remove the tray insert.
- **2** Open the front door.
- **3** Remove the six screws (A).




4 Remove the three screws (B).



- **5** Remove the right cover. See **"Right cover removal" on page 257**.
- 6 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 7 Remove the rear cover. See "Rear cover removal" on page 343.
- **8** Remove the waste toner bottle contact block. See <u>"Waste toner bottle contact block removal" on page 281</u>.
- **9** Remove the cable cover.

10 Disconnect the cable (C).




11 Route the interlock switch cover assembly out of the frame.

Control panel base removal

- **1** Remove the tray insert.
- **2** Open the front door.
- 3 Remove the control panel top cover. See <u>"2-line control panel top cover removal" on page 296, "2.4-inch control panel top cover removal" on page 297</u>, or <u>"4.3-inch control panel top cover removal" on page 299</u>,

4 Remove the six screws (A), and then remove the cover.




2-line control panel badge cover removal

Remove the badge cover (A) from the bezel.



2.4-inch control panel badge cover removal

Remove the badge cover (A) from the bezel.




4.3-inch control panel badge cover removal

Remove the badge cover (A) from the bezel.




2-line control panel bezel removal

- 1 Remove the control panel top cover. See <u>"2-line control panel top cover removal" on page 296</u>.
- 2 Remove the four screws (A).




3 Remove the five screws (B), and then remove the bezel.




2.4-inch control panel bezel removal

- 1 Remove the badge cover. See <u>"2.4-inch control panel badge cover removal" on page 291</u>.
- 2 Remove the control panel top cover. See <u>"2.4-inch control panel top cover removal" on page 297</u>.

3 Remove the six screws (A) securing the bezel to the control panel top cover.




4 Remove the five screws (B) securing the control panel assembly.




4.3-inch control panel bezel removal

- 1 Remove the badge cover. See <u>"4.3-inch control panel badge cover removal" on page 291</u>.
- 2 Remove the control panel top cover. See <u>"4.3-inch control panel top cover removal" on page 299</u>.

Remove the four screws (A), and then remove the control panel assembly.



Remove the two screws (B), and then detach the bezel from the control panel top cover.




Installation note: Before installing the new bezel, make sure that the control panel display is properly seated in the tabs (C).




2-line control panel assembly removal

- 1 Remove the control panel top cover. See <u>"2-line control panel top cover removal" on page 296</u>.
- **2** Remove the four screws (A), and then remove the control panel assembly.




2-line control panel top cover removal

1 Remove the two screws (A) securing the interlock cover assembly, and then move the cover assembly to the side.




2 Remove the seven screws (B).




3 Disconnect the control panel cable.

4 Remove the five screws (C).




2.4-inch control panel top cover removal


- **1** Open the front door.
- **2** Remove the two screws (A) securing the interlock cover assembly, and then move the cover assembly to the side.



3 Remove the seven screws (B).




4 Disconnect the control panel ribbon cable (C.), and then remove the USB cable (D).




5 Remove the control panel bezel with the control panel assembly. See <u>"2.4-inch control panel bezel removal" on page 292.</u>

4.3-inch control panel top cover removal


- **1** Open the front door.
- **2** Remove the two screws (A) securing the interlock cover assembly, and then move the cover assembly to the side.



3 Remove the seven screws(B).



Push the two tabs (C), and then remove the keypad cover.







Remove the clip (D), and then remove the headphone cable.



Disconnect the speaker cable (E).




7 Disconnect the control panel power and ribbon cables (F).




8 Remove the control panel bezel with control panel assembly. See <u>"4.3-inch control panel bezel removal"</u> on page 293.

2.4-inch control panel keypad removal

- 1 Remove the 2.4-inch control panel. See <u>"2.4-inch control panel bezel removal" on page 292</u>.
- 2 Remove the six screws (A).




3 Disconnect the cable (B).




Weather station removal


- 1 Remove the right cover. See <u>"Right cover removal" on page 257</u>.
- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- **3** Remove the five screws (A), and then remove the cover (B).




4 Open the front door.

Release the left and right door straps.






Remove the left hinge (C) from the left subframe.



Remove the right hinge (D) from the right subframe.




8 Remove the screw (E), and then disconnect the cable (F) from the sensor.




Wireless card removal


- **1** Remove the tray.
- 2 Remove the six screws (A).



Remove the three screws (B).




Disconnect the cable from the wireless card (C).




Front USB cable removal

- Open the front door.
- Remove the tray insert.
- 3 Remove the rear cover. See "Rear cover removal" on page 343.
- Remove the right cover. See **"Right cover removal" on page 257**.
- **5** Remove the waste toner bottle. See <u>"Waste toner bottle removal" on page 280</u>.


Remove the six screws (A).




Remove the three screws (B).




8 Remove the five screws (C).




9 Disconnect the cable (D).




Remove the seven screws (E).



11 Route the USB cable through the rear of the printer, and then through the control panel base.






Fuser removal


Note: For a video demonstration, see **Fuser removal**.

- 1 Remove the right cover. See "Right cover removal" on page 257.
- 2 Remove the left cover. See "Left cover removal" on page 244.
- 3 Disconnect the two-wire fuser cable (A) from the LVPS.
- **4** Position the fuser cable so that it can be pulled through from the front of the printer, and guide the cable through to the front.


Warning—Potential Damage: Be careful not to damage the cable by pulling too hard or cutting the cable insulation.



- **5** Remove the narrow media/exit sensor flag. See "Narrow media/bin full sensor flag removal" on page 352.
- 6 Remove the right out put bin deflector. See "Right output bin deflector removal" on page 354.
- 7 Remove the exit deflector. See "Exit deflector removal" on page 314.
- **8** Disconnect the cable (C) from the bin-full/narrow media sensor, and unroute the cable from its retainer.




9 Unhook the springs (D) from both sides of the fuser.



Parts removal

- Disconnect the thermistor cables (E), and then pull them over the retainer.
- Remove the screw (F).




12 Rotate the top of the fuser toward the front, and then slide to the left to align the fuser side frames with the flat area of the shaft.

Warning—Potential Damage: Do not damage the sensor (fuser exit) on the left of the fuser when rotating.

Lift, and then remove the fuser.

Installation notes:

a Install the flags (A) from the old fuser into the new fuser.




- b Enter the Diagnostics menu, and then navigate to:Printer diagnostics & adjustments > Supply Reset > Fuser Reset
- c Select Start.
- **d** Print approximately 15 test pages in simplex and duplex modes to make sure that the belt is properly working and the flags are properly installed.
- **e** Pay attention to noise that may indicate an improper belt installation.
- **f** If a **Remove media from output bin** or a 34.04 error appears, check the fuser flags for proper installation.


Exit deflector removal

- **1** Open the front door.
- **2** Remove the yellow toner cartridge.
- **3** Remove the exit deflector ground screw (A), and then remove the cable from its retainers.

Note: Be sure to pay close attention to the routing of the cables through the retainers for reinstallation.



Press to release the tabs (B), and then rotate the deflector to remove.




Bottom removals


Pick tires removal

Warning—Potential Damage: Remove only the rubber tires and not the paper pick tire assembly to avoid losing small parts.

- **1** Lower the paper pick motor drive assembly.
- **2** Remove the rubber tire (A) from the pick roll assembly (B). Repeat for the other tire.



Installation note: Install the new rubber tires with the surface texture turning in the direction as shown in the following:




Note: Feel each rubber surface to verify that it turns in the proper direction. The smoother surface pushes the paper toward the front of the printer.

Lower left frame removal


Note: The right and left lower frames are in the same FRU.

1 Remove the media tray, and remove the screw (A) from the front.




- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 3 Remove the imaging kit. See "Imaging kit removal" on page 276.
- 4 Remove the left cover. See "Left cover removal" on page 244.

Disconnect the three cables (B) from the LVPS.




6 Remove the two screws (C).




7 Position the fuser cable (D) so that it can be pulled through from the front of the printer, and then guide the cable through the front.


Warning—Potential Damage: Do not to damage the cable by pulling too hard or cutting the cable insulation.




- **8** Remove the narrow media/exit sensor flag. See <u>"Narrow media/bin full sensor flag removal" on page 352</u>.
- **9** Disconnect the ground wire (E) from the front toner cover bracket, and then route it to the front of the printer.




10 Release the tabs (F), and then rotate the exit deflector to remove.



- 11 Remove the right out put bin deflector. See "Right output bin deflector removal" on page 354.
- **12** Disconnect the cable (G) from the bin-full/narrow media sensor, and then remove the cable from its retainer.




13 Unhook the two springs (H) from both sides of the fuser.




14 Disconnect the two cables (I), and then pull them over the retainer.

Remove the screw (J).



Remove the two screws (K).



17 Rotate the top of the fuser toward the front, and then slide the fuser to the left to align the fuser side frames with the flat area of the shaft.


18 Disconnect the fuser exit sensor cable (L).




19 Lift the front left corner of the top cover, and then tilt the LVPS cage (M) to remove the cage.

Notes:


- There are two posts at the bottom of the cage on the left side that need to be disengaged.
- Pay attention to the sensor (fuser exit) which remains with the cage.




- **20** Place the printer on its right side.
- 21 Remove the connector (N).



22 At the rear of the printer, remove the five screws (P).




- **23** Remove the AC receptacle from the left lower frame.
- 24 Remove the three screws (Q).




25 Tilt the front door down, disconnect the left and right door straps, and then separate the door from the frame.

26 Remove the screw (R).




27 Swing the left lower frame away from the printer to remove.



Lower right frame removal


- **1** Remove the tray insert.
- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 3 Remove the imaging kit. See "Imaging kit removal" on page 276.

4 Remove the screw (A), and then remove the four screws (B).




Notes:


- Do not unplug the waste toner bottle sensor contact.
- The cable cover is part of the lower right frame.
- **5** Place the printer on its left side.
- 6 Remove the four screws (C).




Lift the lower right frame pin (D) out of the hole on the printer frame.




Remove the sensor retainer plate (E).




Remove the sensor, and then disconnect the cable (F).




Swing the rear part away from the printer, and then remove the spring (G).



Disconnect the cable (H).




- Swing the rear of the lower right frame away from the printer to remove it.
- **13** From inside the lower right frame, remove the screw (I), and then remove the spring bracket.



Parts removal

14 Disconnect the cable (J), remove the screw (K), and then remove the sensor (L).




Installation notes:


- **a** Reinstall the spring bracket and the weather station.
- **b** Before installing the lower right frame, connect the cable to the sensor (tray present), and then put the spring in place.
- **c** Install the weather station on the new lower right frame.

Sensor (duplex) removal


- 1 Remove the imaging kit. See "Imaging kit removal" on page 276.
- **2** Remove the two screws (A).




3 Pull the corner of the cable cover (B) away from the right side to access the two sensor posts (C).



4 Remove the sensor plate (D).



- **5** Press on the latches to detach the sensor from the printer frame.
- 6 Disconnect the cable (E).



Installation notes:

a Clean the contact surface where the sensor retaining plate was removed before installing the new sensor.


Note: Make sure that the clamps on the sensor legs are securely attached to the printer frame.

b Remove the backing from the new sensor retaining plate, and then place the plate on the surface between the sensor mounting latches.

Transfer module guide removal

- **1** Remove the tray insert.
- 2 Remove the right cover. See "Right cover removal" on page 257.
- 3 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.

- 4 Remove the imaging kit. See "Imaging kit removal" on page 276.
- **5** Remove the transfer module. See <u>"Transfer module removal" on page 272</u>.
- 6 Remove the fuser. See "Fuser removal" on page 311.
- 7 Remove the left cover. See "Left cover removal" on page 244.
- 8 Remove the LVPS. See "LVPS removal" on page 250.
- 9 Remove the lower right frame. See "Lower right frame removal" on page 328.
- **10** Remove the screw (A).




11 Remove the two screws securing the transfer module guide to the frame.

Note: Use either a short #2 Phillips or a right angle screwdriver.




12 Remove the spring (B).

Note: Pay attention to how the spring is attached to the bail.




13 Using a spring hook or screwdriver, press and hold the transfer module drive coupling (C), and then tilt the guide up from the side with the screw holes to remove it.




Sensor (tray present) removal

- 1 Remove the imaging kit. See "Imaging kit removal" on page 276.
- **2** Remove the screw (A) securing the waste toner bottle sensor contact to access the cable cover.
 - **Note:** Do not unplug the waste toner bottle sensor contact.
- **3** Remove the four screws (B), and then remove the cable cover.



4 Remove the lower right frame. See "Lower right frame removal" on page 328.

5 Remove the sensor retaining plate (C), and then press on the latches together to remove the sensor.



6 Disconnect the sensor cable.


Installation notes:

- **a** Clean the contact surface where the sensor retaining plate was removed before installing the new sensor.
- **b** Remove the backing from the new sensor retaining plate, and then place the plate on the surface between the sensor mounting latches.
- **c** Connect the cable to the sensor.
- **d** Replace the spring.


Tray 1 media feeder removal

- 1 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 2 Remove the imaging kit. See "Imaging kit removal" on page 276.
- **3** Remove the left cover. See "Left cover removal" on page 244.
- 4 Remove the rear cover. See "Rear cover removal" on page 343.
- **5** Disconnect the cable (A) from the JSP1 connector on the controller board.


Route the cable through the opening (B), and then remove the cable from its retainer (C).



- Partially reinstall the rear cover to protect the controller board.
- $\boldsymbol{8}\,\,$ Place the printer on its rear, and then remove the two screws (D).



9 On the right side, loosen the screw (E) with a screwdriver, and then remove it while holding the paper feed roller assembly.





10 Move the right side of the paper feed roller assembly out to free the shaft from the opening in the frame.

Note: Pay attention to the location of the shaft and the opening in the frame.

11 Remove the paper feed roller assembly.

Installation notes:

- **a** Place the left side of the paper feed roller assembly in the printer. Make sure that the shaft on the left side aligns with the hole in the frame.
- **b** Reinstall the three screws holding the paper feed roller assembly to the printer.
- **c** Place the printer on the upright position.
- **d** Reroute the cable, and then make sure to secure the cable in its retainer on the left side.
- e Remove the rear cover, and then reconnect the cable on the controller board.
- **f** Replace the rear cover.


Rear side removals

System fan removal

- 1 Remove the rear cover. See <u>"Rear cover removal" on page 343</u>.
- 2 Remove the left cover. See "Left cover removal" on page 244.
- **3** Disconnect system fan cable from the controller board.
- 4 Remove the two screws (A).




Detach the fan.



Lift, and then remove the fan.

Rear cover removal


Remove the eight screws (A).



2 Swing the cover out, and then slide to the right to remove.



Installation note: When installing the rear cover, make sure that the latch (C) is inserted into the bracket (B).



Controller board removal

Note: Back up the eSF solutions and settings before replacing the controller board. See <u>"Backing up eSF</u> solutions and settings" on page 226.

Warning—Potential Damage: After disconnecting the HVPS cable from the controller board, make sure that the HVPS connector is not damaged.


Warning—Potential Damage: Observe all precautions when handling ESD-sensitive parts. See <u>"Handling ESD-sensitive parts"</u> on page 220.

Warning—Potential Damage: Perform a POR after replacing one of the following components. Do not replace both components without performing a POR after installing each one.

- UICC
- Controller board


Warning—Potential Damage: Do not install and remove the components listed above as a method of troubleshooting components. After one of these components is installed in the printer and the printer is powered on, the component cannot be used in another printer. The component must be returned to the manufacturer.

- 1 Remove the rear cover. See "Rear cover removal" on page 343.
- **2** Disconnect all the cables from the controller board.
- **3** Remove the six screws (A).



4 Remove all the USB ground clips (B) from the USB connectors.

Note: Do not lose the ground clips. They will be used on the new controller board.




Installation note: Perform the printhead registration and alignment. See <u>"Registration adjustment" on page 240</u>.

Top side removals

Top cover removal


- 1 Remove the right cover assembly. See "Right cover removal" on page 257.
- 2 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 3 Remove the imaging kit. See "Imaging kit removal" on page 276.
- 4 Remove the rear cover. See "Rear cover removal" on page 343.

5 Disconnect the fan cable from JFAN1 (A) on the controller board, and then remove the screw (B).




6 Remove the two screws (C), and then remove the ground cable from the cover.

7 Lift the paper stop, and then remove the screw (D).




- 8 Remove the right output bin deflector. See "Right output bin deflector removal" on page 354.
- **9** Remove the narrow media/bin full sensor flag. See <u>"Narrow media/bin full sensor flag removal" on page 352</u>.


10 Remove the two screws (E).



11 Remove the four screws (F), and then remove the fuser screw (G).



12 Push in on the cover above the locating pins (H) while lifting to disconnect the cover.




13 Carefully lift the cover while keeping it horizontal, and then guide the fan connector through the opening.


Sensor (narrow media/output bin full) removal

- **1** Open the front door.
- **2** Remove the cable (A) from its retainer, and then disconnect it.

Installation note: Pay attention to the cable routing.



3 Remove the sensor retaining plate (B), and then pinch the four latches (C) to remove the sensor.




Installation notes:

- Clean the contact surface where the sensor retaining plate was removed before installing the new sensor.
- Guide the latches that hold the sensor to the bracket.
- Squeeze the latches together until they latch to the frame.
- Remove the backing from the new sensor retaining plate, and then place the plate on the surface between the sensor mounting legs.
- Reconnect the cable, and then guide the cable through its retainer.

Narrow media/bin full sensor flag removal

- **1** Open the front door.
- **2** Push up on the tab to release the flag, and then remove it.




Note: Be careful not to dislodge the sensor. The flag must be installed on the fuser while the fuser is out.


Printhead removal

- 1 Remove the rear cover. See "Rear cover removal" on page 343.
- **2** Remove the top cover. See <u>"Top cover removal" on page 346</u>.

Disconnect the two cables (A).




Remove the three screws (B), and then remove the printhead.



Installation note: Make sure to perform the registration adjustments after replacing the printhead. See **"Registration adjustment" on page 240**.

Right output bin deflector removal

- **1** Open the front door.
- 2 Remove the deflector (A).



Options removals

- "650-sheet duo tray insert removal" on page 355
- "650-sheet duo tray removal" on page 356
- "Dust cover removal" on page 357
- "Pick tire removal" on page 358

650-sheet duo tray insert removal

Pull out to remove the tray insert.



650-sheet duo tray removal


Warning—Potential Damage: Make sure that the printer is turned off before removing the tray.

- **1** Carefully lift the printer, and set it aside on a flat surface.
- **2** Remove the tray.




Dust cover removal

- 1 Slightly raise the dust cover.
- **2** Pull the dust cover to remove.




Pick tire removal

- **1** Remove the drawer tray insert.
- **2** Lower the auto compensator mechanism (A).



3 Remove the rubber tires (B) from the pick roll assembly (C). Repeat for the other tire (D).



Installation note: Install the new rubber tire with its surface texture turning in the direction as shown.



Note: Feel each rubber surface to verify it turns properly in the direction shown.

Component locations

Printer configurations



| 1 | Control panel |
|---|---|
| | Note: The appearance may vary depending on your printer model. |
| 2 | Standard bin |
| 3 | Standard 250-sheet tray |
| 4 | Manual feeder |
| 5 | Optional 650-sheet duo tray |
| | Note: This tray is available only in CS421, CS521, CS622, C2425, and C2535 printer models. |
| 6 | Optional 550-sheet tray |
| | Note: This tray is available only in CS521, CS622, and C2535 printer models. |

Controller board connectors

| Connector | Connects to | Pin no. | Signal |
|-----------|-------------------------------|---------|-------------------------|
| JCTM1 | Cartridge toner metering card | 1 | +5V_SW |
| | | 2 | Cartridge Meter C |
| | | 3 | Cartridge Meter M |
| | | 4 | Cartridge Meter Y |
| | | 5 | Cartridge Meter K |
| | | 6 | GND |
| JMIRR1 | Printhead mirror motor card | 1 | Mirror Mtr REF Clock |
| | | 2 | Mirror Mtr Lock Signal |
| | | 3 | Mirror Mtr Start Signal |
| | | 4 | GND |
| | | 5 | +25V |

| Connector | Connects to | Pin no. | Signal |
|-----------|------------------------|---------|-------------|
| JUICC24 | 2.4-inch control panel | 1 | LED_DRV_YLW |
| | | 2 | +6.5V |
| | | 3 | GSPI_TXD |
| | | 4 | MIR_SPI_CS- |
| | | 5 | PWR_BUTTON |
| | | 6 | LCD_RS |
| | | 7 | LCD_TE |
| | | 8 | GSPI_RDX |
| | | 9 | SRDYBLE |
| | | 10 | GSPI_CLK |
| | | 11 | GND |
| | | 12 | I2C1_DATA |
| | | 13 | I2C1_CLK |
| | | 14 | NFC_nCS |
| | | 15 | UI_RESET- |
| | | 16 | UI_IRQ- |
| | | 17 | GND |
| | | 18 | LCD_WR |
| | | 19 | LCD_RD |
| | | 20 | +5VL |
| | | 21 | LCD_D0 |
| | | 22 | LCD_D1 |
| | | 23 | GND |
| | | 24 | LCD_D2 |
| | | 25 | LCD_D3 |
| | | 26 | +5VL |
| | | 27 | LCD_D4 |
| | | 28 | LCD_D5 |
| | | 29 | GND |
| | | 30 | LCD_D6 |
| | | 31 | LCD_D7 |
| | | 32 | +5VL |

| Connector | Connects to | Pin no. | Signal |
|-----------|------------------------|---------|---------------|
| JUICC43 | 4.3-inch control panel | 1 | LED_DRV_YLW |
| | | 2 | +6.5V |
| | | 3 | GSPI_TXD |
| | | 4 | MIR_SPI_CS- |
| | | 5 | PWR_BUTTON |
| | | 6 | NFC_nCS |
| | | 7 | SRDYBLE |
| | | 8 | GSPI_RDX |
| | | 9 | +5VL |
| | | 10 | GSPI_CLK |
| | | 11 | GND |
| | | 12 | I2C1_DATA |
| | | 13 | I2C1_CLK |
| | | 14 | +5VL |
| | | 15 | UI_RESET- |
| | | 16 | UI_IRQ- |
| | | 17 | GND |
| | | 18 | LCD_LVDS_D3+ |
| | | 19 | LCD_LVDS_D3- |
| | | 20 | +5VL |
| | | 21 | LCD_LVDS_CLK+ |
| | | 22 | LCD_LVDS_CLK- |
| | | 23 | GND |
| | | 24 | LCD_LVDS_D2+ |
| | | 25 | LCD_LVDS_D2- |
| | | 26 | +5VL |
| | | 27 | LCD_LVDS_D1+ |
| | | 28 | LCD_LVDS_D1- |
| | | 29 | GND |
| | | 30 | LCD_LVDS_D0+ |
| | | 31 | LCD_LVDS_D0- |
| | | 32 | +5VL |

| Connector | Connects to | Pin no. | Signal |
|-----------|----------------------|---------|----------------------|
| JPH1 | Printhead laser card | 1 | LADJ_D4 |
| | | 2 | I2C Data |
| | | 3 | +3.3V |
| | | 4 | I2C Clock |
| | | 5 | GND |
| | | 6 | SHADE_Y |
| | | 7 | LADJ_D2 |
| | | 8 | SHADE_C |
| | | 9 | LENA_CMY- |
| | | 10 | LPOW_Y |
| | | 11 | GND |
| | | 12 | LPOW_C |
| | | 13 | BOOST |
| | | 14 | SHADE_M |
| | | 15 | LADJ_D1 |
| | | 16 | SHADE_K |
| | | 17 | +5V_PH |
| | | 18 | LPOW_M |
| | | 19 | GND |
| | | 20 | LPOW_K |
| | | 21 | LENA_K- |
| | | 22 | Printhead Thermistor |
| | | 23 | GND |
| | | 24 | HSYNC |
| | | 25 | +5V_PH |

| Connector | Connects to | Pin no. | Signal |
|-----------|------------------------|---------|-----------|
| JPH1 | Printhead laser card | 26 | Y_DATA2- |
| | | 27 | Y_DATA2+ |
| | | 28 | GND |
| | | 29 | Y_DATA1- |
| | | 30 | Y_DATA1+ |
| | | 31 | GND |
| | | 32 | M_DATA2- |
| | | 33 | M_DATA2+ |
| | | 34 | GND |
| | | 35 | M_DATA1- |
| | | 36 | M_DATA1+ |
| | | 37 | GND |
| | | 38 | C_DATA2- |
| | | 39 | C_DATA2+ |
| | | 40 | GND |
| | | 41 | C_DATA1- |
| | | 42 | C_DATA1+ |
| | | 43 | GND |
| | | 44 | K_DATA2- |
| | | 45 | K_DATA2+ |
| | | 46 | GND |
| | | 47 | K_DATA1- |
| | | 48 | K_DATA1+ |
| | | 49 | GND |
| | | 50 | LADJ_D3 |
| JUIPWR1 | Control panel card | 1 | 1. +5VL |
| | | 2 | GND |
| JFAN1 | Fan | 1 | GND |
| | | 2 | +25V |
| | | 3 | Fan Tach |
| | | 4 | Fan PWM |
| JSPKR1 | Speaker from audio DAC | 1 | Speaker + |
| | | 2 | Speaker - |

| Connector | Connects to | Pin no. | Signal |
|-----------|-------------------------------|---------|-------------------|
| JCARTP1 | K/ITM BLDC Mtr & CMY BLDC Mtr | 1 | K/ITM Winding W |
| | | 2 | K/ITM Winding V |
| | | 3 | K/ITM Winding U |
| | | 4 | CMY Winding W |
| | | 5 | CMY Winding V |
| | | 6 | CMY Winding U |
| JLVPS1 | LVPS | 1 | +6.5V |
| | | 2 | GND |
| | | 3 | +6.5V |
| | | 4 | GND |
| | | 5 | +6.5V |
| | | 6 | GND |
| | | 7 | +25V |
| | | 8 | GND |
| | | 9 | +25V |
| | | 10 | GND |
| | | 11 | +25V |
| | | 12 | GND |
| | | 13 | AC Relay On/Off |
| | | 14 | Zero-Xing |
| | | 15 | Fuser On/Off |
| | | 16 | 25V On/Off |
| JOPT1 | Tray option connector | 1 | Printer TXD |
| | | 2 | GND |
| | | 3 | GND |
| | | 4 | Printer RXD |
| | | 5 | +25V |
| | | 6 | GND |
| | | 7 | +5VH |
| | | 8 | Input (S2) Signal |
| | | 9 | GND |
| | | 10 | GND |

| Connector | Connects to | Pin no. | Signal |
|-----------|--|---------|------------------------|
| JCARTS1 | K/ITM & CMY BLDC hall effect sensor | 1 | K/ITM Hall_U |
| | | 2 | K/ITM Hall_V |
| | | 3 | K/ITM Hall_W |
| | | 4 | K/ITM FG |
| | | 5 | GND |
| | | 6 | +5V_SW |
| | | 7 | CMY Hall_U |
| | | 8 | CMY Hall_V |
| | | 9 | CMY Hall_W |
| | | 10 | CMY FG |
| | | 11 | GND |
| | | 12 | +5V_SW |
| JTHM1 | TPS thermistor | 1 | TPS Thermistor |
| | | 2 | GND |
| JBIN1 | Fuser exit optical sensor & bin-full / narrow media optical sensor | 1 | BF/NM Sensor Anode |
| | | 2 | BF/NM Sense Voltage |
| | | 3 | GND |
| | | 4 | Fsr Exit Sensor Anode |
| | | 5 | Fsr Exit Sense Voltage |
| | | 6 | GND |

| Connector | Connects to | Pin no. | Signal |
|-----------|----------------------|---------|------------------------------|
| JSP1 | AutoComp assembly | 1 | Quad Encdr LED Anode |
| | | 2 | Pick Mtr(+) |
| | | 3 | Quad Encdr LED Cathode |
| | | 4 | Pick Mtr(-) |
| | | 5 | +5V_SW |
| | | 6 | GND |
| | | 7 | GND |
| | | 8 | GND |
| | | 9 | Encoder Signal A |
| | | 10 | Pick Mtr Encdr Sense Voltage |
| | | 11 | Encoder Signal B |
| | | 12 | Pick Mtr Encdr Anode |
| | | 13 | GND |
| | | 14 | Input (S2) Sensor Anode |
| | | 15 | Input (S2) Sense Voltage |
| | | 16 | GND |
| JTPS2 | Left side TPS sensor | 1 | Sensor Anode |
| | | 2 | Sensor Cathode |
| | | 3 | GND |
| | | 4 | LED Anode |
| | | 5 | LED GND |


| Connector | Connects to | Pin no. | Signal |
|-----------|----------------------|---------|--------------------------|
| JHVPS1 | HVPS | 1 | +5V from HVPS |
| | | 2 | GND |
| | | 3 | M_Developer PWM |
| | | 4 | K-Developer PWM |
| | | 5 | C_Developer PWM |
| | | 6 | CMY_Charge PWM |
| | | 7 | Y_Developer PWM |
| | | 8 | K_Charge PWM |
| | | 9 | K_Transfer PWM |
| | | 10 | CMY_Transfer PWM |
| | | 11 | ITM_Transfer PWM |
| | | 12 | GND |
| | | 13 | CMY Analog Servo Voltage |
| | | 14 | K Analog Servo Voltage |
| | | 15 | ITM Analog Servo Voltage |
| | | 16 | HVPS ID Voltage |
| | | 17 | +25V after PFET (Q32) |
| | | 18 | GND |
| JWS1 | Weather station card | 1 | GND |
| | | 2 | I2C_Clock |
| | | 3 | GND |
| | | 4 | I2C_Data |
| | | 5 | +3.3V |
| | | 6 | GND |

| Connector | Connects to | Pin no. | Signal |
|-----------|---------------------------------------|---------|---------------------------|
| JFUSES2 | Fuser, duplex/MPF optical sensor, and | 1 | Fuser Stepper-Mtr PhaseA1 |
| | bubble optical sensor | 2 | Fuser Stepper-Mtr PhaseA2 |
| | | 3 | Fuser Stepper-Mtr PhaseB1 |
| | | 4 | Fuser Stepper-Mtr PhaseB2 |
| | | 5 | Fuser Hot-Roll Thermistor |
| | | 6 | GND |
| | | 7 | Dplx/MPF Sensor Anode |
| | | 8 | GND |
| | | 9 | Dplx/MPF Sense Votage |
| | | 10 | Fuser Belt Thermistor |
| | | 11 | GND |
| | | 12 | GND |
| | | 13 | Fuser Belt ID Voltage |
| | | 14 | Bubble Sensor Anode |
| | | 15 | Bubble Sense Voltage |
| | | 16 | GND |
| | | 17 | GND |
| | | 18 | GND |
| | | 19 | GND |
| | | 20 | GND |
| JTPS1 | Right side TPS sensor | 1 | Sensor Anode |
| | | 2 | Sensor Cathode |
| | | 3 | GND |
| | | 4 | LED Current Source |
| | | 5 | LED GND |
| JTRAY1 | Tray 1 present optical sensor | 1 | Sensor Anode |
| | | 2 | Sense Voltage |
| | | 3 | GND |
| JCVR1 | Cover switch | 1 | 25V Source |
| | | 2 | 25V Safety |
| JSC1 | Image basket card | 1 | +3.3V_SCHIP |
| | | 2 | I2C_Data |
| | | 3 | I2C_Clock |
| | | 4 | GND |

| Connector | Connects to | Pin no. | Signal |
|-----------|---|---------|------------------------|
| JRIP1 | FirmwWare debug (LB-Trace) port | 1 | GND |
| | | 2 | RXD |
| | | 3 | TXD |
| | | 4 | +3.3V |
| JVIP1 | Socket for viper card | 1 | GSPI TXD |
| | | 2 | +3.3V |
| | | 3 | GSPI CLK |
| | | 4 | GND |
| | | 5 | GSPI CS- |
| | | 6 | GSPI RXD |
| 59_JWT1 | Waste toner bottle | 1 | GND |
| | | 2 | AC Supply Voltage |
| | | 3 | Ref. Voltage |
| | | 4 | Sense Voltage |
| JFUSB1 | Front USB host connector | N/A | N/A |
| JIPS1 | Internal network adapters (INA) and wireless card | 1 | GND |
| | | 2 | No Connect |
| | | 3 | No Connect |
| | | 4 | GND |
| | | 5 | ISP_USB_P |
| | | 6 | ISP_USB_N |
| | | 7 | GND |
| | | 8 | +3.3V |
| | | 9 | ISP_RESET- |
| | | 10 | +5V_ISP |
| | | 11 | I2C2_DATA |
| | | 12 | +5V_ISP |
| | | 13 | I2C2_CLCK |
| | | 14 | +5V_ISP |
| JSEC1 | Security jumper | 1 | Security Jumper Signal |
| | | 2 | GND |
| | | 3 | GND |
| JRUSB1 | Rear USB host connector | N/A | N/A |
| JUSB1 | USB device connector | N/A | N/A |


| Connector | Connects to | Pin no. | Signal |
|-----------|-------------------------------|---------|------------------|
| JETH1 | EtherNet connector .01/.1/1Gb | - | - |
| JLPWRDB1 | Low Power Debug Port | 1 | GND |
| | | 2 | RXD |
| | | 3 | TXD |
| | | 4 | +3.3V |
| JPHONE1 | | 1 | Headphone Detect |
| | | 2 | Headphone - |
| | | 3 | Headphone + |
| | | 4 | GND |

Motor locations



| Part | Description |
|------|------------------------|
| 1 | Motor (fuser) |
| 2 | Motor (tray 1 pick) |
| 3 | Motor (K drive unit) |
| 4 | Motor (CMY drive unit) |

Sensor locations



| Part | Description |
|------|--------------------------------|
| 1 | Sensor (narrow media/bin full) |
| 2 | Sensor (fuser exit) |
| 3 | Sensor (input) |
| 4 | Sensor (redrive/duplex path 1) |
| 5 | Sensor (tray present) |

Maintenance

Inspection guide

Use this guide in identifying the parts that must be inspected, cleaned, or replaced based on the page count.

If any unsafe condition exists, find out how serious the hazard is and if you can continue before you correct the hazard.

As you service the machine, check for the following:

- Damaged, missing, or altered parts, especially in the area of the power switch and the power supply
- Damaged, missing, or altered covers, especially in the area of the top cover and power supply cover
- Possible safety exposure from any non-Lexmark components

Use the following table to determine when to inspect the following parts.:

| Lexmark C2240, C2325, C2425, C2535, CS421, CS521, CS622 | Every service call | Every 125K | Notes | |
|---|--------------------|----------------------------------|--|--|
| Tray - All | | | | |
| Tray side guides | Ins | pect | Check for correct positioning. | |
| Tray length guides | Ins | pect | Check for correct positioning. | |
| Transfer module | Inspect | NA | Ensure correct installation. | |
| Fuser | Inspect | Replace | Ensure correct installation. | |
| Pick tires - All | | • | | |
| Tray pick tires | Inspect and c | clean if needed | Clean with a damp cloth. | |
| MPF pick tires | Inspect and c | clean if needed | Clean with a damp cloth. | |
| Paper path | • | | | |
| Duplex path rollers | Ins | pect | Check for media fragments and tears. | |
| | | | Check for excessive toner build up on white rollers. | |
| | | Clean with damp cloth if needed. | | |
| Miscellaneous | | | | |
| Toner spillage | CI | ean | Use a toner vacuum and cloth to remove the spillage. | |

Scheduled maintenance

The control panel displays an **80.xx** error when it reaches certain page counts. It is necessary to replace the appropriate maintenance kit to maintain print quality and printer reliability.

Note: When replacing the maintenance kit, install all the parts that are included in the box, and then reset the maintenance counter.

Maintenance kits

After 125K printed pages (sides) a maintenance kit replacement may be required. Install the correct fuser maintenance kit to match the type of fuser that is installed in the printer.

Notes:

- You can continue to run past the rated life of the fuser.
- The fuser has no hard stop and should not typically wear out with use.
- Use the Embedded Web Server to turn off the notifications for fuser life warnings.

The following error codes indicate that the fuser is nearing its end of life and requires a maintenance kit replacement.

| Error code | Description |
|------------|--|
| 80.0x | The maintenance kit is nearly low. |
| 80.1x | The maintenance kit is low. |
| 80.2x | The maintenance kit is very low. Only 2000 estimated pages remain. |
| 80.3x | The maintenance kit is low. 0 estimated pages remain. |
| 80.4x | The maintenance kit is very low. 0 estimated pages remain. |

| Part number and kit | Contents | Maintenance interval |
|-------------------------------------|---|-------------------------|
| 41X2095—100 V fuser maintenance kit | 41X1299—Fuser 100 V40X5168—Pick roller | 125K |
| 41X2096—110 V fuser maintenance kit | 41X1041—Fuser 110 V40X5168—Pick roller | 125K |
| 41X2097—220 V fuser maintenance kit | 41X1300—Fuser 220 V40X5168—Pick roller | 125K |

When performing the scheduled maintenance procedure, clean the following areas of paper dust and toner contamination:

- Trays
- Photoconductor cartridge area
- · Developer unit housing area
- Transfer roller area
- Duplex area
- Standard bin

- Bridge unit area (if equipped)
- Finisher bins (if equipped)

Resetting the maintenance counter

- 1 Enter the Diagnostics menu, and then navigate to:
 Printer diagnostics & adjustments > Supply Reset > Maintenance kit reset
- 2 Press OK or touch Start.

Cleaning the printer parts

Cleaning the printer



CAUTION—SHOCK HAZARD: To avoid the risk of electrical shock when cleaning the exterior of the printer, unplug the power cord from the electrical outlet and disconnect all cables from the printer before proceeding.



ATTENTION—RISQUE D'ELECTROCUTION : pour éviter tout risque d'électrocution lors du nettoyage de l'extérieur de l'imprimante, débranchez le cordon d'alimentation électrique de la prise et déconnectez tous les câbles de l'imprimante avant de continuer.



PRECAUCIÓN: PELIGRO DE DESCARGAS ELÉCTRICAS: Para evitar el riesgo de descarga eléctrica al limpiar el exterior de la impresora, desconecte el cable de alimentación de la toma eléctrica y desconecte todos los cables de la impresora antes de realizar la operación.



VORSICHT – STROMSCHLAGGEFAHR: Um das Risiko eines elektrischen Schlags beim Reinigen des Druckergehäuses zu vermeiden, ziehen Sie das Netzkabel aus der Steckdose, und ziehen Sie alle Kabel vom Drucker ab. bevor Sie fortfahren.

Notes:


- Perform this task after every few months.
- Damage to the printer caused by improper handling is not covered by the printer warranty.
- 1 Turn off the printer, and then unplug the power cord from the electrical outlet.
- 2 Remove paper from the standard bin and manual feeder.
- 3 Remove any dust, lint, and pieces of paper around the printer using a soft brush or vacuum.
- **4** Wipe the outside of the printer with a damp, soft, lint-free cloth.

Notes:

- Do not use household cleaners or detergents, as they may damage the finish of the printer.
- Make sure that all areas of the printer are dry after cleaning.
- **5** Connect the power cord to the electrical outlet, and then turn on the printer.

Cleaning the printhead lenses

- 1 Remove the waste toner bottle. See "Waste toner bottle removal" on page 280.
- 2 Remove the imaging kit. See "Imaging kit removal" on page 276.
- **3** Using a damp, soft, lint-free cloth, wipe the printhead lenses (A).



Parts catalog

Legend


The following column headings are used in the parts catalog:

- Asm-index—Identifies the item in the illustration
- P/N—Identifies the part number of a FRU
- Units/mach—Refers to the number of units in a printer
- Units/opt—Refers to the number of units in an option
- Units/FRU—Refers to the number of units in a FRU
- **Description**—A brief description of the part

The following abbreviations are used in the parts catalog:

- **NS** (not shown) in the Asm-index column indicates that the part is procurable but is not shown in the illustration.
- PP (parts packet) in the Description column indicates that the part is contained in a parts packet.


Assembly 1: 2-line control panel



Assembly 1: 2-line control panel

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|-----------------------------------|--|
| 1 | 41X2070 | 1 | 1 | CS321 control panel badge cover | "2-line control panel badge cover removal" on page 290 |
| 1 | 41X2127 | 1 | 1 | C2325 control panel badge cover | "2-line control panel badge cover removal" on page 290 |
| 2 | 41X2044 | 1 | 1 | 2-line control panel bezel | "2-line control panel bezel removal" on page 292 |
| 3 | 41X2047 | 1 | 1 | 2-line control panel assembly | "2-line control panel assembly removal" on page 295 |
| 4 | 41X2045 | 1 | 1 | 2-line control panel top cover | "2-line control panel top cover removal" on page 296 |
| 5 | 41X2046 | 1 | 1 | 2-line control panel ribbon cable | "2-line control panel top cover removal" on page 296 |
| 6 | 41X1305 | 1 | 1 | 2-line control panel base cover | "Control panel base removal" on page 289 |

Assembly 2: 2.4-inch and 4.3-inch control panel




Assembly 2: 2.4-inch and 4.3-inch control panel

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|---|--|
| 1 | 41X2049 | 1 | 1 | CS421 control panel badge cover | "2.4-inch control panel badge cover removal" on page 291 |
| 1 | 41X2050 | 1 | 1 | CS521 control panel badge cover | "2.4-inch control panel badge cover removal" on page 291 |
| 1 | 41X2132 | 1 | 1 | C2425 control panel badge cover | "2.4-inch control panel badge cover removal" on page 291 |
| 1 | 41X2133 | 1 | 1 | C2535 control panel badge cover | "2.4-inch control panel badge cover removal" on page 291 |
| 1 | 41X1303 | 1 | 1 | Blank control panel badge cover | "2.4-inch control panel badge cover removal" on page 291 |
| 2 | 41X1304 | 1 | 1 | 2.4-inch control panel bezel (CS421, C2425, CS521, and C2535) | "2.4-inch control panel bezel removal" on page 292 |
| 3 | 41X1627 | 1 | 1 | 2.4-inch control panel assembly (CS421, C2425, CS521, and C2535) | "2.4-inch control panel top cover removal" on page 297 |
| 4 | 41X1308 | 1 | 1 | Headphone cable | |
| 5 | 41X1309 | 1 | 1 | 2.4-inch control panel FFC (CS421, C2425, CS521, and C2535) | "2.4-inch control panel top cover removal" on page 297 |
| 6 | 41X2021 | 1 | 1 | 4.3-inch control panel FFC (CS622 and C2240) | "4.3-inch control panel top cover removal" on page 299 |
| 7 | 41X1307 | 1 | 1 | USB cable | "Front USB cable removal" on page 307 |
| 8 | 41X1305 | 1 | 1 | Control panel base cover | "Control panel base removal" on page 289 |
| 9 | 41X1306 | 1 | 1 | 4.3-inch control panel top cover (CS622 and C2240) | "4.3-inch control panel top cover removal" on page 299 |
| 10 | 41X2113 | 1 | 1 | 4.3-inch control panel assembly (CS622 and C2240) | "4.3-inch control panel top cover removal" on page 299 |
| 11 | 41X1302 | 1 | 1 | 4.3-inch control panel bezel (CS622 and C2240) | "4.3-inch control panel bezel removal" on page 293 |
| 12 | 41X2115 | 1 | 1 | 4.3-inch control panel keyboard cover without volume (CS622 and C2240) | "4.3-inch control panel top cover removal" on page 299 |
| 13 | 41X1310 | 1 | 1 | 4.3-inch control panel keyboard cover (CS622 and C2240) | "4.3-inch control panel top cover removal" on page 299 |

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|------------------------------------|--|
| 14 | 41X2048 | 1 | 1 | CS622 control panel badge cover | "4.3-inch control panel badge cover removal" on page 291 |
| 14 | 41X2134 | 1 | 1 | C2240 control panel badge cover | "4.3-inch control panel badge cover removal" on page 291 |
| NS | 41X2119 | 1 | 1 | Control panel power cable | |


Assembly 3: Covers



Assembly 3: Covers

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|--|--|
| 1 | 40X7633 | 1 | 1 | Top cover | "Top cover removal" on page 346 |
| 2 | 40X7621 | 1 | 1 | Toner cover | |
| 3 | 40X9244 | 1 | 1 | Front toner door bracket | |
| 4 | 41X0397 | 1 | 1 | System fan | "System fan removal" on page 342 |
| 5 | 41X2100 | 1 | 1 | Rear cover, CS62x and C2240 | "Rear cover removal" on page 343 |
| 5 | 41X1788 | 1 | 1 | Rear cover, C2325, CS4x, C2425, CS52x, and C2535 | "Rear cover removal" on page 343 |
| 6 | 40X7630 | 1 | 1 | Right cover | "Right cover removal" on page 257 |
| 7 | 41X1285 | 1 | 1 | 250-sheet tray assembly | |
| 8 | 40X7619 | 1 | 2 | Door straps | |
| 9 | 41X1286 | 1 | 1 | Front door assembly | "Front door removal" on page 282 |
| 10 | 41X1305 | 1 | 1 | Control pane base | "Control panel base removal" on page 289 |
| 11 | 41X1291 | 1 | 1 | Left cover | "Left cover removal" on page 244 |
| 12 | 41X2663 | 1 | 1 | Front door inner deflector | "Front door inner deflector removal" on page 287 |


Assembly 4: Paper path and frame



Assembly 4: Paper path and frame

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|-------------------------------|---|
| 1 | 41X2305 | 1 | 1 | Fuser deflector | "Exit deflector removal" on page 314 |
| 2 | 41X2349 | 1 | 1 | Narrow media/bin full flag | "Narrow media/bin full sensor flag removal" on page 352 |
| 3 | 41X2350 | 1 | 1 | Right deflector flag | "Right output bin deflector removal" on page 354 |
| 4 | 41X1041 | 1 | 1 | 110 V Fuser | "Fuser removal" on page 311 |
| 4 | 41X1300 | 1 | 1 | 220 V Fuser | "Fuser removal" on page 311 |
| 4 | 41X1299 | 1 | 1 | 100 V Fuser | "Fuser removal" on page 311 |
| 5 | 41X1040 | 1 | 1 | Printhead | "Printhead removal" on page 352 |
| 6 | 40X7629 | 1 | 1 | Motor (fuser drive) | "Motor (fuser drive) removal" on page 260 |
| 7 | 41X2327 | 1 | 1 | Subframe cable cover | |
| 8 | 41X1312 | 1 | 1 | Lower right subframe | "Lower right frame removal" on page 328 |
| 9 | 40X5168 | 2 | 2 | Pick tires | "Pick tires removal" on page 316 |
| 10 | 41X1292 | 1 | 1 | Media feeder | "Tray 1 media feeder removal" on page 339 |
| 11 | 41X1039 | 1 | 1 | Transfer module | "Transfer module removal" on page 272 |
| 12 | 41X0580 | 1 | 1 | Transfer module guide | "Transfer module guide removal" on page 335 |
| 13 | 41X2326 | 1 | 1 | Lower left subframe | "Lower left frame removal" on page 318 |
| 14 | 41X1289 | 1 | 1 | EP drive assembly | "EP drive assembly removal" on page 247 |
| NS | 41X2360 | 4 | 4 | Sub-frame foot | |


Assembly 5: Electronics



Assembly 5: Electronics

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|--|--|
| 1 | 41X1789 | 1 | 1 | Controller board (CS421 and C2425) | "Controller board removal" on page 345 |
| 1 | 41X2098 | 1 | 1 | Controller board (CS521 and CS2535) | "Controller board removal" on page 345 |
| 1 | 41X1790 | 1 | 1 | Controller board (CS622 and C2240) | "Controller board removal" on page 345 |
| 1 | 41X2140 | 1 | 1 | Controller board (C2325) | "Controller board removal" on page 345 |
| 2 | 40X7620 | 1 | 1 | Toner meter card | "TMC card removal" on page 261 |
| 3 | 41X1042 | 1 | 1 | High voltage power supply | "HVPS removal" on page 267 |
| 4 | 40X7301 | 3 | 1 | Photo sensors: Sensor (tray present) Sensor (duplex) Sensor (narrow media/bin full) | "Sensor (tray present) removal" on page 338 "Sensor (duplex) removal" on page 334 "Sensor (narrow media/output bin full) removal" on page 350 |
| 5 | 41X1290 | 1 | 1 | Weather station | "Weather station service check" on page 169 |
| 6 | 40X5413 | 1 | 1 | Sensor (fuser exit) | "Sensor (fuser exit) removal" on page 252 |
| 7 | 41X2019 | 1 | 1 | 110 W low-voltage power supply (C2325) | "LVPS removal" on page 250 |
| 7 | 41X1043 | 1 | 1 | 175 W low voltage power supply (CS421, C2425, CS521, C2535, CS622 and C2240) | "LVPS removal" on page 250 |
| NS | 41X1311 | 1 | 1 | Speaker (CS622 and C2240) | "Speaker (CS622) removal" on page 257 |


Assembly 6: Cables and sensors



Assembly 6: Cables and sensors

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|--|---|
| 1 | 41X1904 | 1 | 1 | Sensor (left toner patch with thermistor) | "Sensors (toner patch) removal" on page 264 |
| 2 | 41X2348 | 1 | 1 | Sensor (right toner patch with thermistor) | "Sensors (toner patch) removal" on page 264 |
| 3 | 41X1722 | 1 | 1 | Waste toner bottle contact block | "Waste toner bottle contact block removal" on page 281 |
| 4 | 41X1723 | 4 | 1 | Toner cartridge contact | "Toner cartridge contacts removal" on page 278 |
| 5A | 41X2328 | 1 | 1 | Fuser exit narrow media to controller board | |
| 5B | 41X2329 | 1 | 1 | Fuser/input sensor cable | |
| 5C | 41X2332 | 1 | 1 | LVPS to controller board cable | |
| 5D | 41X2330 | 1 | 1 | EP motor to controller board cable | |
| 5E | 41X2335 | 1 | 1 | Tray 2 to controller board cable | |
| 5F | 41X2334 | 1 | 1 | HVPS to controller board cable | |
| 5G | 41X2336 | 1 | 1 | Tray present sensor cable | |
| 5H | 41X2331 | 1 | 1 | AC power to LVPS cable | |
| 6 | 41X1561 | 1 | 1 | Front and right side interlock switch cover assembly | "Interlock switch cover assembly removal" on page 288 |
| NS | 41X2333 | 1 | 1 | Weather station cable | "Weather station removal" on page 303 |

Assembly 7: Option trays



Assembly 7: Option trays

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|--------------------------------|---|
| 1 | 41X1783 | 1 | 1 | Optional 650-sheet duo tray | "650-sheet duo tray removal" on page 356 |
| 2 | 40X5168 | 2 | 2 | Pick tires | "Pick tire removal" on page 358 |
| 3 | 41X1784 | 1 | 1 | 650-sheet duo tray insert | "650-sheet duo tray insert removal" on page 355 |
| 4 | 40X7178 | 2 | 1 | 650-sheet duo tray MPF rollers | |
| 5 | 41X1780 | 1 | 1 | 550-sheet tray | |
| 6 | 41X1781 | 1 | 1 | 550-sheet tray insert | |

Assembly 8: Miscellaneous

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|---|-------------------|
| NS | 41X1026 | 1 | 1 | 500 GB USB hard disk drive | |
| NS | 41X1373 | 1 | 1 | SATA hard disk drive with FIPS | |
| NS | 41X1872 | 1 | 1 | Marknet N8372, front Wi-Fi—FSM (CS421, CS521, CS622, C2240) | |
| NS | 41X1873 | 1 | 1 | Wireless network card cardlet without cable | |
| NS | 41X1871 | 1 | 1 | 1 port vertical fax card | |
| NS | 40X4823 | 1 | 1 | 1284-B THCK parallel adapter | |
| NS | 41X1945 | 1 | 1 | N8230 fiber ISP with side cover adapter | |
| NS | 41X1946 | 1 | 1 | N8230 fiber ISP with backpack adapter | |
| NS | 41X1013 | 1 | 1 | Simplified Chinese font card | |
| NS | 41X1014 | 1 | 1 | Traditional Chinese font card | |
| | | | | Note: This part is obsolete. | |
| NS | 41X1015 | 1 | 1 | Korean font card | |
| NS | 41X1016 | 1 | 1 | Japanese font card | |
| NS | 41X1010 | 1 | 1 | 256 MB flash card | |
| NS | 41X2055 | 1 | 1 | Security element smart card with interconnect | |
| NS | 41X0020 | 1 | 1 | Serial ISP with backpack adapter | |
| NS | 41X0997 | 1 | 1 | Contact front solutions module | |
| NS | 41X0998 | 1 | 1 | Contactless front solutions module | |
| NS | 41X0045 | 1 | 1 | English keyboard | |
| NS | 41X0046 | 1 | 1 | French keyboard | |
| NS | 41X0048 | 1 | 1 | German keyboard | |
| NS | 41X0049 | 1 | 1 | Spanish keyboard | |
| NS | 41X2033 | 1 | 1 | PCIe 8 GB x32 DDP RAM card | |
| NS | 41X2302 | 1 | 1 | Braille label kit | |
| NS | 41X0357 | 1 | 1 | 110 V surge protector | |
| NS | 41X0370 | 1 | 1 | 220 V surge protector | |
| NS | 40X1367 | 1 | 1 | 10 ft. parallel cable | |
| NS | 40X1368 | 1 | 1 | USB cable | |
| NS | 40X7648 | 1 | 1 | Screws parts pack | |
| NS | 40X7652 | 1 | 1 | Spring kit | |

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|--|-------------------|
| NS | 3085348 | 1 | N/A | Software and document CD | |
| | | | | Note: This part number is for internal use only and is not available for order. | |
| NS | 41X2055 | 1 | 1 | Smart card | |

Assembly 9: Maintenance kits

| Asm-index | P/N | Units/mach | Units/FRU | Description | Removal procedure |
|-----------|---------|------------|-----------|---|-------------------|
| NS | 41X2095 | 1 | 1 | 100 V Fuser maintenance kitFuser 100 VPick roller | |
| NS | 41X2096 | 1 | 1 | 110 V Fuser maintenance kitFuser 110 VPick roller | |
| NS | 41X2097 | 1 | 1 | 220 V Fuser maintenance kit • Fuser 220 V • Pick roller | |

Printer specifications

Power consumption

Product power consumption

The following table documents the power consumption characteristics of the product.

Note: Some modes may not apply to your product.

| Mode | Description | Power consumption (Watts) |
|------------|---|--|
| Printing | The product is generating hard-copy output from electronic inputs. | One-sided: 400 (C2325, C2425, CS421); 530 (CS521); 570 (C2240, CS622) Two-sided: 275 (C2325); 280 (C2425, CS421); 360 (CS521); 380 (C2240, CS622) |
| Сору | The product is generating hard-copy output from hard-copy original documents. | N/A |
| Scan | The product is scanning hard-copy documents. | N/A |
| Ready | The product is waiting for a print job. | 32.5 (C2325); 35.5 (C2425, CS421); 37.0 (C2240, CS521, CS622) |
| Sleep Mode | The product is in a high-level energy-saving mode. | 1.3 (CS521); 1.4 (C2325, C2435, CS421); 1.5 (C2240, CS622) |
| Hibernate | The product is in a low-level energy-saving mode. | 0.2 |
| Off | The product is plugged into an electrical outlet, but the power switch is turned off. | 0.2 |

The power consumption levels listed in the previous table represent time-averaged measurements. Instantaneous power draws may be substantially higher than the average.

Values are subject to change. See www.lexmark.com for current values.

Sleep Mode

This product is designed with an energy-saving mode called *Sleep Mode*. The Sleep Mode saves energy by lowering power consumption during extended periods of inactivity. The Sleep Mode is automatically engaged after this product is not used for a specified period of time, called the *Sleep Mode Timeout*.

| Factory default Sleep Mode Timeout for this product (in minutes): | 15 |
|---|----|
|---|----|

By using the configuration menus, the Sleep Mode Timeout can be modified between 1 minute and 120 minutes. Setting the Sleep Mode Timeout to a low value reduces energy consumption, but may increase the response time of the product. Setting the Sleep Mode Timeout to a high value maintains a fast response, but uses more energy.

Hibernate Mode

This product is designed with an ultra-low power operating mode called *Hibernate mode*. When operating in Hibernate Mode, all other systems and devices are powered down safely.

The Hibernate mode can be entered in any of the following methods:

- Using the Hibernate Timeout
- Using the Schedule Power modes

Factory default Hibernate Timeout for this product in all countries or regions

3 days

The amount of time the printer waits after a job is printed before it enters Hibernate mode can be modified between one hour and one month.

Off mode

If this product has an off mode which still consumes a small amount of power, then to completely stop product power consumption, disconnect the power supply cord from the electrical outlet.

Total energy usage


It is sometimes helpful to estimate the total product energy usage. Since power consumption claims are provided in power units of Watts, the power consumption should be multiplied by the time the product spends in each mode in order to calculate energy usage. The total product energy usage is the sum of each mode's energy usage.

Selecting a location for the printer

- Leave enough room to open trays, covers, and doors and to install hardware options.
- Set up the printer near an electrical outlet.
- Make sure that airflow in the room meets the latest revision of the ASHRAE 62 standard or the CEN Technical Committee 156 standard.
- Provide a flat, sturdy, and stable surface.
- Keep the printer:
 - Clean, dry, and free of dust
 - Away from stray staples and paper clips
 - Away from the direct airflow of air conditioners, heaters, or ventilators
 - Free from direct sunlight and humidity extremes
- Observe the temperature range.

Operating temperature 10 to 32.2°C (50 to 90°F)

Allow the following recommended amount of space around the printer for proper ventilation:



| 1 | Тор | 254 mm (10 in.) |
|---|------------|---|
| 2 | Rear | 102 mm (4 in.) |
| 3 | Right side | 76 mm (3 in.) |
| 4 | Front | 508 mm (20 in.) |
| | | Note: The minimum space needed in front of the printer is 75 mm (3 in.) |
| 5 | Left side | 76 mm (3 in.) |

Noise emission levels

The following measurements were made in accordance with ISO 7779 and reported in conformance with ISO 9296.

Note: Some modes may not apply to your product.

| 1-meter average sound pressure, dBA | | |
|-------------------------------------|----|--|
| Printing | 50 | |
| Ready | 16 | |

Values are subject to change. See www.lexmark.com for current values.

Temperature information

| Operating temperature and relative humidity Printer / cartridge / imaging unit long- term storage ¹ | 10 to 32.2°C (50 to 90°F) and 15 to 80% RH 15.3 to 32.2°C (60 to 90°F) and 8 to 80% RH Maximum wet bulb temperature: 22.8°C (73°F) Non-condensing environment |
|---|--|
| Printer / cartridge / imaging unit short-term shipping | -40 to 43.3°C (-40 to 110°F) |

 $^{^{1}}$ Supplies shelf life is approximately 2 years. This is based on storage in a standard office environment at 22°C (72°F) and 45% humidity.

² Wet-bulb temperature is determined by the air temperature and the relative humidity.

Enabling the security reset jumper

Notes:

- Before changing the security settings, ask for permission from your administrator.
- Resetting the printer deletes all security settings.
- For MFPs, replacing the controller board deletes all security settings.
- If LDAP is used to authenticate the copy function in MFPs, then the LDAP configuration and copy function are no longer protected.
- To prevent the tampering of the jumper, secure the controller board cage with a Kensington lock. To disable the effect of the jumper reset, select **No Effect** from the Security Reset Jumper Setting section in the Security menu.
- If Enable Audit is activated from the Security Audit Log in the Miscellaneous section of the Security menu, then the printer logs a message each time the jumper is reset.

To reset the jumper:

- **1** Turn off the printer.
- **2** Access the controller board.
- **3** Locate the jumper at the JSEC1 connector on the controller board.
- **4** Move the jumper to cover the middle and exposed prongs.

Note: The movement of the jumper triggers the reset, not the jumper position.

5 Turn on the printer.

Options and features

Some of the options may not be available in every country or region.

Available internal options

- Flash memory
- Font cards
- Firmware cards
 - Forms and Bar Code
 - PRESCRIBE
- Printer hard disk

Note: Some options are available only in some printer models. For more information, contact the place where you purchased the printer.

Adding available options in the print driver

For Windows users

- 1 Open the printers folder.
- **2** Select the printer you want to update, and then do either of the following:
 - For Windows 7 or later, select **Printer properties**.
 - For earlier versions, select **Properties**.
- 3 Navigate to the Configuration tab, and then select **Update Now Ask Printer**.
- **4** Apply the changes.

For Macintosh users

- 1 From System Preferences in the Apple menu, navigate to your printer, and then select **Options & Supplies**.
- **2** Navigate to the list of hardware options, and then add any installed options.
- 3 Apply the changes.

Input/output configurations and capacities

Input sources

| Printer model | Number of standard trays | Maximum number of optional trays | Maximum number of trays |
|-----------------|--------------------------|--|----------------------------|
| C2325 | 2 | 0 | 2 |
| CS421 and C2425 | 2 | 1 | 3 |
| CS521 and C2535 | 2 | 2 | 4 |
| C2240 and CS622 | 2 | 2 | 4 |

Input capacities

| Printer model | Standard tray | Manual slot | Multipurpose feeder capacity | Total standard capacity | Maximum input capacity |
|-----------------|---------------|-------------|------------------------------------|-------------------------|------------------------|
| C2325 | 250 | 1 | N/A | 251 | 251 |
| CS421 and C2425 | 250 | 1 | 100 | 251 | 901 |
| CS521 and C2535 | 250 | 1 | 100 | 251 | 1451 |
| C2240 and CS622 | 250 | 1 | 100 | 251 | 1451 |

Paper capacity means 20-lb xerographic paper at ambient environment per sheet.

Output capacities

| Printer model | Standard output capacity | Maximum output capacity | |
|--|--------------------------|-------------------------|--|
| C2325 | 125 | 125 | |
| CS421 and C2425 | 125 | 125 | |
| CS521 and C2535 | 125 | 125 | |
| C2240 and CS622 | 125 | 125 | |
| Paper capacity means 20-lb xerographic paper at ambient environment per sheet. | | | |

^{*} Available only when 650-sheet option tray is installed.

Theory of operation

Paper path and transport components

For an image to be printed, the paper or specialty media has to be moved from an input source (such as a tray) into the printer and eventually exit into an output source.

The most important component in this process is this paper itself. Old, damaged, or out-of-specification paper can and will cause feed and transport problems. If you encounter problems, you should always check the paper first. In addition, it is always good practice to check the printer and driver settings to see if the paper being used matches the user's settings. It is not uncommon to find a user printing on cardstock with the printer programmed to print on a plain paper setting.


The printer's feed and transport components can fail and cause paper jams or other feed and transport problems. These components should be examined for damage or wear and replaced if necessary.

Paper path information

The printer has a simple C-shaped paper path. The tray 1 paper is shown in red and the optional 650-sheet duo tray paper path is not shown.

Paper is fed from the rear of the printer and travels upward through the front cover.

The duplex unit is built into the front cover and Tray 1.



Note: The ACM is also known as the paper feed roller assembly.

Transport components

The paper is fed from the tray into the printer by a pick roll and sent to two sets of feed rollers which time the paper to enter the Electrophotographic Process (EP Process) at just the right moment. The feed rollers push the paper to the transfer module where the image is transferred to the page.

The transfer roller moves the paper to the fuser where heat and pressure are applied to the page. The fuser rollers push the paper toward the exit bin and past the exit sensor. The exit rollers guide the paper into the output bin.

Note: If the printer posts a paper jam message but no paper is found, then paper dust or paper particles may have fallen into one of the sensor eyes. Use a can of compressed air to gently clean the sensor.

Duplexing

Printers with duplex support use a secondary paper path to print on the second side of a sheet of paper. The duplexing process is summarized as follows:

After the first side of the paper is printed and the trailing edge of the paper clears the fuser exit sensor, the fuser motor engages to reverse the paper direction and feed it into the duplex unit. The pick motor also reverses. The pick motor drives the duplex aligner rolls (A), which push the media down to the bottom turnaround in the paper tray and gate aligner (B).


Note: While the sheet is being transported through the duplex unit, it is the only sheet of paper being processed by the print engine. A user should not attempt to insert a sheet of paper into the manual paper feed while a duplex job is being processed. This would cause a paper jam error.

When the trailing edge of the media clears the fuser, the fuser engine rotates forward to prepare the fuser for the page traveling though the duplex unit.

As the media reaches the gate aligner, a sensor (S1) is triggered, indicating the presence of the leading edge.

When the S1 sensor is triggered, the paper continues to the (S2) sensor. When the S2 signal is detected, the speed of the pick motor is adjusted to accommodate the speed of the transfer belt, ensuring the proper registration of the image on the media. The paper travels to the transfer module (C), and the second image is transferred to the reverse side of the media.

Once the image is transferred, the media travels to the fuser (D), the fuser exit rolls (E), and then to the output bin.



Print engine theory

Electrophotographic process (EP process)

The method that all laser and LED printers use to print is called the electrophotographic process. These machines use differences in charge to manipulate and move toner from the print cartridge to the printed page.

Even though the basic EP process is the same for every laser and LED printer, the specifics for each printer are different.

Electrophotographic process basics

This printer is a single-laser printer that uses four print cartridges (cyan, yellow, magenta, and black) to create text and images on paper.

The printer has four photoconductor units (sometimes called a photodeveloper cartridge or PC unit) built into the print cartridges and transfer module. Each color toner is painted to its respective photoconductor unit at the same time. The transfer belt passes under the four photoconductor units and the four-color image is produced and transferred to the paper in one pass.

During the printing process, the printer follows the six basic EP process steps to create its output to the page.

- **1** Charge the photoconductor units.
- **2** Expose the photoconductor units with the laser.
- **3** Develop toner on the photoconductor units.
- **4** First transfer to the transfer module, and second transfer to the paper.
- **5** Fuse the toner to the paper.
- **6** Clean/erase the photoconductor units and the transfer module.

In summary, the printer controller board receives print data and the command to print. The controller board then initiates the print process. The controller board is the command center for the EP process and coordinates the various motors and signals.

The high-voltage power supply (HVPS) sends charge to various components in the EP process. The laser fires on the photoconductor units and alters the surface charge relative to the planed image for each photoconductor unit. Each photoconductor unit rotates past its respective developer roll, and toner is developed on the surface of each photoconductor unit. The four separate color images are then transferred to the transfer belt on the transfer module as it passes under the photoconductors. After the image is transferred to the transfer belt, the photoconductor units are cleaned and recharged.

The transfer belt carries the four-colored image towards the transfer rollers. Paper is picked up from the tray and carried to the transfer roll where the image is transferred from the transfer belt to the paper. The timing of the paper pick is determined by the speed of the transfer belt.

The paper is carried to the fuser rollers where heat and pressure are applied to the page to permanently bond the toner to the page. The fuser rollers push the paper into the output bin. The transfer unit is cleaned and the process begins again for the next page.

Step 1: Charge

During the charge step, voltage is sent from the HVPS to the charge roller beside each of the four photoconductor units. In this printer, the charge roll is part of the photoconductor unit in the print cartridges.

The charge roller puts a uniform negative charge over the entire surface of the photoconductor unit to prepare it for the laser beam.

Service tips

- If the surface of the charge roller is damaged (such as a nick or pit), then the charge on the photoconductor
 unit is uneven. A repeating mark appears on the printed page. Check the service manual for the repeating
 marks table.
- If the charge roller is severely damaged, then the surface of the photoconductor unit is not properly charged and heavy amounts of toner are deposited on the photoconductor unit. The printed page becomes saturated with 100 percent of each color. The imaging kit must be replaced immediately.

Step 2: Expose

During the expose step, the laser fires a focused beam of light at the surface of each photoconductor unit and writes an invisible image, called a latent image or electrostatic image, for each color.

The laser beam discharges only the surface where the beam hits the photoconductor unit. This discharge creates a difference in charge potential between the exposed area and the rest of the photoconductor unit surface.

Service tips

- The laser beam passes through a glass lens as it exits the laser unit. If this lens gets contaminated with toner or other debris, then vertical streaking of white/lightness appears on the page. Make sure to clean the lens.
- Do not touch the surface of the photoconductor unit with your bare hand. The oil from your skin may cause
 a charge differential on the surface, and toner may not stick properly. The result can be repeating blotches
 of voids/light print on a page. The imaging kit may need to be replaced.
- The surface of the photoconductor unit is coated with an organic substance that makes it sensitive to light.
 Make sure to cover the photoconductor unit when you are working on the printer. If exposed to light for too long, then light/dark print quality problems may occur, and the photoconductor unit may need to be replaced.

Step 3: Develop

When the laser exposes the photoconductor unit, the HVPS sends charge to the developer roll. For each color, the print cartridge engages the photoconductor unit so it is in contact with the surface. Because of the charge difference between the toner on the developer roller and the electrostatic image created by the laser, the toner is attracted to areas of the photoconductor unit surface exposed by the laser.

This process is similar to using glue to write on a can and then rolling it over glitter. The glitter sticks to the glue but does not stick to the rest of the can.

Service tips

- Do not touch the surface of the developer roller with your bare hand. The oil from your skin may cause a charge differential on the surface, and toner may not stick properly. The result can be repeating blotches of voids/light print on a page. The affected developer may need to be replaced.
- If the developer roller is damaged, then it cannot contact the surface of the photoconductor unit properly. The result can be repeating marks, thin vertical voids, or thin vertical lines of color on the printed page. Check the surface of the developer for damage.

Step 4a: First transfer

When the latent images are developed on each photoconductor unit, the HVPS sends voltage to the first transfer rollers inside the transfer module.

The charge difference between the developed toner image on the photoconductor unit surface and the first transfer roller causes the images to transfer to the surface of the transfer belt for each color. This transfer occurs during a direct surface-to-surface contact between the photoconductor units and the transfer belt.

Service tips

- Do not touch the surface of the transfer belt with your bare hand. The oil from your skin may cause a charge differential on the surface, and toner may not stick properly. The result can be repeating blotches of voids/light print on a page. The transfer belt may need to be replaced.
- Do not use solvents or other cleaners to clean the transfer belt surface. The surface may have scratches or a charge differential that may produce voids or light blotches on the printed page. The transfer belt may need to be replaced.

Step 4b: Second transfer

When the four planes of color are transferred to the transfer belt from the photoconductor units, the image is carried toward the transfer roller, which is also part of the transfer module. Based on the speed of the transfer belt, the proper time to send the signal to pick the paper from an input source is determined. The pick is timed so that the paper passes between the transfer belt and transfer roller when the image on the belt reaches the second transfer area.

The HVPS sends voltage to the transfer roller to create a positive charge. When the image on the transfer belt reaches the transfer roller, the negatively charged toner clings to the paper, and the entire image is transferred from the transfer belt to the paper.

Service tips

- If the transfer roller has nicks, pits, or flat spots on it, then the surface cannot come into contact with the paper and transfer module. The result can be voids or light spots on the page or repeating voids/light areas.
- If the transfer roller does not engage the transfer module, or does not have voltage coming from the HVPS, then the toner does not fully transfer from the transfer module; the entire page may be very light or blank. Any toner that does transfer can be because of contact transfer instead of a charge transfer. Check the HVPS contacts to the transfer roller.

Step 5: Fuse

When the image has been fully transferred to the paper, the transfer roller helps move the paper into the fuser area.

The fuser applies heat and pressure to the page to melt the toner particles and bond them permanently to the paper. The fuser moves the paper to the redrive rolls which move the paper to the output bin.

Service tips

- If the fuser rollers are damaged, then the toner may be pulled off the page or cause paper jams.
- Toner that rubs off a printed page indicate a malfunctioning fuser or an improper paper setting. Always check the paper type setting before replacing the fuser. A common mistake is to print on heavier media (such as cardstock) with the paper type set to plain paper.
- When removing paper jams from the fuser, make sure to use the fuser release tabs to relieve the pressure
 on the page. In addition, never pull unfused toner through the fuser if possible; try to back the jammed page
 out of the fuser in the opposite direction it was travelling.

Step 6: Clean/Erase

Two main cleaning processes take place during the EP process. One process cleans the transfer belt, and the other cleans the photoconductor units.

Transfer module clean

When the toner image on the transfer belt has been transferred to the page, the transfer belt rotates around and is cleaned by the cleaning blade. The cleaning occurs for every page that is printed.

After the toner is moved to the cleaning blade, the toner is moved to the waste toner area using an auger system.

Photoconductor clean/erase

After each plane of color has been transferred to the transfer belt from the photoconductor units, a cleaning blade scrapes the remaining toner from the surface of each photoconductor unit.

The photoconductor unit surface is prepared to restart the EP process. This cleaning/erasing cycle happens after each plane of color is transferred to the transfer belt.

Color theory

Color theory

What is RGB color?

Red, green, and blue light can be added together in various amounts to produce a large range of colors observed in nature. For example, red and green can be combined to create yellow. Televisions and computer monitors create colors in this manner. RGB color is a method of describing colors by indicating the amount of red, green, or blue needed to produce a certain color.

What is CMYK color?

Cyan, magenta, yellow, and black inks or toners can be printed in various amounts to produce a large range of colors observed in nature. For example, cyan and yellow can be combined to create green. Printing presses, inkjet printers, and color laser printers create colors in this manner. CMYK color is a method of describing colors by indicating the amount of cyan, magenta, yellow, and black needed to reproduce a particular color.

How is color specified in a document to be printed?

Software programs typically specify document color using RGB or CMYK color combinations. They also allow users to modify the color of each object in a document. For more information, see the software program Help topics.

How does the printer know what color to print?

When a user prints a document, information describing the type and color of each object is sent to the printer. The color information is passed through color conversion tables that translate the color into the appropriate amounts of cyan, magenta, yellow, and black toner needed to produce the desired color. The object information determines the application of color conversion tables. For example, one type of color conversion table can be applied to text while applying a different color conversion table to photographic images.

Should I use PostScript or PCL emulation? What settings produce the best color?

We recommend the PostScript driver for best color quality. The default settings in the PostScript driver provide the preferred color quality for the majority of printouts.

Why doesn't the printed color match the color I see on the computer screen?

The color conversion tables used in Auto Color Correction mode generally approximate the colors of a standard computer monitor. However, because of technology differences that exist between printers and monitors, many colors can also be affected by monitor variations and lighting conditions.

The printed page appears tinted. Can I adjust the color?

Sometimes a printed page may appear tinted (for example, everything looks too red). This tint can be caused by environmental conditions, paper type, lighting conditions, or user preference. Adjust the Color Balance setting to create a more preferable color. Color Balance lets the user make subtle adjustments to the amount of toner being used in each color plane. Selecting positive or negative values for cyan, magenta, yellow, and black (from the Color Balance menu) can slightly increase or decrease the amount of toner used for the chosen color. For example, if a printed page has a red tint, then decreasing both magenta and yellow can improve the color balance.

What is manual color correction?

When manual color correction is enabled, the printer uses user-selected color conversion tables to process objects. However, Color Correction must be set to Manual, or no user-defined color conversion can be implemented. Manual color correction settings are specific to the type of object being printed (text, graphics, or images), and how the color of the object is specified in the software program (RGB or CMYK combinations).

Notes:

- Manual color correction is not useful if the software program does not specify colors with RGB or CMYK
 combinations. It is also not effective in situations in which the software program or the computer
 operating system controls the adjustment of colors.
- The color conversion tables—applied to each object when Color Correction is set to Auto—generate preferred colors for the majority of documents.

To manually apply a different color conversion table:

- 1 From the home screen, touch Settings > Print > Quality > Advanced Imaging > Color Correction.
- 2 Select Manual, and then touch Color Correction Content.
- **3** Select the appropriate color conversion table for the affected object type.

| Object type | Color conversion tables |
|-------------------------|---|
| RGB Image RGB Text | Vivid—Produces brighter, more saturated colors and may be applied to all incoming color formats. |
| RGB Graphics | sRGB Display—Produces an output that approximates the colors shown on a computer monitor. Black toner usage is optimized for printing photographs. |
| | Display—True Black—Produces an output that approximates the colors shown on a computer monitor. Uses only black toner to create all levels of neutral gray. |
| | sRGB Vivid—Provides an increased color saturation for the sRGB display color correction. Black toner usage is optimized for printing business graphics. |
| | Off—No color correction is implemented. |
| CMYK Image CMYK Text | US CMYK—Applies color correction to approximate the SWOP (Specifications for Web Offset Publishing) color output. |
| CMYK Graphics | Euro CMYK—Applies color correction to approximate EuroScale color output. |
| | Vivid CMYK—Increases the color saturation of the US CMYK color correction setting. |
| | Off—No color correction is implemented. |

How can I match a particular color (such as a corporate logo)?

From the printer Quality menu, nine types of Color Samples sets are available. These sets are also available in the Color Samples page of the Embedded Web Server. Selecting any sample set generates a multiple-page printout consisting of hundreds of colored boxes. Either a CMYK or RGB combination is located on each box, depending on the table selected. The observed color of each box is obtained by passing the CMYK or RGB combination labeled on the box through the selected color conversion table.

To print color sample pages:

- 1 From the home screen, touch Settings > Print > Quality > Advanced Imaging > Color Samples > Print Color Samples.
- **2** Select the appropriate color conversion table to print.

By examining Color Samples sets, a user can identify the box whose color is the closest to the desired color. The color combination labeled on the box can then be used for modifying the color of the object in a software program. For more information, see the software program Help topics. Manual color correction may be used for the selected color conversion table for the particular object.

Selecting which Color Samples set to use for a particular color-matching problem depends on the Color Correction setting being used (Auto, Off, or Manual), the type of object being printed (text, graphics, or images), and how the color of the object is specified in the software program (RGB or CMYK combinations). When the printer Color Correction setting is set to Off, the color is based on the print job information; and no color conversion is implemented.

Note: The Color Samples pages are not useful if the software program does not specify colors with RGB or CMYK combinations. The software program or the computer operating system sometimes may adjust the RGB or CMYK combinations specified in the program through color management. The resulting printed color may not be an exact match of the Color Samples pages.

What are detailed Color Samples and how do I access them?

Detailed Color Samples sets are available in the Embedded Web Server of a network printer. A detailed Color Samples set contains a range of shades (shown as colored boxes) that are similar to a user-defined RGBor CMYK value. The likeness of the colors in the set are dependent on the value entered in the RGB or CMYK Increment box.

To access a detailed Color Samples set from the Embedded Web Server:

- 1 From the home screen, touch Settings > Print > Quality > Advanced Imaging > Color Samples > Print Color Samples.
- **2** Select **Advanced** to narrow the set to one color range.
- **3** Select the appropriate color conversion table to print.
- **4** Enter the RGB or CMYK color number.
- **5** Enter an increment value from 1 to 255.

Note: The closer the value is to 1, the narrower the color sample range appears.

6 Select Print.

Acronyms

Acronyms

ASIC Application-specific integrated circuit

BLDC Brushless DC motor
BOR Black only retract

C Cyan

CCD Charge coupled device
CCP Carbonless copy paper
CRC Cyclic redundancy check

CSU Customer setup

CTLS Capacitance toner level sensing
DIMM Dual inline memory module

DRAM Dynamic random access memory

EDO Enhanced data out
EP Electrophotography

EPROM Erasable programmable read-only memory

FRU Electrostatic discharge
FIat flexible cable
Field replaceable unit

GB Gigabyte

HCF High-capacity feeder
HCIT High-capacity input tray

HCOF High-capacity output finisher
HVPS High voltage power supply

K Black

LAA Locally Administered Access

LCD Liquid crystal display

LDAP Lightweight directory access protocol

LED Light-emitting diode

LVPS Low voltage power supply

M Magenta
MB Megabyte

MFP Multi-function product
MPF Multipurpose feeder

MROM Masked read only memory

MS Microswitch

NVM Nonvolatile memory

NVRAM Nonvolatile random access memory

OEM Original equipment manufacturer

OPT Optical sensor
PC Photoconductor
pel, pixel Picture element
POR Power-on reset
POST Power-on self test

PSD Position sensing device
PWM Pulse width modulation
RIP Raster imaging processor

ROM Read only memory

SDRAM Synchronous dual random access memory

SIMM Single inline memory module
SRAM Static random access memory

TMC Toner meter cycle

TPS Toner patch sensing

UPR Used parts return

V ac Volts alternating current

V dc Volts direct current

Y Yellow

Index

| A | error codes |
|--|--|
| acronyms 417 | 110 error messages 116 |
| adding hardware options | 200 paper jam messages 76 |
| print driver 405 | 202 paper jam messages 79 |
| adding internal options | 231 paper jam messages 86 |
| print driver 405 | 232 paper jam messages 91 |
| additional input tray diagnostics | 241 paper jam messages 92 |
| motor tests 209 | 242 paper jam messages 92 |
| sensor tests 209 | 243 paper jam messages 94 |
| adjustment | ESD-sensitive parts 220 |
| registration adjustment 240 | eSF solutions 226 |
| advanced print quality samples 202 | event log |
| avoiding paper jams 74 | display log 203 |
| | mark log 203 |
| C | print log 203 |
| change history 17 | print log summary 203 |
| cleaning | _ |
| exterior of the printer 377 | F |
| interior of the printer 377 | finding |
| printhead lenses 378 | serial number 22 |
| cleaning the printer 377 | front door inner deflector removal 287 |
| clearances around the printer 402 | |
| color theory 413 | Н |
| configurations | hardware options, adding |
| printer models 21 | print driver 405 |
| configuring the door interlock bypass jumpers 200 | home screen |
| connectors | using 200 |
| controller board 362 | home screen icons 200 |
| control panel | horizontal bottom contact connector 231 |
| critical information 220 | horizontal sliding contact connector 236 |
| controller board | horizontal top contact connector 228 |
| critical information 220 | humidity around the printer 403 |
| controller board, restoring configuration 221 | , |
| 3 · · · · · · · · · · · · · · · · · · · | 1 |
| D | indicator light |
| data security notice 217 | understanding the status 199 |
| diagnostics menu | input capacities 406 |
| accessing 202 | input configurations 406 |
| duplex support 408 | inspection guide 375 |
| duplex support 400 | internal options |
| E | firmware card 405 |
| - | memory card 405 |
| electrophotographic process 409 | printer hard disk 405 |
| electrostatic-sensitive parts 220 | internal options, adding |
| embedded solutions 226 | print driver 405 |
| emission notices 403 | invalid code, fixing 214 |
| Entering the TPS characterization data 242 EP process 409 | , 3 |

| invalid engine mode accessing 214 | mottled print and dots 48 text or images cut off 46 |
|---|---|
| J | toner easily rubs off 36 uneven print density 59 |
| jams | vertical white lines 50 |
| avoiding 74 | printer |
| locating jam areas 75 | fully configured 361 |
| locations 75 | printer configurations 361 |
| iodalono 70 | printer diagnostics |
| I | input tray quick print 204 |
| | printer diagnostics & adjustments |
| locations | motor tests 207 |
| motor 373 | sensor tests 206 |
| sensor 374 | universal override 209 |
| low insertion force (LIF) connector 239 | printer diagnostics and adjustments |
| M | add-on cards tests 208 |
| | color alignment adjust 208 |
| maintenance counter 377 | registration adjust 207 |
| maintenance kit | supply reset 208 |
| resetting the counter 377 | weather station 208 |
| maintenance kits 376 | printer location |
| menu Configuration Many 240 | selecting 402 |
| Configuration Menu 210 | printer messages |
| N1 | Non-Lexmark supply 97 printer model |
| N | configurations 21 |
| noise emission levels 403 | printer setup |
| Non-Lexmark supply 97 | engine setting [x] 205 |
| notices 401, 402, 403 | EP setup 205 |
| | model name 205 |
| 0 | permanent page count 204 |
| output capacities 406 | printed page count (color) 204 |
| output configurations 406 | printed page count (mono) 204 |
| | process ID 204 |
| P | serial number 204 |
| paper jams | printer status 199 |
| avoiding 74 | printhead lenses |
| paper path 407 | cleaning 378 |
| parts catalog legend 380 | J |
| power button light | R |
| understanding the status 199 | recovery mode |
| print driver | accessing 214 |
| hardware options, adding 405 | removal |
| print quality | 2.4-inch control panel badge cover 291 |
| initial check 31 | 2.4-inch control panel bezel 292 |
| print quality troubleshooting | 2.4-inch control panel keypad 302 |
| blank or white pages 41 | 2.4-inch control panel top cover 297 |
| dark print 53 | 2-line control panel assembly 295 |
| ghost images 51 | 2-line control panel badge cover 290 |
| horizontal colored lines or banding 45 | 2-line control panel bezel 292 |
| horizontal white lines 44 | 2-line control panel top cover 296 |
| light print 63 | 4.3-inch control panel badge cover 291 |
| | |

| 4.3-inch control panel bezel 293 | reports |
|---|--|
| 4.3-inch control panel top cover 299 | device settings 202 |
| 650-sheet duo tray 356 | installed licenses 202 |
| 650-sheet duo tray insert 355 | resetting |
| control panel base 289 | supply usage counters 97 |
| controller board 345 | resetting the supply usage counters 97 |
| developer unit 266 | restoring |
| dust cover 357 | configuration file 224 |
| EP drive assembly 247 | license file 224 |
| exit deflector 314 | ribbon cables 226 |
| front door 282 | |
| front USB cable 307 | S |
| fuser 311 | scheduled maintenance 376 |
| high-voltage power supply (HVPS) 267 | |
| imaging kit 276 | security reset jumper |
| interlock switch cover assembly 288 | enabling 404 |
| left cover 244 | selecting a location for the printer 402 |
| lower left frame 318 | service checks troubleshooting |
| lower right frame 328 | 100 service error messages 115 |
| LVPS 250 | 120 service error messages 117 |
| motor (drive unit) 247 | 121 service error messages 119 |
| motor (drive drive) 240 | 126 service error messages 124 |
| narrow media/exit sensor flag 352 | 142 service error messages 125 |
| pick tire 358 | 151 service error messages 127 |
| pick tire 338 pick tires 316 | 160 service error messages 128 |
| printhead 352 | 161 service error messages 129 |
| rear cover 343 | 162 service error messages 131 |
| | 163 service error messages 131 |
| right output his deflector, 254 | 166 service error messages 132 |
| right output bin deflector 354 | 167 service error messages 132 |
| sensor (duplex) 334 | 171 service error messages 132 |
| sensor (fuser exit) 252 | 600 service error message 133 |
| sensor (narrow media/output bin full) 350 | 602 service error messages 134 |
| sensor (tray present) 338 | 620 service error messages 135 |
| sensors (toner patch) 264 | 642 service error messages 135 |
| speaker (CS622) 257 | 651 service error messages 136 |
| system fan 342 | 661 service error messages 136 |
| TMC card 261 | 662 service error messages 137 |
| toner cartridge contacts 278 | 663 service error messages 137 |
| toner supply door 259 | 666 service error messages 138 |
| top cover 346 | 667 service error messages 138 |
| transfer module 272 | 900 service error messages 140 |
| transfer module guide 335 | 913.xx error code check 146 |
| tray 1 media feeder 339 | 91y service error messages 145 |
| waste toner bottle 280 | 938 service error messages 147 |
| waste toner bottle contact block 281 | 95y service error messages 147 |
| wireless card 306 | 96y service error messages 151 |
| removal procedures | 97y service error messages 151 |
| tips 244 | 980–984 service error messages 153 |
| removals | 99y service error messages 153 |
| front door inner deflector 287 | sensor (tray [x]) service check 172 |
| weather station 303 | service engineer (SE) menu |
| | accessing 213 |
| | decessing 215 |

| general SE 213 | 651 service error messages 136 |
|--|---|
| network SE 213 | 661 service error messages 136 |
| supplies used to resolve print quality issues 32 | 662 service error messages 137 |
| supply reset | 663 service error messages 137 |
| fuser reset 208 | 666 service error messages 138 |
| ITM reset 208 | 667 service error messages 138 |
| supply usage counters | 900 service error messages 140 |
| resetting 97 | 913.xx error code check 146 |
| supported paper sizes 22 | 91y service error messages 145 |
| supported paper types 25 | 938 service error messages 147 |
| supported paper weights 26 | 95y service error messages 147 |
| symptoms | 96y service error messages 151 |
| printer 154 | 97y service error messages 151 |
| • | 980–984 service error messages 153 |
| Т | 99y service error messages 153 |
| - | sensor (tray [x]) service check 172 |
| temperature around the printer 402, 403 | |
| tools, required 27 | U |
| transport components 408 | _ |
| troubleshooting | updating the printer firmware |
| 550-sheet and 650-sheet trays input option | using a flash drive 225 |
| symptoms 171 | using a network computer 225 |
| initial check 31 | user attendance messages |
| troubleshooting, print quality | 24 user attendance error messages 98 |
| blank or white pages 41 | 31 user attendance error messages 98 |
| dark print 53 | 32 user attendance error messages 99 |
| ghost images 51 | 33 user attendance error messages 99 |
| horizontal colored lines or banding 45 | 34 user attendance error messages 102 |
| horizontal white lines 44 | 42 user attendance error messages 102 |
| light print 63 | 43 user attendance error messages 103 |
| mottled print and dots 48 | 80 user attendance error messages 104 |
| text or images cut off 46 | 82 user attendance error messages 104 |
| toner easily rubs off 36 | 84 user attendance error messages 106 |
| uneven print density 59 | 88 user attendance error messages 106 |
| vertical white lines 50 | non-supply user attendance error messages 107 |
| troubleshooting, service checks | using the control panel |
| 100 service error messages 115 | Lexmark C2240 199 |
| 120 service error messages 117 | Lexmark C2325 197 |
| 121 service error messages 119 | Lexmark C2425 198 |
| 126 service error messages 124 | Lexmark C2535 198 |
| 142 service error messages 125 | Lexmark CS421 198 |
| 151 service error messages 127 | Lexmark CS521 198 |
| 160 service error messages 128 | Lexmark CS622 199 |
| 161 service error messages 129 | using the home screen 200 |
| 162 service error messages 131 | |
| 163 service error messages 131 | V |
| 166 service error messages 132 | vertical mount contact connector 233 |
| 167 service error messages 132 | vertical mount contact connector 255 |
| 171 service error messages 132 | 7 |
| 600 service error message 133 | Z |
| 602 service error messages 134 | zero insertion force (ZIF) connectors 227 |
| 620 service error messages 135 | |
| 642 service error messages 135 | |

Part number index

| P/N | Part name | Page |
|---------|------------------------------------|----------|
| 3085348 | Software and document CD | 398 |
| 40X1367 | 10 ft. parallel cable | 397 |
| 40X1368 | USB cable | 397 |
| 40X4823 | 1284-B THCK parallel adapter | 397 |
| 40X5168 | Pick tires | 390, 396 |
| 40X5413 | Sensor (fuser exit) | 392 |
| 40X7178 | 650-sheet duo tray MPF rollers | 396 |
| 40X7301 | Photo sensors | 392 |
| 40X7619 | Door straps | 388 |
| 40X7620 | Toner meter card | 392 |
| 40X7621 | Toner cover | 388 |
| 40X7629 | Motor (fuser drive) | 390 |
| 40X7630 | Right cover | 388 |
| 40X7633 | Top cover | 388 |
| 40X7648 | Screws parts pack | 397 |
| 40X7652 | Spring kit | 397 |
| 40X9244 | Front toner door bracket | 388 |
| 41X0020 | Serial ISP with backpack adapter | 397 |
| 41X0045 | English keyboard | 397 |
| 41X0046 | French keyboard | 397 |
| 41X0048 | German keyboard | 397 |
| 41X0049 | Spanish keyboard | 397 |
| 41X0357 | 110 V surge protector | 397 |
| 41X0370 | 220 V surge protector | 397 |
| 41X0397 | System fan | 388 |
| 41X0580 | Transfer module guide | 390 |
| 41X0997 | Contact front solutions module | 397 |
| 41X0998 | Contactless front solutions module | 397 |
| 41X1010 | 256 MB flash card | 397 |
| 41X1013 | Simplified Chinese font card | 397 |
| 41X1014 | Traditional Chinese font card | 397 |
| 41X1015 | Korean font card | 397 |

| P/N | Part name | Page |
|---------|--|------|
| 41X1016 | Japanese font card | 397 |
| 41X1026 | 500 GB USB hard disk drive | 397 |
| 41X1039 | Transfer module | 390 |
| 41X1040 | Printhead | 390 |
| 41X1041 | 110 V Fuser | 390 |
| 41X1042 | High voltage power supply | 392 |
| 41X1043 | 175 W low voltage power supply (CS421, C2425, CS521, C2535, CS622 and C2240) | 392 |
| 41X1285 | 250-sheet tray assembly | 388 |
| 41X1286 | Front door assembly | 388 |
| 41X1289 | EP drive assembly | 390 |
| 41X1290 | Weather station | 392 |
| 41X1291 | Left cover | 388 |
| 41X1292 | Media feeder | 390 |
| 41X1299 | 100 V Fuser | 390 |
| 41X1300 | 220 V Fuser | 390 |
| 41X1302 | 4.3-inch control panel bezel (CS622 and C2240) | 384 |
| 41X1303 | Blank control panel badge cover | 384 |
| 41X1304 | 2.4-inch control panel bezel (CS421, C2425, CS521, and C2535) | 384 |
| 41X1305 | 2-line control panel base cover | 382 |
| 41X1305 | Control pane base | 388 |
| 41X1305 | Control panel base cover | 384 |
| 41X1306 | 4.3-inch control panel top cover (CS622 and C2240) | 384 |
| 41X1307 | USB cable | 384 |
| 41X1308 | Headphone cable | 384 |
| 41X1309 | 2.4-inch control panel FFC (CS421, C2425, CS521, and C2535) | 384 |
| 41X1310 | 4.3-inch control panel keyboard cover (CS622 and C2240) | 384 |
| 41X1311 | Speaker (CS622 and C2240) | 392 |
| 41X1312 | Lower right subframe | 390 |
| 41X1373 | SATA hard disk drive with FIPS | 397 |
| 41X1561 | Front and right side interlock switch cover assembly | 394 |
| 41X1627 | 2.4-inch control panel assembly (CS421, C2425, CS521, and C2535) | 384 |
| 41X1722 | Waste toner bottle contact block | 394 |
| 41X1723 | Toner cartridge contact | 394 |
| 41X1780 | 550-sheet trav | 396 |

| P/N | Part name | Page |
|---------|--|------|
| 41X1781 | 550-sheet tray insert | 396 |
| 41X1783 | Optional 650-sheet duo tray | 396 |
| 41X1784 | 650-sheet duo tray insert | 396 |
| 41X1788 | Rear cover, C2325, CS4x, C2425, CS52x, and C2535 | 388 |
| 41X1789 | Controller board (CS421 and C2425) | 392 |
| 41X1790 | Controller board (CS622 and C2240) | 392 |
| 41X1871 | 1 port vertical fax card | 397 |
| 41X1872 | Marknet N8372, front Wi-Fi—FSM (CS421, CS521, CS622, C2240) | 397 |
| 41X1873 | Wireless network card cardlet without cable | 397 |
| 41X1904 | Sensor (left toner patch with thermistor) | 394 |
| 41X1945 | N8230 fiber ISP with side cover adapter | 397 |
| 41X1946 | N8230 fiber ISP with backpack adapter | 397 |
| 41X2019 | 110 W low-voltage power supply (C2325) | 392 |
| 41X2021 | 4.3-inch control panel FFC (CS622 and C2240) | 384 |
| 41X2033 | PCIe 8 GB x32 DDP RAM card | 397 |
| 41X2044 | 2-line control panel bezel | 382 |
| 41X2045 | 2-line control panel top cover | 382 |
| 41X2046 | 2-line control panel ribbon cable | 382 |
| 41X2047 | 2-line control panel assembly | 382 |
| 41X2048 | CS622 control panel badge cover | 385 |
| 41X2049 | CS421 control panel badge cover | 384 |
| 41X2050 | CS521 control panel badge cover | 384 |
| 41X2055 | Security element smart card with interconnect | 397 |
| 41X2055 | Smart card | 398 |
| 41X2070 | CS321 control panel badge cover | 382 |
| 41X2095 | 100 V Fuser maintenance kit | 399 |
| 41X2096 | 110 V Fuser maintenance kit | 399 |
| 41X2097 | 220 V Fuser maintenance kit | 399 |
| 41X2098 | Controller board (CS521 and CS2535) | 392 |
| 41X2100 | Rear cover, CS62x and C2240 | 388 |
| 41X2113 | 4.3-inch control panel assembly (CS622 and C2240) | 384 |
| 41X2115 | 4.3-inch control panel keyboard cover without volume (CS622 and C2240) | 384 |
| 41X2119 | Control panel power cable | 385 |
| 41X2127 | C2325 control panel badge cover | 382 |

| P/N | Part name | Page |
|---------|---|------|
| 41X2132 | C2425 control panel badge cover | 384 |
| 41X2133 | C2535 control panel badge cover | 384 |
| 41X2134 | C2240 control panel badge cover | 385 |
| 41X2140 | Controller board (C2325) | 392 |
| 41X2302 | Braille label kit | 397 |
| 41X2305 | Fuser deflector | 390 |
| 41X2326 | Lower left subframe | 390 |
| 41X2327 | Subframe cable cover | 390 |
| 41X2328 | Fuser exit narrow media to controller board | 394 |
| 41X2329 | Fuser/input sensor cable | 394 |
| 41X2330 | EP motor to controller board cable | 394 |
| 41X2331 | AC power to LVPS cable | 394 |
| 41X2332 | LVPS to controller board cable | 394 |
| 41X2333 | Weather station cable | 394 |
| 41X2334 | HVPS to controller board cable | 394 |
| 41X2335 | Tray 2 to controller board cable | 394 |
| 41X2336 | Tray present sensor cable | 394 |
| 41X2348 | Sensor (right toner patch with thermistor) | 394 |
| 41X2349 | Narrow media/bin full flag | 390 |
| 41X2350 | Right deflector flag | 390 |
| 41X2360 | Sub-frame foot | 390 |
| 41X2663 | Front door inner deflector | 388 |

Part name index

| P/N | Part name | Page |
|---------|--|------|
| 41X1871 | 1 port vertical fax card | 397 |
| 40X1367 | 10 ft. parallel cable | 397 |
| 41X1299 | 100 V Fuser | 390 |
| 41X2095 | 100 V Fuser maintenance kit | 399 |
| 41X1041 | 110 V Fuser | 390 |
| 41X2096 | 110 V Fuser maintenance kit | 399 |
| 41X0357 | 110 V surge protector | 397 |
| 41X2019 | 110 W low-voltage power supply (C2325) | 392 |
| 40X4823 | 1284-B THCK parallel adapter | 397 |
| 41X1043 | 175 W low voltage power supply (CS421, C2425, CS521, C2535, CS622 and C2240) | 392 |
| 41X2047 | 2-line control panel assembly | 382 |
| 41X1305 | 2-line control panel base cover | 382 |
| 41X2044 | 2-line control panel bezel | 382 |
| 41X2046 | 2-line control panel ribbon cable | 382 |
| 41X2045 | 2-line control panel top cover | 382 |
| 41X1627 | 2.4-inch control panel assembly (CS421, C2425, CS521, and C2535) | 384 |
| 41X1304 | 2.4-inch control panel bezel (CS421, C2425, CS521, and C2535) | 384 |
| 41X1309 | 2.4-inch control panel FFC (CS421, C2425, CS521, and C2535) | 384 |
| 41X1300 | 220 V Fuser | 390 |
| 41X2097 | 220 V Fuser maintenance kit | 399 |
| 41X0370 | 220 V surge protector | 397 |
| 41X1285 | 250-sheet tray assembly | 388 |
| 41X1010 | 256 MB flash card | 397 |
| 41X2113 | 4.3-inch control panel assembly (CS622 and C2240) | 384 |
| 41X1302 | 4.3-inch control panel bezel (CS622 and C2240) | 384 |
| 41X2021 | 4.3-inch control panel FFC (CS622 and C2240) | 384 |
| 41X1310 | 4.3-inch control panel keyboard cover (CS622 and C2240) | 384 |
| 41X2115 | 4.3-inch control panel keyboard cover without volume (CS622 and C2240) | 384 |
| 41X1306 | 4.3-inch control panel top cover (CS622 and C2240) | 384 |
| 41X1026 | 500 GB USB hard disk drive | 397 |
| 41X1780 | 550-sheet tray | 396 |
| 41X1781 | 550-sheet tray insert | 396 |

| P/N | Part name | Page |
|---------|--|------|
| 41X1784 | 650-sheet duo tray insert | 396 |
| 40X7178 | 650-sheet duo tray MPF rollers | 396 |
| 41X2331 | AC power to LVPS cable | 394 |
| 41X1303 | Blank control panel badge cover | 384 |
| 41X2302 | Braille label kit | 397 |
| 41X2134 | C2240 control panel badge cover | 385 |
| 41X2127 | C2325 control panel badge cover | 382 |
| 41X2132 | C2425 control panel badge cover | 384 |
| 41X2133 | C2535 control panel badge cover | 384 |
| 41X0997 | Contact front solutions module | 397 |
| 41X0998 | Contactless front solutions module | 397 |
| 41X1305 | Control pane base | 388 |
| 41X1305 | Control panel base cover | 384 |
| 41X2119 | Control panel power cable | 385 |
| 41X2140 | Controller board (C2325) | 392 |
| 41X1789 | Controller board (CS421 and C2425) | 392 |
| 41X2098 | Controller board (CS521 and CS2535) | 392 |
| 41X1790 | Controller board (CS622 and C2240) | 392 |
| 41X2070 | CS321 control panel badge cover | 382 |
| 41X2049 | CS421 control panel badge cover | 384 |
| 41X2050 | CS521 control panel badge cover | 384 |
| 41X2048 | CS622 control panel badge cover | 385 |
| 40X7619 | Door straps | 388 |
| 41X0045 | English keyboard | 397 |
| 41X1289 | EP drive assembly | 390 |
| 41X2330 | EP motor to controller board cable | 394 |
| 41X0046 | French keyboard | 397 |
| 41X1561 | Front and right side interlock switch cover assembly | 394 |
| 41X1286 | Front door assembly | 388 |
| 41X2663 | Front door inner deflector | 388 |
| 40X9244 | Front toner door bracket | 388 |
| 41X2305 | Fuser deflector | 390 |
| 41X2328 | Fuser exit narrow media to controller board | 394 |
| 41X2329 | Fuser/input sensor cable | 394 |

| P/N | Part name | Page |
|---------|---|----------|
| 41X0048 | German keyboard | 397 |
| 41X1308 | Headphone cable | 384 |
| 41X1042 | High voltage power supply | 392 |
| 41X2334 | HVPS to controller board cable | 394 |
| 41X1016 | Japanese font card | 397 |
| 41X1015 | Korean font card | 397 |
| 41X1291 | Left cover | 388 |
| 41X2326 | Lower left subframe | 390 |
| 41X1312 | Lower right subframe | 390 |
| 41X2332 | LVPS to controller board cable | 394 |
| 41X1872 | Marknet N8372, front Wi-Fi—FSM (CS421, CS521, CS622, C2240) | 397 |
| 41X1292 | Media feeder | 390 |
| 40X7629 | Motor (fuser drive) | 390 |
| 41X1946 | N8230 fiber ISP with backpack adapter | 397 |
| 41X1945 | N8230 fiber ISP with side cover adapter | 397 |
| 41X2349 | Narrow media/bin full flag | 390 |
| 41X1783 | Optional 650-sheet duo tray | 396 |
| 41X2033 | PCIe 8 GB x32 DDP RAM card | 397 |
| 40X7301 | Photo sensors | 392 |
| 40X5168 | Pick tires | 390, 396 |
| 41X1040 | Printhead | 390 |
| 41X1788 | Rear cover, C2325, CS4x, C2425, CS52x, and C2535 | 388 |
| 41X2100 | Rear cover, CS62x and C2240 | 388 |
| 40X7630 | Right cover | 388 |
| 41X2350 | Right deflector flag | 390 |
| 41X1373 | SATA hard disk drive with FIPS | 397 |
| 40X7648 | Screws parts pack | 397 |
| 41X2055 | Security element smart card with interconnect | 397 |
| 40X5413 | Sensor (fuser exit) | 392 |
| 41X1904 | Sensor (left toner patch with thermistor) | 394 |
| 41X2348 | Sensor (right toner patch with thermistor) | 394 |
| 41X0020 | Serial ISP with backpack adapter | 397 |
| 41X1013 | Simplified Chinese font card | 397 |
| 41X2055 | Smart card | 398 |

| P/N | Part name | Page |
|-------------|---|------|
| 3085348 | Software and document CD | 398 |
| 41X0049 | Spanish keyboard | 397 |
| 41X1311 | Speaker (CS622 and C2240) | 392 |
| 40X7652 | Spring kit | 397 |
| 41X2327 | Subframe cable cover | 390 |
| 41X2360 | Sub-frame foot | 390 |
| 41X0397 | System fan | 388 |
| 41X1723 | Toner cartridge contact | 394 |
| 40X7621 | Toner cover | 388 |
| 40X762 0 | Toner meter card | 392 |
| 40X7633 | Top cover | 388 |
| 41X1014 | Traditional Chinese font card | 397 |
| 41X1039 | Transfer module | 390 |
| 41X0580 | Transfer module guide | 390 |
| 41X2335 | Tray 2 to controller board cable | 394 |
| 41X2336 | Tray present sensor cable | 394 |
| 41X1307 | USB cable | 384 |
| 40X1368 | USB cable | 397 |
| 41X1722 | Waste toner bottle contact block | 394 |
| 41X1290 | Weather station | 392 |
| 41X2333 | Weather station cable | 394 |
| 41X1873 | Wireless network card cardlet without cable | 397 |

