



41.8 Error Message and/or Printers cycling engine repeatedly

HP P4014/P4015/P4515

Due to an issue with earlier firmware versions the P4010 series printers are known to exhibit prolonged cycling of the print engine during or at initial printing. This issue in rare cases has also been accompanied with a 41.8 error code which is not listed in the manual. Fix would be replacing the fuser.