



***Fan Error – Service Manual correction/clarification  
HP P4014/P4015/P4515 LaserJet Printers***

***57.01 ERROR (right rear fan) RK2-1992***

Turn printer off, then on  
Fan **FN102** has experienced an error.

- Inspect fan **FN102** to determine if its rotational movement is obstructed.
- Verify that the fan connection at connector J79 on the DC controller PCA is securely seated.
- If the error persists, replace the fan.

***57.03 ERROR (Right Front Fan) RK2-1989***

Turn printer off, then on  
Fan **FN103** has experienced an error.

- Inspect fan **FN103** to determine if its rotational movement is obstructed.
- Verify that the fan connection at connector J75 on the DC controller PCA is securely seated.
- If the error persists, replace the fan.