



*Noise from document feeder*

*HP M527MFP and HP Color M577MFP*



Laser Pros has encountered an increasing number of cases where the above listed models develop a high pitched “chirp” or even as bad as a “grind” noise that usually leads to ADF paper jams!

Unfortunately, HP does not list any replaceable components (other than the roller/pad kit p# W5U23-67901) then requiring the entire ADF to be replaced p# B5L47-67907 pictured below.

