

Table 8-12 Fusing assembly

Ref	Description	Part number	Qty
	Fusing assembly (110-127 V)	CB506-67901	1
	Fusing assembly (220-240 V)	CB506-67902	1
1	Roller, pressure		1
2	Sleeve guide assembly (110-127 V)		1
2	Sleeve guide assembly (220-240 V)		1
A01	Guide, paper inlet, lower		1
A02	Holder, fusing sensor		2
A03	Lever, release, left		1
A04	Sheet, fusing protective		1
A05	Bushing		2
A6	Roller, face-up		1
A07	Spring, torsion		1
A08	Spring, torsion		1
A09	Side plate, fusing, left		1
A10	Spring, compression		2
A11	Plate, pressure, right		1
A12	Plate, pressure, left		1
A13	Bushing		1
A14	Bushing		1
A15	Flag, sensor, right		1
A16	Flag, sensor, left		1
A17	Lever, sensor		2
A18	Spring, torsion		1
A19	Spring, torsion		1
A20	Guide, cable, right		1
A21	Guide, cable, left		1
A22	Spring, leaf		1
A23	Bar, filter, rear		1
A24	Eliminator		1
A25	Holder, brush		1
A26	Rib, cable guide		1
A27	Cam		2
A28	Sheet, protective, right upper		1
A29	Sheet, protective, right lower		1

Table 8-12 Fusing assembly (continued)

Ref	Description	Part number	Qty
A30	Side plate, fusing, right		1
A31	Lever, release, right		1
A32	Guide, paper delivery, lower		1
A33	Screw, stepped		2
A34	Sheet, protective, left		1
A35	Gear, 18T		1
A36	Gear, 17T		1
A37	IC, photo interrupter		2
A38	Guide, paper delivery guide, upper		1
A39	Pressure roller gear assembly		1
A40	Upper entrance guide assembly		1
A41	Cable, FSR AC		1
A42	Cable, FSR DC		1
A43	Holder, fusing lever		1
A44	Screw, M3x8		4
A45	Screw, RS, M3x8		2
A46	Screw, D, M3x8		2
A47	Screw with washer, M3x6		1
A48	Screw with washer, M3x6		1
A49	Screw, tap, S		2
A50	Ring, E		2
A51	Lever, paper delivery sensor		1
A52	Label, "Caution, high temp."		1

¹ Only orderable parts have part numbers.