



*No power – will not turn on*

*HP LaserJet M604, M605 and M606 failure*



LPI has noticed an increase in cases with the above listed models failing with a “no power symptom” where the machine will not turn on.

***Note:***

Not to be confused with a “no display” symptom where one can hear motors cycle when powered on – most of the time ending up being a failed formatter board. After verifying the printer has a good power source, the fix is to replace the HVPS/LVPS main power supply # RM2-6301 and see the printer’s service manual for proper replacement procedure.